MobileDeviceService

Personal informations : Dusan Cerveny Trencianska 123 dusan.cerveny@gmail.com 0905456215
Registration Date : 2014-05-05 16:17:05.0
Fault : Nefunkcny akcelerometer
IMEI : 6546516841654
Device type : phone
Repair report : Vymena maticnej dosky vsetky sensory su funkcne nahraty novy SW
Repair costs : 155.6€
Send back date : 2014-05-05 16:20:03.0
Device tested by : Peter Oškvarok
Device repaired by : Veronika Neviemaka
Device sent by : Jozef Hudec