Change Order Report For Project Main

MainBoard.PrjPcb And MainBoard.PrjPcb

Action	Object	Change Document	Status
Add Co	omponents		
Add	D2.1	To MainBoard.PcbDoc	Footprint Not Found D5A20V
Add	D2.2	To MainBoard.PcbDoc	Footprint Not Found D5A20V
Add	FB1	To MainBoard.PcbDoc	Footprint Not Found BEADC1608
Add	IC7	To MainBoard.PcbDoc	Footprint Not Found SHTC3
Add	IC13	To MainBoard.PcbDoc	Footprint Not Found SOP65P780
Add	IC14	To MainBoard.PcbDoc	Footprint Not Found SOP65P780
Add	IC15	To MainBoard.PcbDoc	Footprint Not Found SOP65P780.
Add	IC17	To MainBoard.PcbDoc	Footprint Not Found SOP65P780
Add	IN_1	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_F
Add	IN_2	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_F
Add	IN_3_U_Channel_1	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_F
Add	IN_3_U_Channel_2	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_F
Add	IN_3_U_Channel_3	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_F
Add	IN_3_U_Channel_4	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_F
Add	IN_3_U_Channel_5	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_F
Add	IN_3_U_Channel_6	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_F
Add	IN_3_U_Channel_7	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_F
Add	IN 3 U Channel 8	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_F
Add	M1	To MainBoard.PcbDoc	Footprint Not Found SOT23
Add	M2	To MainBoard.PcbDoc	Footprint Not Found SOT23
Add	OUT_1	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_F
Add	OUT_2	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_F
Add	Q7	To MainBoard.PcbDoc	Footprint Not Found SOT95P237
Add	Q8	To MainBoard.PcbDoc	Footprint Not Found SOT95P237
Add	Q9	To MainBoard.PcbDoc	Footprint Not Found SOT95P237
Add	Q10	To MainBoard.PcbDoc	Footprint Not Found SOT95P237
Add	RELAY_1.1	To MainBoard.PcbDoc	Footprint Not Found RELAY_DC
Add	RELAY_1.2	To MainBoard.PcbDoc	Footprint Not Found RELAY_DC
Add	RELAY_2.1	To MainBoard.PcbDoc	Footprint Not Found RELAY DC
Add	RELAY 2.2	To MainBoard.PcbDoc	Footprint Not Found RELAY DC
Add	 S1	To MainBoard.PcbDoc	Footprint Not Found 1825027-8

utorok 8-jún-08/2021 2:27:41 PM Page 1 of 4

Action	Object		Change Document	Status
	s To Nets			
Add	D2.1-1 to IN+_BDD_2		MainBoard.PcbDoc	Unknown Pin: Pin D2.1-1
Add	D2.1-2 to IN- BDD 2		MainBoard.PcbDoc	Unknown Pin: Pin D2.1-2
Add	D2.2-1 to 5V		MainBoard.PcbDoc	Unknown Pin: Pin D2.2-1
Add Add	FB1-1 to 5V_FTDI FB1-2 to NetC4 2		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin FB1-1 Unknown Pin: Pin FB1-2
Add	IC7-4 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC7-4
Add	IC13-1 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC13-1
Add	IC13-5 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC13-5
Add	IC13-7 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC13-7
Add	IC13-8 to NetIC13_8		MainBoard.PcbDoc	Unknown Pin: Pin IC13-8
Add	IC13-10 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC13-10
Add	IC13-11 to GND_ISO	In	MainBoard.PcbDoc	Unknown Pin: Pin IC13-11
Add	IC13-12 to VCC_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC13-12
Add	IC13-13 to NetIC13_13		MainBoard.PcbDoc	Unknown Pin: Pin IC13-13
Add	IC13-14 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC13-14
Add	IC13-16 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC13-16
Add	IC13-17 to VCC_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC13-17
Add	IC13-18 to SDA_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC13-18
Add	IC13-19 to SCL_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC13-19
Add Add	IC13-20 to GND_ISO IC14-1 to GND		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC13-20 Unknown Pin: Pin IC14-1
Add	IC14-1 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC14-5
Add	IC14-5 to GND		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC14-5
Add	IC14-7 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC14-8
Add	IC14-10 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC14-10
Add	IC14-11 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC14-11
Add	IC14-12 to VCC_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC14-12
Add	IC14-13 to NetIC14_13		MainBoard.PcbDoc	Unknown Pin: Pin IC14-13
Add	IC14-14 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC14-14
Add	IC14-16 to GND_ISO		MainBoard,PcbDoc	Unknown Pin: Pin IC14-16
Add	IC14-17 to VCC ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC14-17
Add	IC14-20 to GND ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC14-20
Add	IC15-1 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC15-1
Add	IC15-5 to GND	In	MainBoard.PcbDoc	Unknown Pin: Pin IC15-5
Add	IC15-7 to GND	ln	MainBoard.PcbDoc	Unknown Pin: Pin IC15-7
Add	IC15-8 to NetIC15_8	ln	MainBoard.PcbDoc	Unknown Pin: Pin IC15-8
Add	IC15-10 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC15-10
Add	IC15-11 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC15-11
Add	IC15-12 to VCC_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC15-12
Add	IC15-13 to NetIC15_13		MainBoard.PcbDoc	Unknown Pin: Pin IC15-13
Add	IC15-14 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC15-14
Add	IC15-16 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC15-16
Add	IC15-17 to VCC_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC15-17
Add	IC15-20 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC15-20
Add Add	IC17-1 to GND		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC17-1 Unknown Pin: Pin IC17-5
Add	IC17-5 to GND IC17-7 to GND		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC17-7
Add	IC17-7 to GND IC17-8 to NetIC17_8		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC17-8
Add	IC17-0 to Netic 17_6		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC17-10
Add	IC17-10 to GND_ISO		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC17-11
Add	IC17-11 to CND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC17-12
Add	IC17-13 to NetIC17_13		MainBoard.PcbDoc	Unknown Pin: Pin IC17-13
Add	IC17-14 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC17-14
Add	IC17-16 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC17-16
Add	IC17-17 to VCC_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC17-17
Add	IC17-20 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC17-20
Add	IN_1-1 to GND_BDD2		MainBoard.PcbDoc	Unknown Pin: Pin IN_1-1
Add	IN_1-2 to BDD1_+		MainBoard.PcbDoc	Unknown Pin: Pin IN_1-2
Add	IN_2-1 to GND_BDD2	In	MainBoard.PcbDoc	Unknown Pin: Pin IN_2-1
Add	IN_2-2 to BDD2_+	In	MainBoard.PcbDoc	Unknown Pin: Pin IN_2-2
Add	IN_3_U_Channel_1-1 to cerpadlo+_U_Channel_1		MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	IN_3_U_Channel_1-2 to cerpadloU_Channel_1		MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	IN_3_U_Channel_2-1 to cerpadlo+_U_Channel_2	In	MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add			MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	IN_3_U_Channel_3-1 to cerpadlo+_U_Channel_3			Unknown Pin: Pin IN_3_U_Channe
Add			MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	IN_3_U_Channel_4-1 to cerpadlo+_U_Channel_4			Unknown Pin: Pin IN 3 U Channe
Add			MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	IN_3_U_Channel_5-1 to cerpadlo+_U_Channel_5	In	MainBoard.PcbDoc	Unknown Pin: Pin IN 3 U Channe

utorok 8-jún-08/2021 2:27:41 PM Page 2 of 4

Action	Object		Change Document	Status
Add Pins	s To Nets			
Add	IN 3 U Channel 5-2 to cerpadlo- U Channel 5	In	MainBoard.PcbDoc	Unknown Pin: Pin IN 3 U Channe
Add	IN 3 U Channel 6-1 to cerpadio+ U Channel 6			Unknown Pin: Pin IN 3 U Channe
Add	IN 3 U Channel 6-2 to cerpadlo- U Channel 6		MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	IN 3 U Channel 7-1 to cerpadlo+ U Channel 7		MainBoard.PcbDoc	Unknown Pin: Pin IN 3 U Channe
Add	IN_3_U_Channel_7-2 to cerpadloU_Channel_7		MainBoard.PcbDoc	Unknown Pin: Pin IN 3 U Channe
Add	IN 3 U Channel 8-1 to cerpadlo+ U Channel 8		MainBoard.PcbDoc	Unknown Pin: Pin IN 3 U Channe
Add	IN 3 U Channel 8-2 to cerpadlo- U Channel 8		MainBoard.PcbDoc	Unknown Pin: Pin IN 3 U Channe
Add	M1-1 to NetM1_1		MainBoard.PcbDoc	Unknown Pin: Pin M1-1
Add	M1-2 to GND_BDD2	In	MainBoard.PcbDoc	Unknown Pin: Pin M1-2
Add	M1-3 to RELE_2	In	MainBoard.PcbDoc	Unknown Pin: Pin M1-3
Add	M2-1 to NetM2_1	In	MainBoard.PcbDoc	Unknown Pin: Pin M2-1
Add	M2-2 to GND_BDD2	In	MainBoard.PcbDoc	Unknown Pin: Pin M2-2
Add	OUT_1-1 to OUT_2_BDD_1	In	MainBoard.PcbDoc	Unknown Pin: Pin OUT_1-1
Add	OUT_1-2 to OUT_1_BDD_1	In	MainBoard.PcbDoc	Unknown Pin: Pin OUT_1-2
Add	OUT_2-1 to OUT_2_BDD_2	ln	MainBoard.PcbDoc	Unknown Pin: Pin OUT_2-1
Add	OUT_2-2 to OUT_1_BDD_2	ln	MainBoard.PcbDoc	Unknown Pin: Pin OUT_2-2
Add	Q7-1 to EN_4	In	MainBoard.PcbDoc	Unknown Pin: Pin Q7-1
Add	Q7-2 to GND		MainBoard.PcbDoc	Unknown Pin: Pin Q7-2
Add	Q7-3 to NetIC14_8		MainBoard.PcbDoc	Unknown Pin: Pin Q7-3
Add	Q8-1 to EN_2		MainBoard.PcbDoc	Unknown Pin: Pin Q8-1
Add	Q8-2 to GND		MainBoard.PcbDoc	Unknown Pin: Pin Q8-2
Add	Q8-3 to NetIC13_8	In	MainBoard.PcbDoc	Unknown Pin: Pin Q8-3
Add	Q9-1 to EN_6		MainBoard.PcbDoc	Unknown Pin: Pin Q9-1
Add	Q9-2 to GND		MainBoard.PcbDoc	Unknown Pin: Pin Q9-2
Add	Q9-3 to NetIC15_8		MainBoard.PcbDoc	Unknown Pin: Pin Q9-3
Add	Q10-1 to EN_1		MainBoard.PcbDoc	Unknown Pin: Pin Q10-1
Add	Q10-2 to GND		MainBoard.PcbDoc	Unknown Pin: Pin Q10-2
Add	Q10-3 to NetIC17_8		MainBoard.PcbDoc	Unknown Pin: Pin Q10-3
Add	RELAY_1.1-1 to OUT_1_BDD_1		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.1-1
Add	RELAY_1.1-2 to 5V		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.1-2
Add	RELAY_1.1-3 to IN+_BDD_1		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.1-3
Add	RELAY 1.1-4 to IN- BDD 1		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.1-4
Add	RELAY_1.1-5 to RELE_2		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.1-5
Add	RELAY_1.2-1 to OUT_2_BDD_1		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.2-1
Add	RELAY_1.2-2 to 5V		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.2-2
Add	RELAY_1.2-3 to INBDD_1		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.2-3
Add	RELAY_1.2-4 to IN+_BDD_1		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.2-4
Add	RELAY_1.2-5 to RELE_2		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.2-5
Add	RELAY_2.1-1 to OUT_1_BDD_2		MainBoard.PcbDoc	Unknown Pin: Pin RELAY 2.1-1
Add	RELAY_2.1-2 to 5V		MainBoard Pob Doc	Unknown Pin: Pin RELAY_2.1-2
Add	RELAY 2.1-3 to IN+_BDD_2		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_2.1-3
Add	RELAY_2.1-4 to INBDD_2		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_2.1-4
Add	RELAY 2.2-1 to OUT 2 BDD 2		MainBoard PobDoc	Unknown Pin: Pin RELAY_2.2-1
Add Add	RELAY_2.2-2 to 5V RELAY_2.2-3 to INBDD_2		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin RELAY_2.2-2 Unknown Pin: Pin RELAY_2.2-3
Add	RELAY 2.2-3 to INBDD_2 RELAY 2.2-4 to IN+_BDD_2		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin RELAY 2.2-3 Unknown Pin: Pin RELAY 2.2-4
Add	S1-1 to GND		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin S1-1
Add	\$1-1 to GND \$1-2 to RST		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin S1-1 Unknown Pin: Pin S1-2
Auu	01-2 IU NO1	111	IVIAII IDOAI U.F GUDUC	OHNIOWH FIII. FIII 31-2
Add Net	s			
Add	3V3	To	MainBoard.PcbDoc	
Add	RELE_2		MainBoard.PcbDoc	
۸ ما ما	001 100	т.	Main Daniel Dale Dan	

SCL_ISO To MainBoard.PcbDoc Add SCL SCL To MainBoard.PcbDoc
To MainBoard.PcbDoc Add Add SDA_ISO SDA_ISO To MainBoard.PcbDoc Add Add To MainBoard.PcbDoc SDA_ISO To MainBoard.PcbDoc Add Add SDA_ISO To MainBoard.PcbDoc

To MainBoard.PcbDoc
To MainBoard.PcbDoc
To MainBoard.PcbDoc

Add

Add

Add

SCL_ISO

SCL_ISO

SCL_ISO

utorok 8-jún-08/2021 2:27:41 PM Page 3 of 4

Action	Object	Change Document	Status
Add Cor	mponent Class Members		
Add	D2.1 to polarita_BDD_2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	D2.2 to polarita BDD 2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	FB1 to U_ESP32	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IC7 to U_temp_humidity	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IC13 to U_DO_EZO_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IC14 to U_pH_EZO_2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IC15 to U_TDS_EZO_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IC17 to U_pH_EZO_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IN_1 to U_BDD	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IN_2 to U_BDD	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IN_3_U_Channel_1 to U_Channel_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IN_3_U_Channel_2 to U_Channel_2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IN_3_U_Channel_3 to U_Channel_3	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IN_3_U_Channel_4 to U_Channel_4	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IN_3_U_Channel_5 to U_Channel_5	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IN_3_U_Channel_6 to U_Channel_6	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IN_3_U_Channel_7 to U_Channel_7	In MainBoard.PcbDoc	Failed to add class member : Com
Add	IN_3_U_Channel_8 to U_Channel_8	In MainBoard.PcbDoc	Failed to add class member : Com
Add	M1 to polarita_BDD_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	M2 to polarita_BDD_2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	OUT_1 to U_BDD	In MainBoard.PcbDoc	Failed to add class member : Com
Add	OUT_2 to U_BDD	In MainBoard.PcbDoc	Failed to add class member : Com
Add	Q7 to U_pH_EZO_2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	Q8 to U_DO_EZO_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	Q9 to U_TDS_EZO_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	Q10 to U_pH_EZO_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	RELAY_1.1 to polarita_BDD_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	RELAY_1.2 to polarita_BDD_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	RELAY_2.1 to polarita_BDD_2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	RELAY 2.2 to polarita_BDD 2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	S1 to U_ESP32	In MainBoard.PcbDoc	Failed to add class member : Com

utorok 8-jún-08/2021 2:27:41 PM Page 4 of 4