Change Order Report For Project

MainBoard.PrjPcb And MainBoard.PrjPcb

Action	Object	Change Document	Status
Add Cor	mponents		
Add	ADR0 1	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR0_2	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR1_1	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR1_2	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR1_U_Channel_1	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR1_U_Channel_2	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR1_U_Channel_3	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR1_U_Channel_4	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR1_U_Channel_5	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR1_U_Channel_6	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR1_U_Channel_7	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR1_U_Channel_8	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR2_U_Channel_1 ADR2_U_Channel_2	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add Add	ADR2_U_Channel_2 ADR2_U_Channel_3	To MainBoard PobDoc	Footprint Not Found SOLDER_PA
Add	ADR2_U_Channel_3 ADR2_U_Channel_4	To MainBoard.PcbDoc To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA Footprint Not Found SOLDER_PA
Add	ADR2 U Channel 5	To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR2 U Channel 6	To MainBoard.PcbDoc	Footprint Not Found SOLDER_FA
Add	ADR2 U Channel 7	To MainBoard.PcbDoc To MainBoard.PcbDoc	Footprint Not Found SOLDER_PA
Add	ADR2 U Channel 8	To MainBoard.PcbDoc	Footprint Not Found SOLDER PA
Add	C38 U Channel 1	To MainBoard.PcbDoc	Footprint Not Found Capacitor
Add	C38 U Channel 2	To MainBoard.PcbDoc	Footprint Not Found Capacitor
Add	C38 U Channel 3	To MainBoard.PcbDoc	Footprint Not Found Capacitor
Add	C38 U Channel 4	To MainBoard.PcbDoc	Footprint Not Found Capacitor
Add	C38 U Channel 5	To MainBoard.PcbDoc	Footprint Not Found Capacitor
Add	C38 U Channel 6	To MainBoard.PcbDoc	Footprint Not Found Capacitor
Add	C38 U Channel 7	To MainBoard.PcbDoc	Footprint Not Found Capacitor
Add	C38_U_Channel_8	To MainBoard.PcbDoc	Footprint Not Found Capacitor
Add	D1.1	To MainBoard.PcbDoc	Footprint Not Found D5A20V
Add	D1.2	To MainBoard.PcbDoc	Footprint Not Found D5A20V
Add	D2.1	To MainBoard.PcbDoc	Footprint Not Found D5A20V
Add	D2.2	To MainBoard.PcbDoc	Footprint Not Found D5A20V
Add	FB1	To MainBoard.PcbDoc	Footprint Not Found BEADC1608X
Add	IC7	To MainBoard.PcbDoc	Footprint Not Found SHTC3
Add	IC13	To MainBoard.PcbDoc	Footprint Not Found SOP65P780X
Add	IC14	To MainBoard.PcbDoc	Footprint Not Found SOP65P780X
Add	IC15	To MainBoard.PcbDoc	Footprint Not Found SOP65P780X
Add	IC17	To MainBoard.PcbDoc	Footprint Not Found SOP65P780X
Add	IN_1	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_PI
Add	IN_2	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_PI
Add	IN_3_U_Channel_1	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_P
Add	IN_3_U_Channel_2	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_P
Add	IN_3_U_Channel_3 IN 3 U Channel 4	To MainBoard.PcbDoc To MainBoard.PcbDoc	Footprint Not Found CON_2CH_P
Add Add	IN 3 U Channel 5	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_PI Footprint Not Found CON_2CH_PI
Add	IN 3 U Channel 6	To MainBoard.PcbDoc To MainBoard.PcbDoc	Footprint Not Found CON_2CH_PI
Add	IN 3 U Channel 7	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_PI
Add	IN 3 U Channel 8	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_PI
Add	M1	To MainBoard.PcbDoc	Footprint Not Found SOT23
Add	M2	To MainBoard.PcbDoc	Footprint Not Found SOT23
Add	OUT_1	To MainBoard.PcbDoc	Footprint Not Found CON_2CH_PI
Add	OUT_2	To MainBoard.PcbDoc	Footprint Not Found CON 2CH P
Add	Q7	To MainBoard.PcbDoc	Footprint Not Found SOT95P237X
Add	Q8	To MainBoard.PcbDoc	Footprint Not Found SOT95P237X
Add	Q9	To MainBoard.PcbDoc	Footprint Not Found SOT95P237X
Add	Q10	To MainBoard.PcbDoc	Footprint Not Found SOT95P237X
Add	RELAY_1.1	To MainBoard.PcbDoc	Footprint Not Found RELAY_DC
Add	RELAY_1.2	To MainBoard.PcbDoc	Footprint Not Found RELAY_DC
Add	RELAY_2.1	To MainBoard.PcbDoc	Footprint Not Found RELAY_DC
Add	RELAY_2.2	To MainBoard.PcbDoc	Footprint Not Found RELAY_DC
Add	S1	To MainBoard.PcbDoc	Footprint Not Found 1825027-8

štvrtok 3-jún-03/2021 1:54:53 PM Page 1 of 8

Action	Object		Change Document	Status
Add Pin	s To Nets			
Add	ADR0_1-1 to GND_BDD2	In	MainBoard.PcbDoc	Unknown Pin: Pin ADR0 1-1
Add	ADR0 1-2 to ADR0 1	In	MainBoard.PcbDoc	Unknown Pin: Pin ADR0 1-2
Add	ADR0_1-3 to 3V3		MainBoard.PcbDoc	Unknown Pin: Pin ADR0_1-3
Add	ADRO_2-1 to GND_BDD2		MainBoard.PcbDoc	Unknown Pin: Pin ADR0_2-1
Add Add	ADR0_2-2 to ADR0_2 ADR0_2-3 to 3V3		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin ADR0_2-2 Unknown Pin: Pin ADR0_2-3
Add	ADR1_1-1 to GND_BDD2		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin ADR1 1-1
Add	ADR1_1-2 to ADR1_1		MainBoard.PcbDoc	Unknown Pin: Pin ADR1_1-2
Add	ADR1_1-3 to 3V3		MainBoard.PcbDoc	Unknown Pin: Pin ADR1_1-3
Add	ADR1_2-1 to GND_BDD2		MainBoard.PcbDoc	Unknown Pin: Pin ADR1_2-1
Add	ADR1_2-2 to ADR1_2		MainBoard.PcbDoc	Unknown Pin: Pin ADR1_2-2
Add Add	ADR1_2-3 to 3V3 ADR1_U_Channel_1-1 to 6V		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin ADR1_2-3 Unknown Pin: Pin ADR1_U_Chanr
Add	ADR1_U_Channel_1-3 to GND_BDD2		MainBoard.PcbDoc	Unknown Pin: Pin ADR1_U_Chanr
Add	ADR1 U Channel 2-1 to 6V		MainBoard.PcbDoc	Unknown Pin: Pin ADR1 U Chanr
Add	ADR1_U_Channel_2-3 to GND_BDD2	In	MainBoard.PcbDoc	Unknown Pin: Pin ADR1_U_Chanr
Add	ADR1_U_Channel_3-1 to 6V		MainBoard.PcbDoc	Unknown Pin: Pin ADR1_U_Chanr
Add	ADR1_U_Channel_3-3 to GND_BDD2		MainBoard.PcbDoc	Unknown Pin: Pin ADR1_U_Chanr
Add	ADR1_U_Channel_4-1 to 6V ADR1_U_Channel_4-3 to GND_BDD2		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin ADR1_U_Chanr Unknown Pin: Pin ADR1_U_Chanr
Add Add	ADR1_U_Channel_5-1 to 6V		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin ADR1_U_Chanr
Add	ADR1 U Channel 5-3 to GND BDD2		MainBoard.PcbDoc	Unknown Pin: Pin ADR1_U_Chanr
Add	ADR1_U_Channel_6-1 to 6V		MainBoard.PcbDoc	Unknown Pin: Pin ADR1_U_Chanr
Add	ADR1_U_Channel_6-3 to GND_BDD2	In	MainBoard.PcbDoc	Unknown Pin: Pin ADR1_U_Chanr
Add	ADR1_U_Channel_7-1 to 6V		MainBoard.PcbDoc	Unknown Pin: Pin ADR1_U_Chanr
Add	ADR1_U_Channel_7-3 to GND_BDD2		MainBoard.PcbDoc	Unknown Pin: Pin ADR1_U_Chanr
Add Add	ADR1_U_Channel_8-1 to 6V ADR1_U_Channel_8-3 to GND_BDD2		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin ADR1_U_Chanr Unknown Pin: Pin ADR1_U_Chanr
Add	ADR1_0_Channel_1-1 to 6V		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2 U Channel 1-2 to adresa2 U Channel 1		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_1-3 to GND_BDD2		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_2-1 to 6V		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_2-2 to adresa2_U_Channel_2		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add Add	ADR2_U_Channel_2-3 to GND_BDD2 ADR2_U_Channel_3-1 to 6V		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel 3-1 to 6V ADR2_U_Channel 3-2 to adresa2_U_Channel 3		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2 U Channel 3-3 to GND BDD2		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_4-1 to 6V		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_4-2 to adresa2_U_Channel_4	In	MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_4-3 to GND_BDD2		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_5-1 to 6V		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add Add	ADR2_U_Channel_5-2 to adresa2_U_Channel_5 ADR2_U_Channel_5-3 to GND_BDD2		MainBoard PobDoc	Unknown Pin: Pin ADR2_U_Chanr Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_6-1 to 6V		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_6-2 to adresa2_U_Channel_6		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_6-3 to GND_BDD2		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_7-1 to 6V		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_7-2 to adresa2_U_Channel_7		MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_7-3 to GND_BDD2		MainBoard PobDoc	Unknown Pin: Pin ADR2_U_Chanr
Add Add	ADR2_U_Channel_8-1 to 6V ADR2_U_Channel_8-2 to adresa2_U_Channel_8		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr Unknown Pin: Pin ADR2_U_Chanr
Add	ADR2_U_Channel_8-3 to GND_BDD2		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin ADR2_U_Chanr
Add	C38_U_Channel_1-1 to cerpadloU_Channel_1		MainBoard.PcbDoc	Unknown Pin: Pin C38_U_Channe
Add	C38_U_Channel_1-2 to cerpadlo+_U_Channel_1		MainBoard.PcbDoc	Unknown Pin: Pin C38_U_Channe
Add	C38_U_Channel_2-1 to cerpadloU_Channel_2	In	MainBoard.PcbDoc	Unknown Pin: Pin C38_U_Channe
Add	C38_U_Channel_2-2 to cerpadlo+_U_Channel_2		MainBoard.PcbDoc	Unknown Pin: Pin C38_U_Channe
Add	C38_U_Channel_3-1 to cerpadloU_Channel_3		MainBoard PobDoc	Unknown Pin: Pin C38_U_Channe
Add Add	C38_U_Channel_3-2 to cerpadlo+_U_Channel_3 C38_U_Channel_4-1 to cerpadloU_Channel_4		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin C38_U_Channe Unknown Pin: Pin C38_U_Channe
Add	C38_U_Channel_4-1 to cerpadioU_Channel_4		MainBoard.PcbDoc	Unknown Pin: Pin C38_U_Channe
Add	C38_U_Channel_5-1 to cerpadioU_Channel_5		MainBoard.PcbDoc	Unknown Pin: Pin C38_U_Channe
Add	C38_U_Channel_5-2 to cerpadlo+_U_Channel_5		MainBoard.PcbDoc	Unknown Pin: Pin C38_U_Channe
Add	C38_U_Channel_6-1 to cerpadloU_Channel_6		MainBoard.PcbDoc	Unknown Pin: Pin C38_U_Channe
Add	C38_U_Channel_6-2 to cerpadlo+_U_Channel_6		MainBoard.PcbDoc	Unknown Pin: Pin C38_U_Channe
Add	C38_U_Channel_7-1 to cerpadloU_Channel_7		MainBoard PobDoc	Unknown Pin: Pin C38_U_Channe
Add Add	C38_U_Channel_7-2 to cerpadlo+_U_Channel_7 C38_U_Channel_8-1 to cerpadloU_Channel_8		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin C38_U_Channe Unknown Pin: Pin C38_U_Channe
Add	C38_U_Channel_8-2 to cerpadio+_U_Channel_8		MainBoard.PcbDoc	Unknown Pin: Pin C38_U_Channe
Add	D1.1-1 to IN+_BDD_1		MainBoard.PcbDoc	Unknown Pin: Pin D1.1-1
		_		

štvrtok 3-jún-03/2021 1:54:53 PM Page 2 of 8

Action	Object		Change Document	Status
A LLD'	T- N (-			
	s To Nets	H	M: D IDID	H
Add	D1.1-2 to INBDD_1		MainBoard.PcbDoc	Unknown Pin: Pin D1.1-2
Add Add	D1.2-1 to 5V D1.2-2 to RELE_2		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin D1.2-1 Unknown Pin: Pin D1.2-2
Add	D2.1-1 to IN+ BDD 2		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin D2.1-1
Add	D2.1-1 to IN- BDD 2		MainBoard.PcbDoc	Unknown Pin: Pin D2.1-2
Add	D2.2-1 to 5V		MainBoard.PcbDoc	Unknown Pin: Pin D2.2-1
Add	FB1-1 to 5V FTDI		MainBoard.PcbDoc	Unknown Pin: Pin FB1-1
Add	FB1-2 to NetC4_2		MainBoard.PcbDoc	Unknown Pin: Pin FB1-2
Add	IC7-4 to GND	In	MainBoard.PcbDoc	Unknown Pin: Pin IC7-4
Add	IC13-1 to GND	In	MainBoard.PcbDoc	Unknown Pin: Pin IC13-1
Add	IC13-5 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC13-5
Add	IC13-7 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC13-7
Add	IC13-8 to NetIC13_8		MainBoard.PcbDoc	Unknown Pin: Pin IC13-8
Add	IC13-10 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC13-10
Add	IC13-11 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC13-11
Add Add	IC13-12 to VCC_ISO IC13-13 to NetIC13_13		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC13-12 Unknown Pin: Pin IC13-13
Add	IC13-13 to Netic 13_13 IC13-14 to GND_ISO		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC13-14
Add	IC13-14 to GND_ISO		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC13-16
Add	IC13-10 to CND_ISC		MainBoard.PcbDoc	Unknown Pin: Pin IC13-17
Add	IC13-18 to SDA_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC13-18
Add	IC13-19 to SCL_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC13-19
Add	IC13-20 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC13-20
Add	IC14-1 to GND	In	MainBoard.PcbDoc	Unknown Pin: Pin IC14-1
Add	IC14-5 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC14-5
Add	IC14-7 to GND	In	MainBoard.PcbDoc	Unknown Pin: Pin IC14-7
Add	IC14-8 to NetIC14_8		MainBoard.PcbDoc	Unknown Pin: Pin IC14-8
Add	IC14-10 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC14-10
Add	IC14-11 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC14-11
Add	IC14-12 to VCC_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC14-12
Add	IC14-13 to NetIC14_13		MainBoard.PcbDoc	Unknown Pin: Pin IC14-13
Add Add	IC14-14 to GND_ISO IC14-16 to GND_ISO		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC14-14 Unknown Pin: Pin IC14-16
Add	IC14-10 to GND_ISO		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC14-17
Add	IC14-20 to GND ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC14-20
Add	IC15-1 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC15-1
Add	IC15-5 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC15-5
Add	IC15-7 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC15-7
Add	IC15-8 to NetIC15_8	In	MainBoard.PcbDoc	Unknown Pin: Pin IC15-8
Add	IC15-10 to GND	In	MainBoard.PcbDoc	Unknown Pin: Pin IC15-10
Add	IC15-11 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC15-11
Add	IC15-12 to VCC_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC15-12
Add	IC15-13 to NetIC15_13		MainBoard.PcbDoc	Unknown Pin: Pin IC15-13
Add	IC15-14 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC15-14
Add	IC15-16 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC15-16
Add	IC15-17 to VCC_ISO IC15-20 to GND_ISO		MainBoard PobDoc	Unknown Pin: Pin IC15-17
Add Add	IC15-20 to GND_ISO IC17-1 to GND		MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IC15-20 Unknown Pin: Pin IC17-1
Add	IC17-1 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC17-5
Add	IC17-7 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC17-7
Add	IC17-8 to NetIC17_8		MainBoard.PcbDoc	Unknown Pin: Pin IC17-8
Add	IC17-10 to GND		MainBoard.PcbDoc	Unknown Pin: Pin IC17-10
Add	IC17-11 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC17-11
Add	IC17-12 to VCC_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC17-12
Add	IC17-13 to NetIC17_13		MainBoard.PcbDoc	Unknown Pin: Pin IC17-13
Add	IC17-14 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC17-14
Add	IC17-16 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC17-16
Add	IC17-17 to VCC_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC17-17
Add	IC17-20 to GND_ISO		MainBoard.PcbDoc	Unknown Pin: Pin IC17-20
Add	IN_1-1 to GND_BDD2		MainBoard.PcbDoc	Unknown Pin: Pin IN_1-1
Add	IN_1-2 to BDD1_+		MainBoard.PcbDoc	Unknown Pin: Pin IN_1-2
Add	IN_2-1 to GND_BDD2		MainBoard PobDoc	Unknown Pin: Pin IN_2-1
Add	IN_2-2 to BDD2_+		MainBoard PobDoc	Unknown Pin: Pin IN_2-2
Add			MainBoard PobDoc	Unknown Pin: Pin IN_3_U_Channe
Add Add			MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe Unknown Pin: Pin IN_3_U_Channe
Add			MainBoard.PcbDoc MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add			MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	IN 3 U Channel 3-2 to cerpadio- U Channel 3			Unknown Pin: Pin IN_3_U_Channe
, wu	J_J_O_OHAHHOI_O Z to oblipadioU_OHAHHOI_J	41	manipourur oppoo	STREET OF STREET

štvrtok 3-jún-03/2021 1:54:53 PM Page 3 of 8

Action	Object		Change Document	Status
Add Pin	s To Nets			
Add	IN 3 U Channel 4-1 to cerpadlo+ U Channel 4	In	MainBoard.PcbDoc	Unknown Pin: Pin IN 3 U Channe
Add	IN 3 U Channel 4-2 to cerpadlo- U Channel 4		MainBoard.PcbDoc	Unknown Pin: Pin IN 3 U Channe
Add	IN 3 U Channel 5-1 to cerpadlo+ U Channel 5			Unknown Pin: Pin IN 3 U Channe
Add	IN_3_U_Channel_5-2 to cerpadloU_Channel_5	In	MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	IN_3_U_Channel_6-1 to cerpadlo+_U_Channel_6			Unknown Pin: Pin IN_3_U_Channe
Add	IN_3_U_Channel_6-2 to cerpadloU_Channel_6	ln	MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	IN_3_U_Channel_7-1 to cerpadlo+_U_Channel_7	ln	MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	IN_3_U_Channel_7-2 to cerpadloU_Channel_7	In	MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	IN_3_U_Channel_8-1 to cerpadlo+_U_Channel_8		MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	IN_3_U_Channel_8-2 to cerpadloU_Channel_8	In	MainBoard.PcbDoc	Unknown Pin: Pin IN_3_U_Channe
Add	M1-1 to NetM1_1	In	MainBoard.PcbDoc	Unknown Pin: Pin M1-1
Add	M1-2 to GND_BDD2	ln	MainBoard.PcbDoc	Unknown Pin: Pin M1-2
Add	M1-3 to RELE_2	In	MainBoard.PcbDoc	Unknown Pin: Pin M1-3
Add	M2-1 to NetM2_1	ln	MainBoard.PcbDoc	Unknown Pin: Pin M2-1
Add	M2-2 to GND_BDD2	In	MainBoard.PcbDoc	Unknown Pin: Pin M2-2
Add	OUT_1-1 to OUT_2_BDD_1	In	MainBoard.PcbDoc	Unknown Pin: Pin OUT_1-1
Add	OUT_1-2 to OUT_1_BDD_1	ln	MainBoard.PcbDoc	Unknown Pin: Pin OUT_1-2
Add	OUT_2-1 to OUT_2_BDD_2	ln	MainBoard.PcbDoc	Unknown Pin: Pin OUT_2-1
Add	OUT_2-2 to OUT_1_BDD_2	In	MainBoard.PcbDoc	Unknown Pin: Pin OUT_2-2
Add	Q7-1 to EN_4		MainBoard.PcbDoc	Unknown Pin: Pin Q7-1
Add	Q7-2 to GND	In	MainBoard.PcbDoc	Unknown Pin: Pin Q7-2
Add	Q7-3 to NetIC14_8		MainBoard.PcbDoc	Unknown Pin: Pin Q7-3
Add	Q8-1 to EN_2		MainBoard.PcbDoc	Unknown Pin: Pin Q8-1
Add	Q8-2 to GND	In	MainBoard.PcbDoc	Unknown Pin: Pin Q8-2
Add	Q8-3 to NetIC13_8	In	MainBoard.PcbDoc	Unknown Pin: Pin Q8-3
Add	Q9-1 to EN_6	In	MainBoard.PcbDoc	Unknown Pin: Pin Q9-1
Add	Q9-2 to GND	In	MainBoard.PcbDoc	Unknown Pin: Pin Q9-2
Add	Q9-3 to NetIC15_8	In	MainBoard.PcbDoc	Unknown Pin: Pin Q9-3
Add	Q10-1 to EN_1	In	MainBoard.PcbDoc	Unknown Pin: Pin Q10-1
Add	Q10-2 to GND		MainBoard.PcbDoc	Unknown Pin: Pin Q10-2
Add	Q10-3 to NetIC17_8		MainBoard.PcbDoc	Unknown Pin: Pin Q10-3
Add	RELAY_1.1-1 to OUT_1_BDD_1		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.1-1
Add	RELAY_1.1-2 to 5V	In	MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.1-2
Add	RELAY_1.1-3 to IN+_BDD_1	ln	MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.1-3
Add	RELAY_1.1-4 to INBDD_1		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.1-4
Add	RELAY_1.1-5 to RELE_2	ln	MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.1-5
Add	RELAY_1.2-1 to OUT_2_BDD_1		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.2-1
Add	RELAY_1.2-2 to 5V		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.2-2
Add	RELAY_1.2-3 to INBDD_1		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.2-3
Add	RELAY_1.2-4 to IN+_BDD_1		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.2-4
Add	RELAY_1.2-5 to RELE_2		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_1.2-5
Add	RELAY_2.1-1 to OUT_1_BDD_2		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_2.1-1
Add	RELAY_2.1-2 to 5V		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_2.1-2
Add	RELAY_2.1-3 to IN+_BDD_2		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_2.1-3
Add	RELAY_2.1-4 to INBDD_2		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_2.1-4
Add	RELAY_2.2-1 to OUT_2_BDD_2		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_2.2-1
Add	RELAY_2.2-2 to 5V		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_2.2-2
Add	RELAY_2.2-3 to INBDD_2		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_2.2-3
Add	RELAY_2.2-4 to IN+_BDD_2		MainBoard.PcbDoc	Unknown Pin: Pin RELAY_2.2-4
Add	S1-1 to GND		MainBoard.PcbDoc	Unknown Pin: Pin S1-1
Add	S1-2 to RST	ln	MainBoard.PcbDoc	Unknown Pin: Pin S1-2
Add Net				
Add	3V3		MainBoard.PcbDoc	
Add	RELE_2		MainBoard.PcbDoc	
Add	SCL_ISO	То	MainBoard.PcbDoc	
Add	SCL_ISO		MainBoard.PcbDoc	
Add	SCL ISO	To	MainBoard PcbDoc	

Add N	ets	
Add	3V3	To MainBoard.PcbDoc
Add	RELE_2	To MainBoard.PcbDoc
Add	SCL_ISO	To MainBoard.PcbDoc
Add	SCL	To MainBoard.PcbDoc
Add	SCL	To MainBoard.PcbDoc
Add	SDA_ISO	To MainBoard.PcbDoc
Add	SDA_ISO	To MainBoard.PcbDoc
Add	SDA_ISO	To MainBoard.PcbDoc
Add	SDA ISO	To MainBoard.PcbDoc

Page 4 of 8 štvrtok 3-jún-03/2021 1:54:53 PM

Action	Object	Change Document	Status
A 1 1 A	(O)		
	omponent Class Members		
Add	5V to U_Power	In MainBoard.PcbDoc	
Add	12V to U_Power	In MainBoard.PcbDoc	
Add	ADR0_1 to PAC_BDD_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR0_2 to PAC_BDD_2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR1_1 to PAC_BDD_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR1_2 to PAC_BDD_2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR1 U Channel 1 to U Channel 1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR1 U Channel 2 to U Channel 2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR1 U Channel 3 to U Channel 3	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR1 U Channel 4 to U Channel 4	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR1_U_Channel_5 to U_Channel_5	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR1 U Channel 6 to U Channel 6	In MainBoard.PcbDoc	Failed to add class member: Com
Add	ADR1 U Channel 7 to U Channel 7	In MainBoard.PcbDoc	Failed to add class member: Com
Add	ADR1 U Channel 8 to U Channel 8		
		In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR2_U_Channel_1 to U_Channel_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR2_U_Channel_2 to U_Channel_2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR2_U_Channel_3 to U_Channel_3	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR2_U_Channel_4 to U_Channel_4	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR2_U_Channel_5 to U_Channel_5	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR2_U_Channel_6 to U_Channel_6	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR2_U_Channel_7 to U_Channel_7	In MainBoard.PcbDoc	Failed to add class member : Com
Add	ADR2_U_Channel_8 to U_Channel_8	In MainBoard.PcbDoc	Failed to add class member : Com
Add	C1 to U_ESP32	In MainBoard.PcbDoc	
Add	C2 to U_ESP32	In MainBoard.PcbDoc	
Add	C3 to U_ESP32	In MainBoard.PcbDoc	
Add	C4 to U_ESP32	In MainBoard.PcbDoc	
Add	C5 to U_ESP32	In MainBoard.PcbDoc	
Add	C6 to U_ESP32	In MainBoard.PcbDoc	
Add	C7 to U ESP32	In MainBoard.PcbDoc	
Add	C8 to U_ESP32	In MainBoard.PcbDoc	
Add	C9 to U_ESP32	In MainBoard.PcbDoc	
Add	C10 to U Power	In MainBoard.PcbDoc	
Add	C11 to U_Power	In MainBoard.PcbDoc	
Add	C12 to U_Power	In MainBoard.PcbDoc	
Add	C13 to U_Power	In MainBoard.PcbDoc	
Add	C14 to U_Power	In MainBoard.PcbDoc	
Add	C15 to U_Power	In MainBoard.PcbDoc	
Add	C16 to U_Power	In MainBoard.PcbDoc	
Add	C17 to U_Power	In MainBoard.PcbDoc	
Add	C18 to U_Power	In MainBoard.PcbDoc	
Add	C19 to U_Power	In MainBoard.PcbDoc	
Add	C20 to U_Power	In MainBoard.PcbDoc	
Add	C21 to U Power	In MainBoard.PcbDoc	
Add	C22 to U Power	In MainBoard.PcbDoc	
Add	C23 to U Power	In MainBoard.PcbDoc	
Add	C24 to U Power	In MainBoard.PcbDoc	
Add	C25 to U_Power	In MainBoard.PcbDoc	
Add	C26 to U Power	In MainBoard.PcbDoc	
Add	C27 to polarita_BDD_1	In MainBoard.PcbDoc	
Add	C28 to polarita_BDD_1	In MainBoard.PcbDoc	
Add	C29 to U_Duty_cycle_BDD	In MainBoard.PcbDoc	
		In MainBoard.PcbDoc	
Add	C30 to U_Duty_cycle_BDD		
Add	C31 to U_BDD	In MainBoard.PcbDoc	
Add	C32 to U_BDD	In MainBoard.PcbDoc	
Add	C33 to U_Power	In MainBoard.PcbDoc	
Add	C34 to U_Power	In MainBoard.PcbDoc	
Add	C35 to U_Power	In MainBoard.PcbDoc	
Add	C36 to U_Power	In MainBoard.PcbDoc	
Add	C37 to U_Power	In MainBoard.PcbDoc	
Add	C38_U_Channel_1 to U_Channel_1	In MainBoard.PcbDoc	Failed to add class member : Com
Add	C38_U_Channel_2 to U_Channel_2	In MainBoard.PcbDoc	Failed to add class member : Com
Add	C38_U_Channel_3 to U_Channel_3	In MainBoard.PcbDoc	Failed to add class member : Com
Add	C38 U Channel 4 to U Channel 4	In MainBoard.PcbDoc	Failed to add class member : Com
Add	C38 U Channel 5 to U Channel 5	In MainBoard.PcbDoc	Failed to add class member : Com
Add	C38_U_Channel_6 to U_Channel_6	In MainBoard.PcbDoc	Failed to add class member : Com
Add	C38 U Channel 7 to U Channel 7	In MainBoard.PcbDoc	Failed to add class member: Com
Add	C38 U Channel 8 to U Channel 8	In MainBoard.PcbDoc	Failed to add class member: Com
Add	C39_U_Channel_1 to U_Channel_1	In MainBoard.PcbDoc	i alled to add class membel . Com
Add	C39_U_Channel_2 to U_Channel_2	In MainBoard.PcbDoc	

Change Document

Status

Action Object

štvrtok 3-jún-03/2021 1:54:53 PM Page 5 of 8

Action	Object		Change Document	Status
Add Co	mu anant Class Mambana			
	mponent Class Members	-	M : D ID D	
Add	C39_U_Channel_3 to U_Channel_3		MainBoard.PcbDoc	
Add	C39 U Channel 4 to U Channel 4		MainBoard.PcbDoc	
Add	C39_U_Channel_5 to U_Channel_5		MainBoard.PcbDoc	
Add	C39_U_Channel_6 to U_Channel_6		MainBoard.PcbDoc	
Add	C39_U_Channel_7 to U_Channel_7		MainBoard.PcbDoc	
Add	C39_U_Channel_8 to U_Channel_8		MainBoard.PcbDoc	
Add	C40 to U_H_Bridge	In	MainBoard.PcbDoc	
Add	C41 to U_H_Bridge		MainBoard.PcbDoc	
Add	C42 to U_pH_EZO_2	In	MainBoard.PcbDoc	
Add	C43 to U_pH_EZO_2	ln	MainBoard.PcbDoc	
Add	C44 to U pH EZO 2	In	MainBoard.PcbDoc	
Add	C45 to U_pH_EZO_2		MainBoard.PcbDoc	
Add	C46 to U DO EZO 1		MainBoard.PcbDoc	
Add	C47 to U_DO_EZO_1		MainBoard.PcbDoc	
Add	C48 to U DO EZO 1		MainBoard.PcbDoc	
Add	C49 to U_DO_EZO_1		MainBoard.PcbDoc	
Add	C50 to U_TDS_EZO_1		MainBoard.PcbDoc	
Add			MainBoard.PcbDoc MainBoard.PcbDoc	
	C51 to U_TDS_EZO_1			
Add	C52 to U_TDS_EZO_1		MainBoard.PcbDoc	
Add	C53 to U_TDS_EZO_1		MainBoard.PcbDoc	
Add	C54 to U_pH_EZO_1		MainBoard.PcbDoc	
Add	C55 to U_pH_EZO_1		MainBoard.PcbDoc	
Add	C56 to U_pH_EZO_1		MainBoard.PcbDoc	
Add	C57 to U_pH_EZO_1		MainBoard.PcbDoc	
Add	D1.1 to polarita_BDD_1	In	MainBoard.PcbDoc	Failed to add class member : Com
Add	D1.2 to polarita_BDD_1	ln	MainBoard.PcbDoc	Failed to add class member : Com
Add	D1 to U_ESP32	In	MainBoard.PcbDoc	
Add	D2.1 to polarita BDD 2	In	MainBoard.PcbDoc	Failed to add class member : Com
Add	D2.2 to polarita_BDD_2		MainBoard.PcbDoc	Failed to add class member : Com
Add	D2 to U_ESP32		MainBoard.PcbDoc	
Add	D3 to U_Rele		MainBoard.PcbDoc	
Add	D4 to U Rele		MainBoard.PcbDoc	
Add	D5 to U Rele		MainBoard.PcbDoc	
Add	D6 to U Rele		MainBoard.PcbDoc	
Add	DO EZO1 to U DO EZO 1		MainBoard.PcbDoc	
Add	Extern_Voltage to U_Rele		MainBoard.PcbDoc	
Add	FB1 to U ESP32		MainBoard.PcbDoc	Failed to add class member : Com
	IC1 to U_ESP32			Falled to add class member . Com
Add			MainBoard.PcbDoc	
Add	IC2 to U_ESP32		MainBoard.PcbDoc	
Add	IC3 to U_Power		MainBoard.PcbDoc	
Add	IC4 to U_Power		MainBoard.PcbDoc	
Add	IC5 to U_Power		MainBoard.PcbDoc	
Add	IC6 to U_Rele		MainBoard.PcbDoc	
Add	IC7 to U_temp_humidity		MainBoard.PcbDoc	Failed to add class member : Com
Add	IC8 to U_BDD	In	MainBoard.PcbDoc	
Add	IC9 to U_Power	In	MainBoard.PcbDoc	
Add	IC10_U_Channel_1 to U_Channel_1	In	MainBoard.PcbDoc	
Add	IC10_U_Channel_2 to U_Channel_2	In	MainBoard.PcbDoc	
Add	IC10_U_Channel_3 to U_Channel_3		MainBoard.PcbDoc	
Add	IC10_U_Channel_4 to U_Channel_4		MainBoard.PcbDoc	
Add	IC10 U Channel 5 to U Channel 5		MainBoard.PcbDoc	
Add	IC10_U_Channel_6 to U_Channel_6		MainBoard.PcbDoc	
Add	IC10 U Channel 7 to U Channel 7		MainBoard.PcbDoc	
Add	IC10_U_Channel_8 to U_Channel_8		MainBoard.PcbDoc	
Add	IC11 to U_H_Bridge		MainBoard.PcbDoc	
Add	IC12 to U_Zmena polarity_BDD		MainBoard.PcbDoc MainBoard.PcbDoc	
Add	IC13 to U_DO_EZO_1		MainBoard.PcbDoc MainBoard.PcbDoc	Failed to add class member : Com
Add	IC14 to U_pH_EZO_2		MainBoard PobDoc	Failed to add class member : Com
Add	IC15 to U_TDS_EZO_1		MainBoard.PcbDoc	Failed to add class member : Com
Add	IC16 to U_WQLT		MainBoard.PcbDoc	E 9 14 14 1 2 2
Add	IC17 to U_pH_EZO_1		MainBoard.PcbDoc	Failed to add class member : Com
Add	IC_BDD_1.1 to PAC_BDD_1		MainBoard.PcbDoc	
Add	IC_BDD_1.2 to PAC_BDD_1		MainBoard.PcbDoc	
Add	IC_BDD_2.1 to PAC_BDD_2		MainBoard.PcbDoc	
Add	IC_BDD_2.2 to PAC_BDD_2	In	MainBoard.PcbDoc	
Add	IN_1 to U_BDD	In	MainBoard.PcbDoc	Failed to add class member : Com
Add	IN_2 to U_BDD	In	MainBoard.PcbDoc	Failed to add class member : Com
Add	IN_3_U_Channel_1 to U_Channel_1		MainBoard.PcbDoc	Failed to add class member : Com
Auu				
Add	IN 3 U Channel 2 to U Channel 2	ln	MainBoard.PcbDoc	Failed to add class member : Com

Change Document

Status

Action Object

štvrtok 3-jún-03/2021 1:54:53 PM Page 6 of 8

Add N. 3 U. Channel & to U. Channel & In Man-Board PocDoc Falled to add class member: Com Add N. 3 U. Channel & fol U. Channe	Action	Object	Change Document	Status
Ass.	Add C	omponent Class Members		
Add N. 3.U. Chamel & to U. Chamel & 5 to U. Chamel & 5 to U. Chamel & 1 to			In MainBoard.PcbDoc	Failed to add class member : Com
Add N. 3. U. Chennel & D. U. Channel & In. Man-Board PubDoc Feliated to add class member: Com Add N. 3. U. Chennel & D. U. Channel & D. U. Cha				Failed to add class member : Com
Add N. 3. U. Channel 7 to U. Channel 7. In ManBoard PooDoc Feliat of add class member: Com Add N. 3. U. Channel 8 to U. Channel 8 in ManBoard PooDoc Feliat of add class member: Com Add M. 10 potentia BDD 1 in ManBoard PooDoc Feliat of add class member: Com Add M. 10 potentia BDD 2 in ManBoard PooDoc Feliat of add class member: Com Add M. 10 potentia BDD 2 in ManBoard PooDoc Feliat of add class member: Com Add OUT 1 to U. BDD in ManBoard PooDoc Feliat of add class member: Com Add OUT 2 to U. BDD in ManBoard PooDoc Feliat of add class member: Com Add OUT 2 to U. BDD in ManBoard PooDoc Feliat of add class member: Com Add OUT 2 to U. BDD in ManBoard PooDoc Feliat of add class member: Com Add OUT 2 to U. BH EZO 2 in ManBoard PooDoc Feliat of add class member: Com Add OUT 2 to U. BH EZO 2 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 2 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc Add OUT 3 to U. BH EZO 3 in ManBoard PooDoc A				
Add L to U ESP32 In ManBaser PobDoc Faled to add class member : Con Add L to U ESP32 In ManBaser PobDoc Faled to add class member : Con Add L to U ESP32 In ManBaser PobDoc Faled to add class member : Con Add Mot to posinis BDD 2 In ManBaser PobDoc Faled to add class member : Con Add Mot to posinis BDD 2 In ManBaser PobDoc Faled to add class member : Con Add OUT : 10 U BDD In ManBaser PobDoc Faled to add class member : Con Add OUT : 20 U BDD In ManBaser PobDoc Faled to add class member : Con Add OUT : 20 U BDD In ManBaser PobDoc Faled to add class member : Con Add D				
Add M to goarde BDD 1 in MainBoard PobDoc Falled to add class member: Com Add M to goarde BDD 2 in MainBoard PobDoc Falled to add class member: Com Add DUT 1 but BDD in MainBoard PobDoc Falled to add class member: Com Add OUT 1 but BDD in MainBoard PobDoc Falled to add class member: Com Add DUT 2 but BDD in MainBoard PobDoc Falled to add class member: Com Add DUT 2 but BDD in MainBoard PobDoc Falled to add class member: Com Add Dut 1 but BDD in MainBoard PobDoc Falled to add class member: Com Add Dut 1 but ESD 2 in MainBoard PobDoc Falled to add class member: Com Add Dut 1 but ESD 2 in MainBoard PobDoc Falled to add class member: Com Add Dut 1 but ESD 2 in MainBoard PobDoc Falled to add class member: Com Add Dut 1 but ESD 2 in MainBoard PobDoc Falled to Add class MainBoard PobDoc Falled to Add Class Fall Class Fal				
Add Mit to polarita 800 1 In MariBoard Po200c Falled to add class member: Com Add Mit to polarita 800 2 In MariBoard Po200c Falled to add class member: Com Add OUT 1 to U 800 In MariBoard Po200c Falled to add class member: Com Add OUT 2 to U 800 In MariBoard Po200c Falled to add class member: Com Add Pit E201 to U 91 E20 2 In MariBoard Po200c Add Pit E201 to U 91 E20 1 In MariBoard Po200c Add Pit E201 to U 91 E20 2 In MariBoard Po200c Add Pit E201 to U 91 E20 2 In MariBoard Po200c Add O2 to U 58792 In MariBoard Po200c Falled to add class member: Com Add O2 to U 58792 In MariBoard Po200c Falled to add class member: Com Add O2 to U 58792 In MariBoard Po200c Falled to add class member: Com Add O2 to U 58792 In MariBoard Po200c Falled to add class member: Com Add O2 to U 58792 In MariBoard Po200c Falled to add class member: Com Add O2 to U 58792 In MariBoard Po200c Falled to add class member: Com Add II to U 58792 In MariBoard Po200c Falled to add class member: Com Add II to U 58792 In MariBoard Po200c Falled to add class member: Com Add II to U 58792 In MariBoard Po200c Falled to add class member: Com Add II to U 58792 In MariBoard Po200c Falled to add class member: Com Add II to U 58792 In MariBoard Po200c Falled to add class member: Com Add II to U 58792 In MariBoard Po200c Falled to add class member: Com Add II to U 58792 In MariBoard Po200c Falled to add class member: Com Add II to U 58792 In MariBoard Po200c Falled to Add Class member: Com Add II to U 58792 In MariBoard Po200c Falled to Add Class member: Com Add II to U 5879				Falled to add class member . Com
Add Wit to U BDD In MainBoard PobDoc Falled to add class member : Com Add OUT : 2 to U BDD In MainBoard PobDoc Falled to add class member : Com Add DUT : 2 to U BDD In MainBoard PobDoc Falled to add class member : Com Add Pet EZO 1 to U pt EZO 2 in MainBoard PobDoc Add Pet EZO 1 to U pt EZO 2 in MainBoard PobDoc Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to add class member : Com Add Cit to U ESP32 in MainBoard PobDoc Falled to Add Cit to U ESP32 in MainBoard PobDoc Falled to Add Cit to U ESP32 in MainBoard PobDoc Falled to Doc Falled to Add Cit to U ESP32 in MainBoard PobDoc Falled to D				Failed to add class member : Com
Add OUT 1 to U BDD In MailBoard PcbDoc Failed to add class member: Com Add OUT 2 to U BDD In MailBoard PcbDoc Failed to add class member: Com Add Pct EZO 1 to U pt EZO 2 In MailBoard PcbDoc Add Pct EZO 2 to U pt EZO 1 In MailBoard PcbDoc Add Oz 1 to U ESP32 In MailBoard PcbDoc Add Oz 1 to U ESP32 In MailBoard PcbDoc Add Oz 1 to U ESP32 In MailBoard PcbDoc Add Oz 1 to U ESP32 In MailBoard PcbDoc Add Oz 1 to U ESP32 In MailBoard PcbDoc Add Oz 1 to U ESP32 In MailBoard PcbDoc Add Oz 1 to U ESP32 In MailBoard PcbDoc Add Oz 1 to U ESP32 In MailBoard PcbDoc Add Oz 1 to U pt V code BDD 1 In MailBoard PcbDoc Add Oz 1 to U pt V code BDD 1 In MailBoard PcbDoc Add Oz 1 to U pt V code BDD 1 In MailBoard PcbDoc Add Oz 1 to U pt V code BDD 1 In MailBoard PcbDoc Add Oz 1 to U pt V code BDD 1 In MailBoard PcbDoc Falled to add class member: Com Add Oz 1 to U pt EZO 2 In MailBoard PcbDoc Falled to add class member: Com Add Oz 1 to U pt EZO 1 In MailBoard PcbDoc Falled to add class member: Com Add Oz 1 to U pt EZO 1 In MailBoard PcbDoc Falled to add class member: Com Add Oz 1 to U pt EZO 1 In MailBoard PcbDoc Falled to add class member: Com Add Oz 1 to U pt EZO 1 In MailBoard PcbDoc Falled to add class member: Com Add Oz 1 to U pt EZO 2 In MailBoard PcbDoc Falled to add class member: Com Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard PcbDoc Add Rz 1 to U ESP32 In MailBoard Pcb				
Add PH EZO1 to U pH EZO 1				Failed to add class member : Com
Add Of 10 to USP32 In MainBoard Pebboe Add Of 10 to Usry cycle, BDO 1 In MainBoard Pebboe Add Of 10 to Usry cycle, BDO 2 In MainBoard Pebboe Add Of 10 to Usry cycle, BDO 2 In MainBoard Pebboe Add Of 10 to Usry cycle, BDO 1 In MainBoard Pebboe Add Of 10 to Usry cycle, BDO 1 In MainBoard Pebboe Add Of 10 to Usry cycle, BDO 1 In MainBoard Pebboe Add Of 10 to USP32 In MainBoard Pebboe Add Of 10 to USP32 In MainBoard Pebboe Add R1 to Usp4 cycle BDO 1 In MainBoard Pebboe Add R1 to Usp4 cycle BDO 2 In MainBoard Pebboe Add R	Add	OUT_2 to U_BDD	In MainBoard.PcbDoc	Failed to add class member : Com
Add Q 10 b U SP32 In ManBoard Pobloc Add Q 20 b U SP32 In ManBoard Pobloc Add Q 40 b U SP32 In ManBoard Pobloc Add Q 40 b Ux yedie BDD 1 In ManBoard Pobloc Add Q 40 b Ux yedie BDD 2 In ManBoard Pobloc Add Q 60 b Ux yedie BDD 2 In ManBoard Pobloc Add Q 60 b Ux yedie BDD 2 In ManBoard Pobloc Add Q 60 b Ux yedie BDD 2 In ManBoard Pobloc Add Q 60 b Ux yedie BDD 2 In ManBoard Pobloc Falled b add diass member : Com Add Q 60 b Ux yedie BDD 2 In ManBoard Pobloc Falled b add diass member : Com Add Q 60 b Ux yedie BDD 2 In ManBoard Pobloc Falled b add diass member : Com Add Q 60 b Ux H SZO 1 In ManBoard Pobloc Falled b add diass member : Com Add Q 10 b Ux H SZO 1 In ManBoard Pobloc Falled b add diass member : Com Add Q 10 b Ux H SZO 1 In ManBoard Pobloc Falled b add diass member : Com Add Q 10 b Ux H SZO 1 In ManBoard Pobloc Falled b add class member : Com Add Q 10 b Ux H SZO 1 In ManBoard Pobloc Falled b add class member : Com Add Q 10 b Ux H SZO 1 In ManBoard Pobloc Falled b add class member : Com Add R 10 b U SZO 2 In ManBoard Pobloc Falled b add class member : Com Add R 10 b U SZO 2 In ManBoard Pobloc Falled b add class member : Com Add R 10 b U SZO 2 In ManBoard Pobloc Falled b add class member : Com Add R 10 b U SZO 2 In ManBoard Pobloc Falled b Add R 20 b U SZO 2 In ManBoard Pobloc Falled b Add R 20 b U SZO 2 In ManBoard Pobloc Falled b Add R 20 b U SZO 2 In ManBoard Pobloc Falled b Add R 20 b U SZO 2 In ManBoard Pobloc Falled Falled b Add R 20 b U SZO 2 In ManBoard Pobloc Falled Falle				
Add O3 to U SP32 In ManBoard Pebboo Add O3 to Usy, zyde, BDD, 2 In ManBoard Pebboo Add O4 to Duty, zyde, BDD, 2 In ManBoard Pebboo Add O5 to Duty, zyde, BDD, 2 In ManBoard Pebboo Add O5 to Usy, zyde, BDD D In ManBoard Pebboo Add O5 to Usy, zyde, BDD In ManBoard Pebboo Add O5 to Usy, zyde, BDD In ManBoard Pebboo Failed to add class member : Com Add O5 to Usy, zyde, BDD In ManBoard Pebboo Failed to add class member : Com Add O5 to Usy, zyde, BDD In ManBoard Pebboo Failed to add class member : Com Add O5 to Usy EZO In ManBoard Pebboo Failed to add class member : Com Add O5 to Usy EZO In ManBoard Pebboo Failed to add class member : Com Add R1 to Usy EZO In ManBoard Pebboo Failed to add class member : Com Add R1 to Usy EZO In ManBoard Pebboo Failed to add class member : Com Add R1 to Usy EZO In ManBoard Pebboo Failed to add class member : Com Add R1 to Usy EZO In ManBoard Pebboo R1 In ManBoard Pebboo R2 In ManBoard Pebboo R2 In ManBoard Pebboo R3 In ManBoard				
Add Q 4 to Uty sycle BDD 1 In MainBoard Petibloc Add Q 4 to Uty sycle BDD 1 In MainBoard Petibloc Add OS to Duty sycle BDD 2 In MainBoard Petibloc Add OS to Duty sycle BDD 2 In MainBoard Petibloc Add OS to Uty sycle BDD 1 In MainBoard Petibloc Add Q 1 to U pH EZO 2 In MainBoard Petibloc Add Q 1 to U pH EZO 2 In MainBoard Petibloc Add Q 1 to U pH EZO 1 In MainBoard Petibloc Faliet to add class member : Com Add Q 10 to U pH EZO 1 In MainBoard Petibloc Faliet to add class member : Com Add Q 10 to U pH EZO 1 In MainBoard Petibloc Faliet to add class member : Com Add Q 10 to U pH EZO 1 In MainBoard Petibloc Faliet to add class member : Com Add R 1 to U ESP32 In MainBoard Petibloc Add R 1 to L U ESP32 In MainBoard Petibloc Add R 1 to U ESP32 In MainBoard Petibloc Add R 1 to L U ESP32 In MainBoard Petibloc Add R 1 to L U ESP32 In MainBoard Petibloc Add R 1 to L U ESP32 In MainBoard Petibloc Add R 1 to L U ESP32 In MainBoard Petibloc Add R 1 to L U ESP32 In MainBoard Petibloc Add R 1 to L U ESP32 In MainBoard Petibloc Add R 1 to L U ESP32 In MainBoard Petibloc Add R 1 to L U ESP32 In MainBoard Petibloc Add R 1 to L U ESP32 In MainBoar				
Add Os to Dufty cycle BDD 1 In MainBoard Pebboc Os Add Os to Dufty cycle BDD 2 In MainBoard Pebboc Os Add Os to Dufty cycle BDD 1 In MainBoard Pebboc Os Falled to add class member : Com Add Os to U puty, cycle BDD In MainBoard Pebboc Falled to add class member : Com Add Os to U Dot EZO 1 In MainBoard Pebboc Falled add class member : Com Add Os to U TOS EZO 1 In MainBoard Pebboc Falled add class member : Com Add Os to U Dot EZO 1 In MainBoard Pebboc Falled add class member : Com Add Os to U ESP32 In MainBoard Pebboc Falled add class member : Com Add Rt to U ESP32 In MainBoard Pebboc Falled add class member : Com Add Rt to U ESP32 In MainBoard Pebboc Falled add class member : Com Add Rt to U ESP32 In MainBoard Pebboc Falled add class member : Com Add Rt to U ESP32 In MainBoard Pebboc Falled (Rt to U ESP32 In MainBoard				
Add OS to Dufty code BDD 2 In MainBoard Pebboc Add OS to Dufty code BDD In MainBoard Pebboc Falled to add class member : Com Add OS to U polt PEO 2 In MainBoard Pebboc Falled to add class member : Com Add OS to U polt PEO 1 In MainBoard Pebboc Falled to add class member : Com Add OS to U polt PEO 2 In MainBoard Pebboc Falled to add class member : Com Add OS to U polt PEO 2 In MainBoard Pebboc Falled to add class member : Com Add OS to U polt PEO 2 In MainBoard Pebboc Falled to add class member : Com Add R1 to U ESP32 In MainBoard Pebboc Falled to add class member : Com Add R1 to U ESP32 In MainBoard Pebboc Falled to add class member : Com Add R3 to U ESP32 In MainBoard Pebboc Add R3 to U ESP32 In MainBoard Pebboc Add R3 to U ESP32 In MainBoard Pebboc Add R5 to U ESP32 In MainBoard Pebboc Add R5 to U ESP32 In MainBoard Pebboc Add R5 to U ESP32 In MainBoard Pebboc Add R6 to U ESP32 In MainBoard Pebboc Add R6 to U ESP32 In MainBoard Pebboc Add R6 to U ESP32 In MainBoard Pebboc Add R7 to U ESP32 In MainBoard Pebboc Add R7 to U ESP32 In MainBoard Pebboc Add R7 to U ESP32 In MainBoard Pebboc Add R8 to U ESP32 In MainBoard Pebboc Add R1 to Duft ESP32 In MainBoard Pebboc A				
Add Q7 to U pH (270 2 In MainBoard PeaDoc Failed to add class member : Com Add Q7 to U pH (270 2 In MainBoard PeaDoc Failed to add class member : Com Add Q8 to U DO (270 1 In MainBoard PeaDoc Failed to add class member : Com Add Q8 to U DO (270 1 In MainBoard PeaDoc Failed to add class member : Com Add Q8 to U DO (270 1 In MainBoard PeaDoc Failed to add class member : Com Add Q8 to U DO (270 1 In MainBoard PeaDoc Failed to add class member : Com Add Pit to U ESP32 In MainBoard PeaDoc Failed to add class member : Com Add Pit to U ESP32 In MainBoard PeaDoc Add Pit to Dolaria BDO 1 In MainBoard PeaDoc Add Pit to Dolaria BDO 1 In MainBoard PeaDoc Add Pit to Dolaria BDO 2 In MainBoard PeaDoc Add Pit to Dolaria BDO 2 In MainBoard PeaDoc Add Pit to Dolaria BDO 2 In MainBoard PeaDoc Add Pit to Dolaria BDO 2 In MainBoard PeaDo				
Add OR 10 U DC EZO 1 In MainBoard PcDDc Failed to add class member : Com Add OR 10 U DC EZO 1 In MainBoard PcDDc Failed to add class member : Com Add OR 10 U DF EZO 1 In MainBoard PcDDc Failed to add class member : Com Add OR 10 U JM EZO 1 In MainBoard PcDDc Failed to add class member : Com Add R1 to U SP32 In MainBoard PcDDc Failed to add class member : Com Add R1 to U SP32 In MainBoard PcDDc Add R2 to U SP32 In MainBoard PcDDc Add R3 to Dolarita BDD 1 In MainBoard PcDDc Add R3 to Dolarita BDD 1 In MainBoard PcDDc Add R3 to Dolarita BDD 1 In MainBoard PcDDc Add R3 to Dolarita BDD 1 In MainBoard PcDDc Add R3 to Dolarita BDD 1 In MainBoard PcDDc Add R3 to Dolarita BDD 2 In MainBoard PcDDc Add R3 to Dolarita BDD 2 In MainBoard PcDDc Add R3 to Dolarita BDD 2 In MainBoard PcDDc Add R3 to Dolarita BDD 2 In MainBoard PcDDc Add R3 to Dolarita BDD 2 In MainBoard PcDDc Add R3 to Dolarita BDD 2 In MainBoard PcDDc Add R3 to Dolarita BDD 2 In MainBoard PcDDc Add R3 to U Polarita BDD 2 In MainBoard PcDDc Add R3 to U Polarita BDD 2 In MainBoard PcDDc Add R3 to U Polarita BDD 2 In MainBoard PcDDc Add R3 to U				
Add Q 8to U_DO_EZO_1 In MainBoard PcDDc Failed to add class member : Com Add Q 9to U_TOS_EZO_1 In MainBoard PcDDc Failed to add class member : Com Add I 8to U_SEP32 In MainBoard PcDDc Failed to add class member : Com Add R 8to U_SEP32 In MainBoard PcDDc Failed to add class member : Com Add R 8to U_SEP32 In MainBoard PcDDc Add R 8to D_USEP32 In MainBoard PcDDc Add R 8to Dolarta BDD 1 In MainBoard PcDDc Add R 8to Dolarta BDD 1 In MainBoard PcDDc Add R 8to Dolarta BDD 1 In MainBoard PcDDc Add R 8to Dolarta BDD 1 In MainBoard PcDDc Add R 8to Dolarta BDD 2 In MainBoard PcDDc Add R 8to Duty, cycle BDD 1 In MainBoard PcDDc Add R 8to Duty, cycle BDD 2 In MainBoard PcDDc Add R 8to Duty, cycle BDD 2 In MainBoard PcDDc Add R 8to Duty, cycle BDD 2 In MainBoard PcDDc Add R 8to Duty, cycle BDD 2 In MainBoard PcDDc Add R 8to Duty, cycle BDD 2 In MainBoard PcDDc Add R 8to U_Span 4to U_Span 4to U_Spa				Failed to add class member : Com
Add Ol 10 L DH EZO 1 In MainBoard PebDoc Faled to add class member : Com Add Ol 10 L DH EZO 1 In MainBoard PebDoc Faled to add class member : Com Add R1 to U ESP32 In MainBoard PebDoc Add R2 to U ESP32 In MainBoard PebDoc Add R3 to U ESP32 In MainBoard PebDoc Add R3 to U ESP32 In MainBoard PebDoc Add R3 to U ESP32 In MainBoard PebDoc Add R5 to Dolarts BDD 1 In MainBoard PebDoc Add R5 to polarts BDD 1 In MainBoard PebDoc Add R5 to polarts BDD 1 In MainBoard PebDoc Add R5 to polarts BDD 1 In MainBoard PebDoc Add R5 to polarts BDD 2 In MainBoard PebDoc Add R5 to polarts BDD 2 In MainBoard PebDoc Add R5 to polarts BDD 2 In MainBoard PebDoc Add R5 to polarts BDD 2 In MainBoard PebDoc Add R5 to polarts BDD 2 In MainBoard PebDoc Add R5 to polarts BDD 2 In MainBoard PebDoc Add R5 to polarts BDD 2 In MainBoard PebDoc Add R5 to polarts BDD 2 In MainBoard PebDoc Add R5 to polarts BDD 2 In MainBoard PebDoc Add R5 to polarts BDD 2 In MainBoard PebDoc Add R5 to Duty, cycle BDD 1 In MainBoard PebDoc Add R5 to Duty, cycle BDD 2 In MainBoard PebDoc Add R5 to U Rele In MainBoard PebDoc Add R5 to U Rele In MainBoard PebDoc Add R5 to U				
Add R to U ESP32 In MainBoard PebDoc Add R to Duty evole BDD 1 In MainBoard PebDoc Add R to Duty evole BDD 1 In MainBoard PebDoc Add R to Duty evole BDD 1 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to Duty evole BDD 2 In MainBoard PebDoc Add R to U Duty evole BDD 2 In MainBoard PebDoc Add		Q9 to U_TDS_EZO_1		Failed to add class member : Com
Add			In MainBoard.PcbDoc	Failed to add class member : Com
Add R 4 to U ESP32 In MainBoard PebDoc Add R 5 to U ESP32 In MainBoard PebDoc Add R 5 to U ESP32 In MainBoard PebDoc Add R5 to Delarta BDD 1 In MainBoard PebDoc Add R5 to Delarta BDD 1 In MainBoard PebDoc Add R5 to Delarta BDD 1 In MainBoard PebDoc Add R5 to Delarta BDD 1 In MainBoard PebDoc Add R6 to Duty, cycle BDD 1 In MainBoard PebDoc Add R6 to Duty, cycle BDD 1 In MainBoard PebDoc Add R6 to Duty, cycle BDD 1 In MainBoard PebDoc Add R6 to Duty, cycle BDD 1 In MainBoard PebDoc Add R6 to Duty, cycle BDD 1 In MainBoard PebDoc Add R6 to Duty, cycle BDD 2 In MainBoard PebDoc Add R6 to Duty, cycle BDD 2 In MainBoard PebDoc Add R6 to Duty cycle BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to Delarta BDD 2 In MainBoard PebDoc Add R6 to U Rele In MainBoard PebDoc Add R6 to U Rele In MainBoard PebDoc Add R6 to U Rele In MainBoard PebD				
Add R 5 to U ESP32 In MainBeard PebDoc Add R5 to U ESP32 In MainBeard PebDoc Add R6 to U ESP32 In MainBeard PebDoc Add R6 to U ESP32 In MainBeard PebDoc Add R7 to U ESP32 In MainBeard PebDoc Add R7 to U ESP32 In MainBeard PebDoc Add R8 to U ESP32 In MainBeard PebDoc Add R8 to U ESP32 In MainBeard PebDoc Add R1 to Delarita BDD 1 In MainBeard PebDoc Add R1 to polarita BDD 1 In MainBeard PebDoc Add R1 to polarita BDD 1 In MainBeard PebDoc Add R1 to polarita BDD 1 In MainBeard PebDoc Add R1 to Douby cycle BDD 1 In MainBeard PebDoc Add R1 to Duty cycle BDD 1 In MainBeard PebDoc Add R1 to Duty cycle BDD 1 In MainBeard PebDoc Add R2 to polarita BDD 2 In MainBeard PebDoc Add R2 to polarita BDD 2 In MainBeard PebDoc Add R2 to polarita BDD 2 In MainBeard PebDoc Add R2 to polarita BDD 2 In MainBeard PebDoc Add R2 to polarita BDD 2 In MainBeard PebDoc Add R2 to polarita BDD 2 In MainBeard PebDoc Add R2 to polarita BDD 2 In MainBeard PebDoc Add R2 to polarita BDD 2 In MainBeard PebDoc Add R2 to polarita BDD 2 In MainBeard PebDoc Add R2 to Polarita BDD 2 In MainBeard PebDoc Add R2 to Polarita BDD 2 In MainBeard PebDoc Add R2 to Dolarita BDD 2 In MainBeard PebDoc Add R2 to Dolarita BDD 2 In MainBeard PebDoc Add R2 to Dolarita BDD 2 In MainBeard PebDoc Add R2 to Dolarita BDD 2 In MainBeard PebDoc Add R2 to Dolarita BDD 2 In MainBeard PebDoc Add R2 to Dolarita BDD 2 In MainBeard PebDoc Add R2 to Dolarita BDD 2 In MainBeard PebDoc Add R2 to Dolarita BDD 2 In MainBeard PebDoc Add R2 to Dolarita BDD 2 In MainBeard PebDoc Add R2 to Universe BDD 2 In MainBeard PebDoc Add R2 to Universe BDD 2 In MainBeard PebDoc Add R3 to Universe BDD 2 In MainBeard PebDoc Add				
Add				
Add				
Add				
Add				
MainBoard PobDoc MainBoard P				
MainBoard PebDoc MainBoard P				
MainBoard PebDoc MainBoard P				
Add				
Add	Add			
Add R15 to polarita BDD 1 In MainBoard PcbDoc Add R16 to polarita BDD 1 In MainBoard PcbDoc Add R17 to polarita BDD 1 In MainBoard PcbDoc Add R18 to Duty, cycle_BDD 1 In MainBoard PcbDoc Add R19 to Duty, cycle_BDD 1 In MainBoard_PcbDoc Add R20 to polarita BDD 2 In MainBoard_PcbDoc Add R21 to polarita BDD 2 In MainBoard_PcbDoc Add R22 to polarita BDD 2 In MainBoard_PcbDoc Add R23 to Duty, cycle_BDD 2 In MainBoard_PcbDoc Add R23 to Duty, cycle_BDD 2 In MainBoard_PcbDoc Add R24 to Duty_cycle_BDD 2 In MainBoard_PcbDoc Add R25 to PAC_BDD 1 In MainBoard_PcbDoc Add R25 to PAC_BDD 1 In MainBoard_PcbDoc Add R26 to PAC_BDD 2 In MainBoard_PcbDoc Add R26 to PAC_BDD 1 In MainBoard_PcbDoc Add R26 to PAC_BDD 2 In MainBoard_PcbDoc Add R26 to PAC_BDD 2 In MainBoard_PcbDoc Add R26 to PAC_BDD 2 In MainBoard				
Add R16 to polarita BDD 1 In MainBoard.PcbDoc Add R17 to polarita BDD 1 In MainBoard.PcbDoc Add R18 to Duty, cycle BDD 1 In MainBoard.PcbDoc Add R19 to Duty, cycle BDD 1 In MainBoard.PcbDoc Add R20 to polarita BDD 2 In MainBoard.PcbDoc Add R22 to Dolty, cycle BDD 2 In MainBoard.PcbDoc Add R24 to Duty, cycle BDD 2 In MainBoard.PcbDoc Add R25 to PAC BDD 2 In MainBoard.PcbDoc Add R28 to PAC BDD 2 In MainBoard.PcbDoc Add				
Add R17 to polarita BDD 1 In MainBoard.PcbDoc Add R18 to Duty, cycle BDD 1 In MainBoard.PcbDoc Add R19 to Duty, cycle BDD 1 In MainBoard.PcbDoc Add R20 to polarita BDD 2 In MainBoard.PcbDoc Add R21 to polarita BDD 2 In MainBoard.PcbDoc Add R22 to polarita BDD 2 In MainBoard.PcbDoc Add R22 to polarita BDD 2 In MainBoard.PcbDoc Add R22 to polarita BDD 2 In MainBoard.PcbDoc Add R24 to Duty, cycle BDD 2 In MainBoard.PcbDoc Add R24 to Duty, cycle BDD 2 In MainBoard.PcbDoc Add R25 to PAC BDD 1 In MainBoard.PcbDoc Add R26 to PAC BDD 2 In MainBoard.PcbDoc Add R28 to U Rele In MainBoard.PcbDoc Add R28 to U Rele In MainBoard.PcbDoc Add R31 U Channel 1 to U Channel 2 In MainBoar				
Add R18 to Duty cycle BDD 1 In MainBoard PcbDoc Add R19 to Duty cycle BDD 1 In MainBoard PcbDoc Add R20 to polarita BDD 2 In MainBoard PcbDoc Add R21 to polarita BDD 2 In MainBoard PcbDoc Add R22 to polarita BDD 2 In MainBoard PcbDoc Add R23 to Duty cycle BDD 2 In MainBoard PcbDoc Add R24 to Duty cycle BDD 2 In MainBoard PcbDoc Add R24 to Duty cycle BDD 2 In MainBoard PcbDoc Add R25 to PAC BDD 1 In MainBoard PcbDoc Add R26 to PAC BDD 2 In MainBoard PcbDoc Add R27 to U Rele In MainBoard PcbDoc Add R28 to U Rele In MainBoard PcbDoc Add R28 to U Rele In MainBoard PcbDoc Add R29 to U Rele In MainBoard PcbDoc Add R31 U C Rele In MainBoard PcbDoc Add R31 U C Rele In MainBoard PcbDoc Add R31 U C Channel 2 to U Channel 3 In MainBoard PcbDoc Add R31 U C Channel 4 to U Channel 4 In MainBoard PcbDoc				
Add R19 to Duty_cycle_BDD_1 In MainBoard.PcbDoc Add R20 to polarita_BDD_2 In MainBoard.PcbDoc Add R21 to polarita_BDD_2 In MainBoard.PcbDoc Add R22 to polarita_BDD_2 In MainBoard.PcbDoc Add R23 to Duty_cycle_BDD_2 In MainBoard.PcbDoc Add R24 to Duty_cycle_BDD_2 In MainBoard.PcbDoc Add R25 to PAC_BDD_1 In MainBoard.PcbDoc Add R26 to PAC_BDD_2 In MainBoard.PcbDoc Add R26 to PAC_BDD_2 In MainBoard.PcbDoc Add R26 to PAC_BDD_2 In MainBoard.PcbDoc Add R27 to U_Rele In MainBoard.PcbDoc Add R28 to U_Rele In MainBoard.PcbDoc Add R28 to U_Rele In MainBoard.PcbDoc Add R31 U_Channel 1 to U_Channel 1 In MainBoard.PcbDoc Add R31 U_Channel 3 to U_Channel 2 In MainBoard.PcbDoc Add R31 U_Channel 3 to U_Channel 4 In MainBoard.PcbDoc Add R31 U_Channel 5 to U_Channel 5 In MainBoard.PcbDoc Add R31 U_Channel 5 to U_Channel 6 </td <td></td> <td></td> <td></td> <td></td>				
Add R20 to polarita BDD 2 In MainBoard.PcbDoc Add R21 to polarita BDD 2 In MainBoard.PcbDoc Add R22 to polarita BDD 2 In MainBoard.PcbDoc Add R23 to Duty, cycle BDD 2 In MainBoard.PcbDoc Add R24 to Duty, cycle BDD 2 In MainBoard.PcbDoc Add R24 to Duty, cycle BDD 2 In MainBoard.PcbDoc Add R26 to PAC BDD 1 In MainBoard.PcbDoc Add R26 to PAC BDD 2 In MainBoard.PcbDoc Add R28 to U Rele In MainBoard.PcbDoc Add R28 to U. Rele In MainBoard.PcbDoc Add R28 to U. Rele In MainBoard.PcbDoc Add R29 to U. Rele In MainBoard.PcbDoc Add R31 U. Channel 1 to U. Channel 1 In MainBoard.PcbDoc Add R31 U. Channel 2 to U. Channel 2 In MainBoard.PcbDoc Add R31 U. Channel 3 to U. Channel 3 In MainBoard.PcbDoc Add R31 U. Channel 4 to U. Channel 5 In MainBoard.PcbDoc Add R31 U. Channel 5 to U. Channel 5 In MainBoard.PcbDoc Add R31 U				
Add R21 to polarita BDD 2 In MainBoard.PcbDoc Add R22 to polarita BDD 2 In MainBoard.PcbDoc Add R23 to Duty, cycle BDD 2 In MainBoard.PcbDoc Add R24 to Duty, cycle BDD 2 In MainBoard.PcbDoc Add R25 to PAC_BDD_1 In MainBoard.PcbDoc Add R26 to PAC_BDD_2 In MainBoard.PcbDoc Add R27 to U_Rele In MainBoard.PcbDoc Add R28 to U_Rele In MainBoard.PcbDoc Add R30 to U_Rele In MainBoard.PcbDoc Add R30 to U_Rele In MainBoard.PcbDoc Add R31 U_Channel 1 to U_Channel 1 In MainBoard.PcbDoc Add R31 U_Channel 2 to U_Channel 2 In MainBoard.PcbDoc Add R31 U_Channel 3 to U_Channel 3 In MainBoard.PcbDoc Add R31 U_Channel 4 to U_Channel 5 In MainBoard.PcbDoc Add R31 U_Channel 5 to U_Channel 5 In Main				
Add R22 to polarita BDD 2 In MainBoard.PcbDoc Add R23 to Duty, cycle BDD 2 In MainBoard.PcbDoc Add R24 to Duty, cycle BDD 2 In MainBoard.PcbDoc Add R25 to PAC BDD 1 In MainBoard.PcbDoc Add R26 to PAC BDD 2 In MainBoard.PcbDoc Add R27 to U Rele In MainBoard.PcbDoc Add R28 to U Rele In MainBoard.PcbDoc Add R29 to U Rele In MainBoard.PcbDoc Add R31 U Channel 1 to U Channel 1 In MainBoard.PcbDoc Add R31 U Channel 2 to U Channel 2 In MainBoard.PcbDoc Add R31 U Channel 3 to U Channel 2 In MainBoard.PcbDoc Add R31 U Channel 4 to U Channel 4 In MainBoard.PcbDoc Add R31 U Channel 5 to U Channel 5 In MainBoard.PcbDoc Add R31 U Channel 6 to U Channel 5 In MainBoard.PcbDoc Add R31 U Channel 7 to U Channel 6 In MainBoard.PcbDoc Add R31 U Channel 8 to U Channel 8 In MainBoard.PcbDoc Add R31 U Channel 7 to U Channel 8 In MainBoard.PcbDoc <t< td=""><td></td><td></td><td></td><td></td></t<>				
Add R24 to Duty_cycle_BDD_2 In MainBoard.PcbDoc Add R25 to PAC_BDD_1 In MainBoard.PcbDoc Add R26 to PAC_BDD_2 In MainBoard.PcbDoc Add R27 to U_Rele In MainBoard.PcbDoc Add R28 to U_Rele In MainBoard.PcbDoc Add R29 to U_Rele In MainBoard.PcbDoc Add R31 U_Channel_1 to U_Channel_1 In MainBoard.PcbDoc Add R31_U_Channel_2 to U_Channel_2 In MainBoard.PcbDoc Add R31_U_Channel_3 to U_Channel_3 In MainBoard.PcbDoc Add R31_U_Channel_4 to U_Channel_3 In MainBoard.PcbDoc Add R31_U_Channel_5 to U_Channel_5 In MainBoard.PcbDoc Add R31_U_Channel_5 to U_Channel_5 In MainBoard.PcbDoc Add R31_U_Channel_7 to U_Channel_7 In MainBoard.PcbDoc Add R31_U_Channel_8 to U_Channel_8 In MainBoard.PcbDoc Add R31_U_Channel_8 to U_Channel_8 In MainBoard.PcbDoc Add R31_U_Channel_8 to U_Channel_8 In MainBoard.PcbDoc Add R33_to U_pH_EZO_2 In MainBoard.PcbDoc <				
Add R25 to PAC_BDD_1 In MainBoard.PcbDoc Add R26 to PAC_BDD_2 In MainBoard.PcbDoc Add R27 to U_Rele In MainBoard.PcbDoc Add R28 to U_Rele In MainBoard.PcbDoc Add R29 to U_Rele In MainBoard.PcbDoc Add R30 to U_Rele In MainBoard.PcbDoc Add R31_U_Channel_1 to U_Channel_1 In MainBoard.PcbDoc Add R31_U_Channel_2 to U_Channel_2 In MainBoard.PcbDoc Add R31_U_Channel_3 to U_Channel_3 In MainBoard.PcbDoc Add R31_U_Channel_4 to U_Channel_4 In MainBoard.PcbDoc Add R31_U_Channel_5 to U_Channel_5 In MainBoard.PcbDoc Add R31_U_Channel_6 to U_Channel_6 In MainBoard.PcbDoc Add R31_U_Channel_7 to U_Channel_7 In MainBoard.PcbDoc Add R31_U_Channel_7 to U_Channel_8 In MainBoard.PcbDoc Add R31_U_Channel_7 to U_Channel_8 In MainBoard.PcbDoc Add R31_U_Channel_7 to U_Channel_8 In MainBoard.PcbDoc Add R33_U_Dhyll_EZO_2 In MainBoard.PcbDoc Add <td>Add</td> <td>R23 to Duty_cycle_BDD_2</td> <td>In MainBoard.PcbDoc</td> <td></td>	Add	R23 to Duty_cycle_BDD_2	In MainBoard.PcbDoc	
Add R26 to PAC_BDD_2 In MainBoard.PcbDoc Add R27 to U_Rele In MainBoard.PcbDoc Add R28 to U_Rele In MainBoard.PcbDoc Add R29 to U_Rele In MainBoard.PcbDoc Add R30 to U_Rele In MainBoard.PcbDoc Add R31 U_Channel_1 to U_Channel_1 In MainBoard.PcbDoc Add R31 U_Channel_2 to U_Channel_2 In MainBoard.PcbDoc Add R31 U_Channel_3 to U_Channel_3 In MainBoard.PcbDoc Add R31 U_Channel_5 to U_Channel_4 In MainBoard.PcbDoc Add R31 U_Channel_5 to U_Channel_5 In MainBoard.PcbDoc Add R31 U_Channel_6 to U_Channel_6 In MainBoard.PcbDoc Add R31 U_Channel_7 to U_Channel_7 In MainBoard.PcbDoc Add R31 U_Channel_8 to U_Channel_8 In MainBoard.PcbDoc Add R31 U_Channel_8 to U_Channel_8 In MainBoard.PcbDoc Add R33 to U_pH_EZO_2 In MainBoard.PcbDoc Add R34 to U_pH_EZO_2 In MainBoard.PcbDoc Add R35 to U_pH_EZO_2 In MainBoard.PcbDoc Add <t< td=""><td></td><td></td><td></td><td></td></t<>				
Add R27 to U_Rele In MainBoard.PcbDoc Add R28 to U_Rele In MainBoard.PcbDoc Add R29 to U_Rele In MainBoard.PcbDoc Add R30 to U_Rele In MainBoard.PcbDoc Add R31_U_Channel_1 to U_Channel_1 In MainBoard.PcbDoc Add R31_U_Channel_2 to U_Channel_2 In MainBoard.PcbDoc Add R31_U_Channel_3 to U_Channel_3 In MainBoard.PcbDoc Add R31_U_Channel_3 to U_Channel_4 In MainBoard.PcbDoc Add R31_U_Channel_5 to U_Channel_5 In MainBoard.PcbDoc Add R31_U_Channel_6 to U_Channel_6 In MainBoard.PcbDoc Add R31_U_Channel_7 to U_Channel_7 In MainBoard.PcbDoc Add R31_U_Channel_8 to U_Channel_8 In MainBoard.PcbDoc Add R31_U_Channel_8 to U_Channel_8 In MainBoard.PcbDoc Add R33_to U_pH_EZO_2 In MainBoard.PcbDoc Add R34_to U_pH_EZO_2 In MainBoard.PcbDoc				
Add R28 to U Rele In MainBoard.PcbDoc Add R29 to U Rele In MainBoard.PcbDoc Add R30 to U Rele In MainBoard.PcbDoc Add R31_U Channel 1 to U Channel 1 In MainBoard.PcbDoc Add R31_U Channel 2 to U Channel 2 In MainBoard.PcbDoc Add R31_U Channel 3 to U Channel 3 In MainBoard.PcbDoc Add R31_U Channel 4 to U Channel 4 In MainBoard.PcbDoc Add R31_U Channel 5 to U Channel 5 In MainBoard.PcbDoc Add R31_U Channel 6 to U Channel 6 In MainBoard.PcbDoc Add R31_U Channel 7 to U Channel 7 In MainBoard.PcbDoc Add R31_U Channel 8 to U Channel 8 In MainBoard.PcbDoc Add R32 to U pH EZO 2 In MainBoard.PcbDoc Add R34 to U pH EZO 2 In MainBoard.PcbDoc Add R35 to U pH EZO 2 In MainBoard.PcbDoc Add R36 to U pH EZO 2 In MainBoard.PcbDoc Add R37 to U pH EZO 2 In MainBoard.PcbDoc Add R37 to U pH EZO 2 In MainBoard.PcbDoc				
Add R29 to U_Rele In MainBoard.PcbDoc Add R30 to U_Rele In MainBoard.PcbDoc Add R31_U_Channel_1 to U_Channel_1 In MainBoard.PcbDoc Add R31_U_Channel_2 to U_Channel_2 In MainBoard.PcbDoc Add R31_U_Channel_3 to U_Channel_3 In MainBoard.PcbDoc Add R31_U_Channel_4 to U_Channel_4 In MainBoard.PcbDoc Add R31_U_Channel_5 to U_Channel_5 In MainBoard.PcbDoc Add R31_U_Channel_6 to U_Channel_6 In MainBoard.PcbDoc Add R31_U_Channel_7 to U_Channel_7 In MainBoard.PcbDoc Add R31_U_Channel_8 to U_Channel_8 In MainBoard.PcbDoc Add R32 to U_pH_EZO_2 In MainBoard.PcbDoc Add R33 to U_pH_EZO_2 In MainBoard.PcbDoc Add R35 to U_pH_EZO_2 In MainBoard.PcbDoc Add R35 to U_pH_EZO_2 In MainBoard.PcbDoc Add R35 to U_pH_EZO_2 In MainBoard.PcbDoc Add R36 to U_pH_EZO_2 In MainBoard.PcbDoc Add R37 to U_pH_EZO_2 In MainBoard.PcbDoc				
Add R30 to U_Rele In MainBoard.PcbDoc Add R31_U_Channel_1 to U_Channel_1 In MainBoard.PcbDoc Add R31_U_Channel_2 to U_Channel_2 In MainBoard.PcbDoc Add R31_U_Channel_3 to U_Channel_3 In MainBoard.PcbDoc Add R31_U_Channel_4 to U_Channel_4 In MainBoard.PcbDoc Add R31_U_Channel_5 to U_Channel_5 In MainBoard.PcbDoc Add R31_U_Channel_6 to U_Channel_6 In MainBoard.PcbDoc Add R31_U_Channel_7 to U_Channel_7 In MainBoard.PcbDoc Add R31_U_Channel_8 to U_Channel_8 In MainBoard.PcbDoc Add R32 to U_pH_EZO_2 In MainBoard.PcbDoc Add R33 to U_pH_EZO_2 In MainBoard.PcbDoc Add R35 to U_pH_EZO_2 In MainBoard.PcbDoc Add R36 to U_pH_EZO_2 In MainBoard.PcbDoc Add R36 to U_pH_EZO_2 In MainBoard.PcbDoc Add R37 to U_pH_EZO_2 In MainBoard.PcbDoc Add R38 to U_pH_EZO_2 In MainBoard.PcbDoc				
Add R31_U_Channel_1 to U_Channel_1 In MainBoard.PcbDoc Add R31_U_Channel_2 to U_Channel_2 In MainBoard.PcbDoc Add R31_U_Channel_3 to U_Channel_3 In MainBoard.PcbDoc Add R31_U_Channel_4 to U_Channel_4 In MainBoard.PcbDoc Add R31_U_Channel_5 to U_Channel_5 In MainBoard.PcbDoc Add R31_U_Channel_6 to U_Channel_6 In MainBoard.PcbDoc Add R31_U_Channel_7 to U_Channel_7 In MainBoard.PcbDoc Add R31_U_Channel_8 to U_Channel_8 In MainBoard.PcbDoc Add R32 to U_pH_EZO_2 In MainBoard.PcbDoc Add R33 to U_pH_EZO_2 In MainBoard.PcbDoc Add R35 to U_pH_EZO_2 In MainBoard.PcbDoc Add R36 to U_pH_EZO_2 In MainBoard.PcbDoc Add R37 to U_pH_EZO_2 In MainBoard.PcbDoc Add R38 to U_pH_EZO_2 In MainBoard.PcbDoc		_		
Add R31_U Channel 2 to U Channel 3 In MainBoard.PcbDoc Add R31_U Channel 3 to U Channel 3 In MainBoard.PcbDoc Add R31_U Channel 4 to U Channel 4 In MainBoard.PcbDoc Add R31_U Channel 5 to U Channel 5 In MainBoard.PcbDoc Add R31_U Channel 6 to U Channel 7 In MainBoard.PcbDoc Add R31_U Channel 7 to U Channel 7 In MainBoard.PcbDoc Add R31_U Channel 8 to U Channel 8 In MainBoard.PcbDoc Add R32 to U pH_EZO_2 In MainBoard.PcbDoc Add R33 to U pH_EZO_2 In MainBoard.PcbDoc Add R34 to U pH_EZO_2 In MainBoard.PcbDoc Add R35 to U pH_EZO_2 In MainBoard.PcbDoc Add R36 to U pH_EZO_2 In MainBoard.PcbDoc Add R37 to U pH_EZO_2 In MainBoard.PcbDoc Add R38 to U_pH_EZO_2 In MainBoard.PcbDoc				
Add R31_U_Channel_3 to U_Channel_3 In_MainBoard.PcbDoc Add R31_U_Channel_5 to U_Channel_5 In_MainBoard.PcbDoc Add R31_U_Channel_6 to U_Channel_6 In_MainBoard.PcbDoc Add R31_U_Channel_7 to U_Channel_7 In_MainBoard.PcbDoc Add R31_U_Channel_8 to U_Channel_8 In_MainBoard.PcbDoc Add R32_to U_pH_EZO_2 In_MainBoard.PcbDoc Add R33_to U_pH_EZO_2 In_MainBoard.PcbDoc Add R34_to U_pH_EZO_2 In_MainBoard.PcbDoc Add R35_to U_pH_EZO_2 In_MainBoard.PcbDoc Add R36_to U_pH_EZO_2 In_MainBoard.PcbDoc Add R37_to U_pH_EZO_2 In_MainBoard.PcbDoc Add R38_to U_pH_EZO_2 In_MainBoard.PcbDoc				
Add R31_U_Channel_4 to U_Channel_5 In MainBoard.PcbDoc Add R31_U_Channel_5 to U_Channel_5 In MainBoard.PcbDoc Add R31_U_Channel_6 to U_Channel_6 In MainBoard.PcbDoc Add R31_U_Channel_7 to U_Channel_7 In MainBoard.PcbDoc Add R31_U_Channel_8 to U_Channel_8 In MainBoard.PcbDoc Add R32 to U_pH_EZO_2 In MainBoard.PcbDoc Add R33 to U_pH_EZO_2 In MainBoard.PcbDoc Add R34 to U_pH_EZO_2 In MainBoard.PcbDoc Add R35 to U_pH_EZO_2 In MainBoard.PcbDoc Add R36 to U_pH_EZO_2 In MainBoard.PcbDoc Add R37 to U_pH_EZO_2 In MainBoard.PcbDoc Add R38 to U_pH_EZO_2 In MainBoard.PcbDoc				
Add R31_U_Channel_6 to U_Channel_7 In_MainBoard.PcbDoc Add R31_U_Channel_7 to U_Channel_7 In_MainBoard.PcbDoc Add R31_U_Channel_8 to U_Channel_8 In_MainBoard.PcbDoc Add R32 to U_pH_EZO_2 In_MainBoard.PcbDoc Add R33 to U_pH_EZO_2 In_MainBoard.PcbDoc Add R34 to U_pH_EZO_2 In_MainBoard.PcbDoc Add R35 to U_pH_EZO_2 In_MainBoard.PcbDoc Add R36 to U_pH_EZO_2 In_MainBoard.PcbDoc Add R37 to U_pH_EZO_2 In_MainBoard.PcbDoc Add R38 to U_pH_EZO_2 In_MainBoard.PcbDoc	Add		In MainBoard.PcbDoc	
Add R31_U_Channel_7 to U_Channel_7 In_MainBoard.PcbDoc Add R31_U_Channel_8 to U_Channel_8 In_MainBoard.PcbDoc Add R32 to U_pH_EZO_2 In_MainBoard.PcbDoc Add R33 to U_pH_EZO_2 In_MainBoard.PcbDoc Add R34 to U_pH_EZO_2 In_MainBoard.PcbDoc Add R35 to U_pH_EZO_2 In_MainBoard.PcbDoc Add R36 to U_pH_EZO_2 In_MainBoard.PcbDoc Add R37 to U_pH_EZO_2 In_MainBoard.PcbDoc Add R38 to U_pH_EZO_2 In_MainBoard.PcbDoc				
Add R31 U Channel 8 to U Channel 8 In MainBoard.PcbDoc Add R32 to U pH EZO 2 In MainBoard.PcbDoc Add R33 to U pH EZO 2 In MainBoard.PcbDoc Add R34 to U pH EZO 2 In MainBoard.PcbDoc Add R35 to U pH EZO 2 In MainBoard.PcbDoc Add R36 to U pH EZO 2 In MainBoard.PcbDoc Add R37 to U pH EZO 2 In MainBoard.PcbDoc Add R38 to U pH EZO 2 In MainBoard.PcbDoc Add R38 to U pH EZO 2 In MainBoard.PcbDoc				
Add R32 to U pH_EZO_2 In MainBoard.PcbDoc Add R33 to U pH_EZO_2 In MainBoard.PcbDoc Add R34 to U pH_EZO_2 In MainBoard.PcbDoc Add R35 to U pH_EZO_2 In MainBoard.PcbDoc Add R36 to U pH_EZO_2 In MainBoard.PcbDoc Add R37 to U pH_EZO_2 In MainBoard.PcbDoc Add R38 to U pH_EZO_2 In MainBoard.PcbDoc	_			
Add R33 to U pH_EZO_2 In MainBoard.PcbDoc Add R34 to U pH_EZO_2 In MainBoard.PcbDoc Add R35 to U pH_EZO_2 In MainBoard.PcbDoc Add R36 to U pH_EZO_2 In MainBoard.PcbDoc Add R37 to U pH_EZO_2 In MainBoard.PcbDoc Add R38 to U pH_EZO_2 In MainBoard.PcbDoc				
Add R34 to U_pH_EZO_2 In MainBoard.PcbDoc Add R35 to U_pH_EZO_2 In MainBoard.PcbDoc Add R36 to U_pH_EZO_2 In MainBoard.PcbDoc Add R37 to U_pH_EZO_2 In MainBoard.PcbDoc Add R38 to U_pH_EZO_2 In MainBoard.PcbDoc				
Add R35 to U pH EZO 2 In MainBoard.PcbDoc Add R36 to U pH EZO 2 In MainBoard.PcbDoc Add R37 to U pH EZO 2 In MainBoard.PcbDoc Add R38 to U pH EZO 2 In MainBoard.PcbDoc				
Add R36 to U_pH_EZO_2 In MainBoard.PcbDoc Add R37 to U_pH_EZO_2 In MainBoard.PcbDoc Add R38 to U_pH_EZO_2 In MainBoard.PcbDoc				
Add R37 to U_pH_EZO_2 In MainBoard.PcbDoc Add R38 to U_pH_EZO_2 In MainBoard.PcbDoc				
Add R38 to U_pH_EZO_2 In MainBoard.PcbDoc				
Add R39 to U_pH_EZO_2 In MainBoard.PcbDoc	Add	R38 to U_pH_EZO_2		
	Add	R39 to U_pH_EZO_2	In MainBoard.PcbDoc	

Page 7 of 8 štvrtok 3-jún-03/2021 1:54:53 PM

	Object		Change Document	Otatus
A -1-1 O -				
	mponent Class Members	Ļ		
Add	R40 to U_pH_EZO_2		MainBoard.PcbDoc	
Add	R41 to U_DO_EZO_1		MainBoard.PcbDoc	
Add	R42 to U_DO_EZO_1		MainBoard.PcbDoc	
Add	R43 to U_DO_EZO_1		MainBoard.PcbDoc	
Add	R44 to U_DO_EZO_1	In	MainBoard.PcbDoc	
Add	R45 to U_DO_EZO_1	ln	MainBoard.PcbDoc	
Add	R46 to U DO EZO 1	In	MainBoard.PcbDoc	
Add	R47 to U DO EZO 1	In	MainBoard.PcbDoc	
Add	R48 to U_DO_EZO_1		MainBoard.PcbDoc	
Add	R49 to U DO EZO 1		MainBoard.PcbDoc	
Add	R50 to U TDS EZO 1		MainBoard.PcbDoc	
Add	R51 to U_TDS_EZO_1		MainBoard.PcbDoc	
Add	R52 to U_TDS_EZO_1		MainBoard.PcbDoc	
Add	R53 to U_TDS_EZO_1		MainBoard.PcbDoc	
Add	R54 to U_TDS_EZO_1		MainBoard.PcbDoc	
Add	R55 to U_TDS_EZO_1		MainBoard.PcbDoc MainBoard.PcbDoc	
Add	R56 to U_TDS_EZO_1		MainBoard.PcbDoc	
Add	R57 to U_TDS_EZO_1		MainBoard.PcbDoc	
Add	R58 to U_TDS_EZO_1		MainBoard.PcbDoc	
Add	R60 to U_WQLT		MainBoard.PcbDoc	
Add	R61 to U_WQLT		MainBoard.PcbDoc	
Add	R62 to U_WQLT		MainBoard.PcbDoc	
Add	R63 to U_pH_EZO_1	ln	MainBoard.PcbDoc	
Add	R64 to U_pH_EZO_1	In	MainBoard.PcbDoc	
Add	R65 to U_pH_EZO_1	In	MainBoard.PcbDoc	
Add	R66 to U_pH_EZO_1	ln	MainBoard.PcbDoc	
Add	R67 to U_pH_EZO_1	In	MainBoard.PcbDoc	
Add	R68 to U_pH_EZO_1	ln	MainBoard.PcbDoc	
Add	R69 to U pH EZO 1		MainBoard.PcbDoc	
Add	R70 to U pH EZO 1		MainBoard.PcbDoc	
Add	R71 to U_pH_EZO_1		MainBoard.PcbDoc	
Add	R72 to U_Temp		MainBoard.PcbDoc	
Add	R73 to U_Temp		MainBoard.PcbDoc	
Add	RELAY_1.1 to polarita_BDD_1		MainBoard.PcbDoc	Failed to add class member : Com
Add	RELAY_1.2 to polarita_BDD_1		MainBoard.PcbDoc	Failed to add class member : Com
Add	RELAY_2.1 to polarita_BDD_2		MainBoard.PcbDoc	Failed to add class member : Com
Add	RELAY_2.2 to polarita_BDD_2		MainBoard.PcbDoc	Failed to add class member : Com
Add	Rele_1 to U_Rele		MainBoard.PcbDoc MainBoard.PcbDoc	railed to add class member . Com
Add	Rele_1 to U_Rele		MainBoard.PcbDoc	
Add	Rele_2 to U_Rele		MainBoard.PcbDoc	
Add	Rele_2 to U_Rele		MainBoard.PcbDoc	
Add	Rele_3 to U_Rele		MainBoard.PcbDoc	
Add	Rele_3 to U_Rele		MainBoard.PcbDoc	
Add	Rele_4 to U_Rele		MainBoard.PcbDoc	
Add	Rele_4 to U_Rele		MainBoard.PcbDoc	
Add	S1 to U_ESP32		MainBoard.PcbDoc	Failed to add class member : Com
Add	S2 to U_Power		MainBoard.PcbDoc	
Add	S3 to U_WQLT	In	MainBoard.PcbDoc	
Add	Sw1 to U_Input_Selection	ln	MainBoard.PcbDoc	
Add	Sw2 to U_Input_Selection	ln	MainBoard.PcbDoc	
Add	Sw3 to U_Input_Selection	ln	MainBoard.PcbDoc	
Add	Sw4 to U_Input_Selection		MainBoard.PcbDoc	
Add	T2 to U_Temp		MainBoard.PcbDoc	
Add	T3 to U_Temp		MainBoard.PcbDoc	
Add	TDS EZO1 to U TDS EZO 1		MainBoard.PcbDoc	
Add	Tp_1 to U_Power		MainBoard.PcbDoc	
Add	Tp 3V3 MCU to U Power		MainBoard.PcbDoc MainBoard.PcbDoc	
Add	Tp_3V3_Nico to 0_Power Tp_3V3_Power to U_Power		MainBoard.PcbDoc	
Add	Tp_6V to U_Power		MainBoard.PcbDoc	
Add	Tp_12V to U_Power		MainBoard.PcbDoc	
Add	USB to U_ESP32		MainBoard.PcbDoc	
Add	Xtal1 to U_ESP32	In	MainBoard.PcbDoc	

Change Document

Status

Action Object

štvrtok 3-jún-03/2021 1:54:53 PM Page 8 of 8