



9	STEPPER MOTOR BIPOLAR	STEPPER MOTOR	3
8	L298HN	STEPPER DRIVER	3
7	STRN G	350 OHM STRAIN GAUGE	3
6	USB CABLE	20' USB A TO USB C	1
5	LOAD CELL AMP	HX711 STRAIN GAUGE AMP	3
4	XGZP6847D	PNEUMATIC TRANSDUCERS	3
3	USS2-00081 NO Solenoid Valve	NO SOLINOID	3
2	E-STOP	E-STOP	- 11
1	ATmega2560-16A	ARDUINO MEGA 2560	1
NO	PT NAME	DESCRIPTION	QTY