





AUDIT REPORT FINAL V2.0 PRODUCTION PROCESS AUDIT

1/ Audit team:

Easylink Audit 030321 Report reference:

Dan Audit manager:

E-mail address: com Auditors: / Contract Auditor & SQE

04/03/2021 Report date:

Supplier no.:

2/ Audited organisation:

Organisation name: Easylink Industrial Co.,Ltd.

No. 1 Bengonghuan E. Road, Gangshan, Kaohsiung, Taiwan Address:

Other information: IATF 16949, ISO14000

3/ Audit aims:

1) Process audit on P/N 00206 M8-1.25 x 20mm Welding Screws & 2) Capability of Supplying Heat-Treated Welding Audit aims:

Screws from M6 - M10 upto 80 mm length

4/ Audit scope:

Audit date: 03/03/2021 Exclusions:

Process audited: Heading Thread Tapping

Heat Treat (out-sourced) - Chien Chung Heat Treat - No.2 Yong Lo Street, Kanshan, Kaohsiung, Taiwan

Cleaning + Rust Preventive Oil (out-sourced) - Yong Chen Industrial Co., Ltd. - No. 13 Lan 242, Chung Cheng South Road, Tainan

Number of Number of

Sorting - Easylink Plant 2.

P/N 00206 M8-1.25 x 20mm Welding Screws Product audited:

Easylink Plant 1 and Plant 2(Sorting). Heat Treat (Chien Chung) Cleaning (Yong Chen)
Topy Huang / Easylink (Production&Engineer Manager) Locations audited:

Persons audited:

Yuki Yeh / Easylink (QA Manager) Shan Lee / Easylink (Acount Manager) Chen Kuo Lee / Easylink (Sorting Manager)

Mr. Wang / Yong Chen (Owner & Operation Manager) Mr. Su / Chien Chung Heat Treat (Operation Manager)

5/ Audit report:

Summary + Specs Report constituted of:

6/ Process evaluation

5.1/ Evaluation of criteria:	Score	criteria	critical
Major non-compliance	3	0	0
Minor non-compliance	2	0	0
Compliant with opportunity for improvement	1	4	2

Minor non-compliance	2	0	0
Compliant with opportunity for improvement	1	4	2
Compliant	0	43	15
Justified exclusion	EX	3	3
	Totals	50	20

- 1. ERP + Auto-Storage System + MIS provide strong Flow Information System
- 2. Complete and Strong electronic document system + Record System
- 3. Excellent Tooling and Engineering management, Revision Control in place.
- 4. in-house 30+ optical sorting machines
- 5. Grain Flow and Thread Laps checked in first piece inspection

- 1. Data from sorting were not feedback and analyzed for improvement of processes
- 2. SQE insufficient strength and frequency of supplier management and monitoring activities
- 3. Variety of bad samples for sorting (validation of sorting capability) can be improved.
- 4. Designated process production print with detail requirements, could be designed for subcontracting (heat treat, acid pickling / rust preventive oil)

7/ Audit conclusion:

Easylink has well developed on ERP, MIS, AS/AR for advance state of art to manage documentation, engineering prints, tooling, records, data and material flow information. Process capability and process control on Welding Screws family shows excellency and competency.

PN 02026085 M8-1.25 Weld Screws has been verified in each production process and found meeting all requirements on prints and specs.

THE PROCESS IS:

EFFICACE



Number of opportunities for improvement

4