
Linear calibration: mean-response confidence band
fit: linear
95% confidence
Sensor calibration
Sensor voltage (V)
0
1
2
3
4
Raw residual (V)
0.05
0.00
−0.05
−0.10
0
10
20
30
40
50
Reference temperature (deg C)