FACTORY DAILY PRESTART

Project: SAMPLE — Fabrication shop	**Date:** 13/10/2026
Supervisor/Foreman: Supervisor Name	

Pre-Start Preparation and site inspection checklist (Y = Yes, N = No, N/A = Not applicable to works today)

Has authority been given to proceed with works?	Y	Have all power tools & leads been tagged?	Y	Are the work area and access clear, tidy & dry?	Y
Are emergency exit routes known, clear & well lit?	Y	Are the required plant, tools, and materials available?	Y	Are there adequate bins available for clean-up?	Y
Is the location of the nearest first aid kit known?	Y	Is height equipment suitable for the tasks?	N/A	Do all workers have the required PPE?	Y
Are the necessary Material Data Safety Sheets on-site and chemicals labeled & stored correctly?	Y	Are controls in place for all the hazards identified in the SWMS?	Y	Have all staff been instructed in the correct use of their PPE?	Y
Are lockout kits & danger tags available?	Y	**Pre-start preparation & site inspection is understood and signed by all persons involved below:**			

Tasks for the day:
Cut and weld frames to approved drawings.

High-risk activities:
Hot work and lifting. Inspect extraction and lifting gear.
Issues from the previous shift:
Inspect the extraction filter before welding.

Date	Full Name	Time In	Time Out	Signature
13/10/2026	Worker Name	05:00	—	

DAILY PRESTART — NOTES

SAMPLE — Fabrication shop · 13/10/2026

Session details

Project: SAMPLE — Fabrication shop
Company: Lennox Facades
Start time: 05:00
Supervisor / foreman: Supervisor Name
Focus / team: Not recorded
Record status: Completed

1. Tasks for the day

Talking points: List the tasks planned for today and any changed conditions.

Comments / discussion / agreed controls: Cut and weld frames to approved drawings.

2. High-risk activities

Talking points: Identify high-risk activities and the controls required before work starts.

Comments / discussion / agreed controls: Hot work and lifting. Inspect extraction and lifting gear.

3. Issues from previous shift

Talking points: Record outstanding issues from the previous shift and agreed follow-up.

Comments / discussion / agreed controls: Inspect the extraction filter before welding.

Follow-up actions

No actions recorded

Attendance acknowledgement

Each attendee signed on the supervisor’s device to acknowledge attendance and an opportunity to ask questions. Attendance times are entered by the supervisor; a blank time is not inferred from the signature.

DAILY PRESTART — NOTES


SAMPLE — Fabrication shop · 13/10/2026

Worker Name · Employer: Not recorded · Time in / out: 05:00 / Not recorded · Acknowledgement: Yes · Signed: 13/10/2026, 7:44:03 am AEST

Supervisor sign-off

I confirm I conducted this talk and recorded the attendance, discussion and agreed actions.

Supervisor Name · Signed: 13/10/2026, 7:44:03 am AEST



Record details

Record ID: 3b24ed3a-be6d-40fe-bbe5-d013d1abb194
Completed: 13/10/2026, 7:44:03 am AEST
Exported: 13/10/2026, 7:44:04 am AEST