





LPKF


TRAH8A11












TRAFO
ST1

ENO-ST
ST3

HF-CPU
ST4


EMUF
ST5



FRONT
ST6

MASCHINE
ST7

L P K F
HFBU8810





L P K F
HFBU8810

6.5.88

PLOCK



MIELENTZ






BEST-SEITE

ST7



ELKO-KARTE




TRAFO-KARTE


KANE881D KAVOANST



15.02.88



TRAF821L


ELK0821L
















LPKF

TRAH8J1L


CPU-PLATINE
MIELNTZ/PLOCK
UEBERARBEITET 6.88











ENDSTUFE	HFEN 6820
17.05.86 MIELLENTZ/PLOCK LEHNER/TZ	




A

5T2








ST-4






ST-5




ST-7




EM-CPU880
1 . 88

CNY742
OP181CNY742
OP182



LOETSEITE





MM-STUFENERGIE
25.3.88



LOETSEITE



2a



2a



GND




















BEST-SEITE



3.00 RS232C1
TOE-SITE




- OVERDRIVE
- OVERHEAT
- CPU-FAILURE
- CNC-FAILURE



3 PHASE AUTOMILL



7




LÖT-SEITE
HFD159B1
2.98

↑



8



R/POR

