

AMPROBE®

Data Sheet

35XP-A Digital Multimeter

A compact, full-featured digital multimeter for plant maintenance, HVAC, electrical and electronic applications.

- **■** Temperature measurement Capability to 1000 °C/1832 °F (Type K thermocouple included)
- 750 V AC/1000 V DC—highest voltage rating in this class of
- **■** Capacitance for motor run/start
- 0.1 µA resolution for flame sensor testing
- Frequency to 1 MHz
- Resistance to 40 MΩ
- Data Hold freezes display
- Magne-GripTM holster
- VolTect[™] non-contact voltage detector
- **■** Triple safety ratings



35XP-A

No hassle warranty

No waiting.

No shipping charges.

Our commitment to high-quality products and customer service is demonstrated by our industry exclusive "No Hassle" warranty. In the unlikely event that an Amprobe Test Tool requires warranty service, any of our local dealers are authorized to replace it, on the spot.

(note: \$500 MSLP limit)

















35XP-A Digital Multimeter

Data Sheet

General Specifications

3-3/4 digit liquid crystal display (LCD) with a maximum reading of 3999
Automatic, positive implied, negative polarity indication
(OL) or (-OL) is displayed
Automatic
The "# " is displayed when the battery voltage drops below the operating level
Approx. 10 minutes
2 times per second, nominal
0 °C to 50 °C at <70 % R.H.
-20 °C to 60 °C, 0 to 80 % R.H. with battery removed from meter
Stated accuracy at 23 °C ± 5 °C, <75 % relative humidity
0.1 x (specified accuracy) per °C (0 °C to 18 °C, 28 °C to 50 °C)
2000 m
Single standard 9 volt battery, NEDA 1604, JIS 006P, IEC 6F22
150 hours typical with carbon-zinc, 300 hours typical with alkaline
155 mm x 72 mm x 32 mm
Approx. 400 g including battery
One-year

Specifications

Function	Range	Accuracy	
/oltage			
DC Volts			
Ranges	400 mV, 4 V, 40 V, 400 V, 1000 V	± (0.5 % rdg + 1 dgt)	
AC Volts (45 Hz to 500 Hz)			
Ranges	400 mV (45 Hz to 100 Hz)	± (1.5 % rdg + 5 dgts)	
	4 V, 40 V, 400 V, 750 V	± (1.5 % rdg + 5 dgts)	
Resolution	100 μV		
Input Impedance	400 mV: >100 MΩ; 4 V: 10 MΩ; 40 V to 1000 V: 9.1 MΩ		
Overload Protection	1000 V DC or 750 V AC RMS		
Current			
DC Current			
Ranges	400 μA, 4000 μA, 40 mA, 400 mA	± (1.0 % rdg + 2 dgt)	
	2 A	± (2.0 % rdg + 3 dgts)	
AC Current (45 Hz to 500 Hz)			
Ranges	400 μA, 4000 μA, 40 mA, 400 mA	± (1.5 % rdg + 5 dgts)	
	2 A	± (2.5 % rdg + 5 dgts)	
Resolution	0.1 μΑ		
Input Protection	2 A/1000 V fast blow ceramic fuse 6.3 mm x 32 mm on A input		
Burden Voltage	500 mV max. (2 V max. on 4 mA, 400 mA ranges)		
Resistance	400 Ω , 4 k Ω , 40 k Ω , 400 k Ω , 4 M Ω	± (1.0 % rdg + 4 dgts)	
	40 MΩ	± (2.0 % rdg + 5 dgts)	
Resolution	100 m Ω		
Open Circuit Voltage	-0.45 V DC typical, (-1.2 V DC on 400 Ω range)		
Overload Protection	1000 V DC or 750 V AC RMS		



35XP-A Digital Multimeter

Data Sheet

Specifications, cont.

Function	Range	Accuracy	
Capacitance	4 nF, 40 nF, 400 nF, 4 μF	± (5.0 % rdg + 30 dgts	
	40 uF, 400 uF	± (5.0 % rdg + 5 dgts)	
	4 mF	± (5.0 % rdg + 15 dgts	
Resolution	1 pF		
Test Voltage	< 1 V		
Test Frequency	1.3 Hz on 4 nF to 40 μF ranges, 0.7 Hz on 4	1.3 Hz on 4 nF to 40 μF ranges, 0.7 Hz on 400 μF, 4 mF ranges	
Input Protection	2 A/1000 V fast blow ceramic fuse 6.3 mm x 32 mm on A input		
Temperature	400 °C, 1000 °C, 400 °F, 1832 °F		
	-20 °C to 10 °C	± (2.0 % rdg + 4 °C)	
	10 °C to 200 °C	± (1.0 % rdg + 3 °C)	
	200 °C to 1000 °C	-	
	-4 °F to 50 °F	± (2.0 % rdg + 8 °F)	
	50 °F to 400 °F	± (1.0 % rdg + 6 °F)	
	400 °F to 1832 °F	± (3.0 % rdg + 4 °F)	
Resolution	0.1 °C, 0.1 °F		
Overload Protection	1000 V DC or 750 V AC RMS		
	1000 V 600 V 300 V		
requency	4 k, 40 k, 400 k, 1 M	± (0.1 % rdg + 3 dgts)	
Resolution	1 Hz		
Sensitivity	10 Hz to 1 MHz: >2.5 V rms		
Minimum Pulse Width	> 25 ns		
Duty Cycle Limits	> 30 % and < 70 %		
Overload Protection	1000 V DC or 750 V AC RMS		
Continuity			
Audible Indication	Less than 25 Ω		
Response Time	100 ms		
Overload Protection	1000 VDC or 750 VAC rms		
Diode Test			
Test Current	1.2 mA (approximate)	± (1.5 % rdg + 3 dgts)	
Resolution	1 mV		
Open Circuit Voltage	3.0 DC typical		
Overload Protection	1000 V DC or 750 V AC RMS		
Non-Contact Voltage Indicator			
sense voltage 70 V to 600 V AC beepe	er chirps and big bright red LED comes on, works on	all ranges	



35XP-A Digital Multimeter

Data Sheet



Included Accessories

Pair of test leads (TL245A), K-type thermocouple (TP255A), temperature adapter (XR-TA), fuse 2 A/ 1000 V (P/N FP200), 9 V battery (installed), Magne-Grip™ Holster with magnetic hanging strap (H2-XR) and users manual.

Optional Accessories

VC30A Carrying Case DL243D Test Lead Kit

Amprobe® Test Tools

website: www.Amprobe.com email: info@amprobe.com

Everett, WA 98203 tel: 877-AMPROBE

Amprobe® Test Tools Europe

In den Engematten 14 79286 Glottertal, Germany Tel.: +49 (0) 7684 8009 - 0

©2007 Amprobe Test Tools. All rights reserved. 9/2007 2123441 D-US-N Rev C