#### LIBERTY INSURANCE CORPORATION

Liberty Mutual Insurance
\*\*\*Supplement Instructions\*\*\*

ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL BY LIBERTY MUTUAL/SAFECO INSURANCE COMPANY
Please Submit Supplement Requests at: https://supplements.libertymutual.com

\*\*\*Body Shop Instructions\*\*\*

Body Shops Can Check Claim Status, Payments, Obtain Appraisal Info & More Visit Our Claims Information Portal: https://claiminfoportal.libertymutual.com

P.O. Box 5014 Scranton, PA 18505

Claim #: Workfile ID: 049964022-0001 48645d39

## **Supplement of Record 1 with Summary**

Written By: ANTHONY DEL SESTO, 7/7/2022 10:03:33 AM

Adjuster: WAGNER, DANIELLE

Insured:

SARAH MARQUEZ

Owner Policy #:

AMC

Claim #:

049964022-0001

Type of Loss:

Collision

Date of Loss:

06/26/2022 12:00 AM

Days to Repair: 4

Point of Impact:

12 Front

Deductible:

1000.00

Owner (Insured):

SARAH MARQUEZ 1413 FREDERICK DR TALLAHASSEE, FL 32308-5142 (850) 766-8813 Cellular

(850) 766-8813 Cellular marquezsl83@gmail.com Inspection Location:

Capital City Paint & Body 2233 Capital Circle NE. Tallahassee, FL 32308

Repair Facility

(850) 421-2025 Business

Repair Facility:

2233 Capital Circle NE. Tallahassee, FL 32308 (850) 421-2025 Business

#### **VEHICLE**

2016 HOND Odyssey SE 4D VAN 6-3.5L Gasoline Sequential MPI Silver

VIN:

5FNRL5H39GB063300

Production Date:

Interior Color:

License:

01BAPV

Odometer:

55090

Exterior Color:

Silver

State:

FL

Condition:

TRANSMISSION

Automatic Transmission

POWER

Power Steering
Power Brakes
Power Windows

Power Locks
Power Mirrors

Heated Mirrors

Power Driver Seat
Power Passenger Seat **DECOR** 

Dual Mirrors Privacy Glass Air Conditioning

Intermittent Wipers

Tilt Wheel Cruise Control

Rear Defogger Keyless Entry

Alarm

Message Center

Our to a Mithead Tree

Steering Wheel Touch Controls

Rear Window Wiper Telescopic Wheel Climate Control

Dual Air Condition Backup Camera **RADIO** 

AM Radio FM Radio Stereo

Search/Seek CD Player

Auxiliary Audio Connection

Satellite Radio

SAFETY

Drivers Side Air Bag Passenger Air Bag Antl-Lock Brakes (4) 4 Wheel Disc Brakes Traction Control

,

Clear Coat Paint
OTHER

Rear Spoller

Rear Step Bumper

Hands Free Device

**SEATS** 

Cloth Seats

**Bucket Seats** 

3rd Row Seat

WHEELS

**PAINT** 

Retractable Seats

Aluminum/Alloy Wheels

Clalm #:

049964022-0001

48645d39

Workfile ID:

# **Supplement of Record 1 with Summary**

2016 HOND Odyssey SE 4D VAN 6-3.5L Gasoline Sequential MPI Silver

Console/Storage

Entertainment Center

Overhead Console CONVENIENCE

Dual Power Sliding Doors

Home Link

Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags

# Supplement of Record 1 with Summary

2016 HOND Odyssey SE 4D VAN 6-3.5L Gasoline Sequential MPI Silver

Line			Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT	BUMPE	R			4			
2				O/H front bumper				1.8	
3	** <>		Repl	Non OEM CAPA Bumper cover w/o park sensor	HO1000293PP	1	500.00	Incl.	3.0
4				Add for Clear Coat					1.2
5	**	S01	Repl	Non OEM Center grille	HO1036119	1	38.00	Incl.	
6		S01	Repl	RT Outer grille w/o fog lamps	71103TK8A50	1	21.88	Incl.	
7		S01	Repl	LT Outer grille w/o fog lamps	71108TK8A50	1	21.88	Ind.	
8	**	S01	Repl	Non OEM RT Trim molding w/o fog lamps upper	HO1047100	1	39.00	Ind.	
9	**	S01	Repl	Non OEM LT Trim molding w/o fog lamps upper	HO1046100	1	39.00	Ind.	
10	**	S01	Repl	Non OEM RT Trim molding w/o fog lamps lower	HO1047101	1	30.00	Ind.	
11	**	S01	Repl	Non OEM LT Trim molding w/o fog lamps lower	HO1046101	1	30.00	Ind.	
12		S01	Repl	Reinf beam	71130TK8A00ZZ	1	205.38	0.4	
13	e na vyna e nemenanie	S01	Repl	RT Spacer	71193TK8A50	1	17.83	0.1	·····
14	GRILLI	Ē							
15	**	S01	Repl	Non OEM CAPA Grille NOTE: TO INCLUDE BRCKETS	HO1200220C	1	143.00	0.7	
16			Repl	Sight shield	71125TK8A10	1	48.15	Ind.	
17		S01	Repl	Sight shield dip	91505TM8003	9	4.68		
18	FRONT	LAMPS	······································						
19			R&I	RT R&I headlamp assy	33100TK8A02			0.3	
20	*	S01	Rpr	LT Headlamp	33150TK8A02			1.0	
21	*	S01	Rpr	RT Headlamp-buff	33100TK8A02			1.0	
22			Repl	Aim headlamps		. 1		0.5	
23		<b>\$01</b>	R&I	LT R&I headlamp assy	33150TK8A02			0.3	
				NOTE: POLICY					
24	RADIA	TOR SU	JPPOR'	T					
25	*	S01	Rpr	Radiator support (HSS)	60400TK8A00ZZ		S	2.0	0.5
26	**	S01	Repl	Opt OEM Splash shield	HO1228142OE	1	60.00	0.3	
27	HOOD			The second second					
28	**	S01	Repi	Non OEM CAPA Hood (ALU)	HO1230174PP	1	800.00	1.4	2.6
29		S01		Overlap Major Non-Adj. Panel					-0.2
30		S01		Add for Clear Coat					0.
31		S01		Add for Underside(Complete)					1.3
32		S01	Repl	RT Hinge	60120TK8A10ZZ	1	50.35	0.3	0.3
33		S01		Add for Clear Coat					0.
34		S01	Repl	LT Hinge	60170TK8A10ZZ	1	50.35	0.3	0.
35		S01		Add for Clear Coat					0.

Claim #: Workfile ID:

#: 049964022-0001

48645d39

# **Supplement of Record 1 with Summary**

					SUBTOTALS		2,108.00	20.0	11.9
55	#	S01	Rpr	Frame Pull				2.0 F	
54	#	S01	Rpr	Set-Up and Measure - Rack				2.0	
53	#	S01	Rpr	Color Tint				0.5	
52	#		Repl	Cover Car		1	5.00	0.3	
51	#		Subl	Hazardous waste removal		1	3.50		
50	MISCELL	ANEO	US OF	PERATIONS					
49	*	S01	Rpr	Post-repair scan			m	<u>1.0</u> M	
48	*	S01	Rpr	Pre-repair scan			m	<u>1.0</u> M	
47	VEHICLE	DIAG	NOST	ics					
46		S01	R&I	LT Rocker molding gray texture	71850TK8A20ZA			0.5	
45		S01	R&I	RT Rocker molding gray texture	71800TK8A20ZA			0.5	
44	PILLARS,	ROC	KER &	FLOOR					
43			R&I	LT Washer nozzle	76810TK8A21			Ind.	
42			R&I	RT Washer nozzle	76810TK8A21			Ind.	
41	WINDSH	IELD							
40	#	S01	Rpr	RE-ALIGN FOR GAPS	in angle of the control of the contr			1.0	
39		S01	R&I	Mud guard front & rear set	08P00TK8100B			0.8	
38		S01	Blnd	LT Fender (ALU)	60260TK8A80ZZ				1.1
37		S01	Blnd	RT Fender (ALU)	60210TK8A80ZZ				1.1

#### **ESTIMATE TOTALS**

Category		Basis		Rate	Cost \$
Parts					2,108.00
Body Labor		16.0 hrs	@	\$ 47.00 /hr	752.00
Paint Labor		11.9 hrs	@	\$ 47.00 /hr	559.30
Mechanical Labor		2.0 hrs	@	\$ 77.00 /hr	154.00
Frame Labor		2.0 hrs	@	\$ 49.00 /hr	98.00
Paint Supplies		11.9 hrs	<b>@</b>	\$ 27.00 /hr	321.30
Subtotal					3,992.60
Sales Tax	Tler 1	\$ 3,992.60	<b>@</b>	7.5000 %	299.45
Total Cost of Repairs					4,292.05
Deductible					1,000.00
Total Adjustments					1,000.00
Net Cost of Repairs					3,292.05

Workfile ID:

049964022-0001 48645d39

# **Supplement of Record 1 with Summary**

2016 HOND Odyssey SE 4D VAN 6-3.5L Gasoline Sequential MPI Silver

#### **SUPPLEMENT SUMMARY**

Line			Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Chane						<b>36</b> (1)	The second section of		
8	, , , , , , , , , , , , , , , , , , , ,		Repl	Sight shield dip	91505TM8003	2	-1.04		
17		S01	Repl	Sight shield dip	91505TM8003	9	4.68		
11	*		Rpr	RT Headlamp-buff	33100TK8A02			<u>-0.5</u>	
21	*	S01	Rpr	RT Headlamp-buff	33100TK8A02			1.0	
19			R&I	RT Washer nozzle	76810TK8A21			-0.2	
42		S01	R&I	RT Washer nozzle	76810TK8A21			Incl.	
20			R&I	LT Washer nozzle	76810TK8A21			-0.2	
43		S01	R&I	LT Washer nozzle	76810TK8A21			Ind.	
22	*		Rpr	Pre-repair scan			m	<u>-0.5</u>	
48	*	S01	Rpr	Pre-repair scan			m	<u>1.0</u> M	
23	*		Rpr	Post-repair scan			m	<u>-0.5</u>	
49	*	S01	Rpr	Post-repair scan			m	<u>1.0</u> M	
<b>Dariet</b>	i sulfi								
13	HOOD								
14	*		Rpr	Hood (ALU)	60100TK8A80ZZ			<u>-6.0</u>	-2.6
15				Overlap Major Non-Adj. Panel					0.2
16				Add for Clear Coat					-0.5
17	#	EDERTON: ENA	Refn	Partial Refinish Adjustment		****			0.6
AULE								14.	
5	**	S01	Repl	Non OEM Center grille	HO1036119	1	38.00	Incl.	
6		S01	Repl	RT Outer grille w/o fog lamps	71103TK8A50	1	21.88	Ind.	
7		S01	Repl	LT Outer grille w/o fog lamps	71108TK8A50	1	21.88	Incl.	
8	**	S01	Repl	Non OEM RT Trim molding w/o fog lamps upper	HO1047100	1	39.00	Ind.	
9	**	S01	Repl	Non OEM LT Trim molding w/o fog lamps upper	HO1046100	1	39.00	Ind.	
10	**	S01	Repl	Non OEM RT Trim molding w/o fog lamps lower	HO1047101	1	30.00	Ind.	
11	**	S01	Repl	Non OEM LT Trim molding w/o fog lamps lower	HO1046101	1	30.00	Ind.	
12		S01	Repl	Reinf beam	71130TK8A00ZZ	1	205.38	0.4	
13			Repl	RT Spacer	71193TK8A50	1	17.83	0.1	
20	*	S01	Rpr	LT Headlamp	33150TK8A02			1.0	
23		S01	R&I	LT R&I headlamp assy	33150TK8A02			0.3	
				NOTE: POLICY					
24	RADIA	TOR SU	JPPOR						
25	*	S01	Rpr	Radiator support (HSS)	60400TK8A00ZZ		s	<u>2.0</u>	0.5
26	**	S01	Repl	Opt OEM Splash shield	HO1228142OE	1	60.00	0.3	Mr. 11 y 14, 1
27	HOOD			The state of the s					
28	**	S01	Repl	Non OEM CAPA Hood (ALU)	HO1230174PP	1	800.00	1.4	2.6

Workfile ID:

049964022-0001 48645d39

# **Supplement of Record 1 with Summary**

2016 H	OND Odysse	y SE 4	id van	6-3.5L Gasoline Sequential MPI Silver					
29		S01		Overlap Major Non-Adj. Panel					-0.2
30		S01		Add for Clear Coat					0.5
31		S01		Add for Underside(Complete)					1.3
32		S01	Repl	RT Hinge	60120TK8A10ZZ	1	50.35	0.3	0.3
33		S01		Add for Clear Coat					0.1
34		S01	Repl	LT Hinge	60170TK8A10ZZ	1	50.35	0.3	0.3
. 35		S01		Add for Clear Coat					0.1
36	FENDER								
37		S01	Blnd	RT Fender (ALU)	60210TK8A80ZZ				1.1
38		S01	Blnd	LT Fender (ALU)	60260TK8A80ZZ				1.1
39		S01	R&I	Mud guard front & rear set	08P00TK8100B			0.8	
40	#	501	Rpr	RE-ALIGN FOR GAPS				1.0	
44	PILLARS	, ROC	KER &	FLOOR					
45		S01	R&I	RT Rocker molding gray texture	71800TK8A20ZA			0.5	
46		S01	R&I	LT Rocker molding gray texture	71850TK8A20ZA			0.5	
53	#	S01	Rpr	Color Tint				0.5	
54	#	S01	Rpr	Set-Up and Measure - Rack				2.0	
55	#	S01	Rpr	Frame Pull				2.0 F	
					SUBTOTALS		1,407.31	8.5	5.4

### **RATE CHANGES**

Sales Tax		\$ 1722.19	1.5000 %	(	6.0000 %	to	7.5000 %) =	25.83
County Tax	T1	\$ 1722.19	-1.5000 %	(	1.5000 %	to	0.0000 %) =	-25.83

## **TOTALS SUMMARY**

Category		Basis		Rate	Cost \$
Parts					1,407.31
Body Labor		4.5 hrs	<b>@</b>	\$ 47.00 /hr	211.50
Paint Labor		5.4 hrs	<b>@</b>	\$ 47.00 /hr	253.80
Mechanical Labor		2.0 hrs	@	\$ 77.00 /hr	154.00
Frame Labor		2.0 hrs	<b>@</b>	\$ 49.00 /hr	98.00
Paint Supplies		5.4 hrs	@	\$ 27.00 /hr	145.80
Subtotal					2,270.41
Sales Tax	Tler 1	\$ 2,270.41	<b>@</b>	7.5000 %	170.28
Additional Supplement Taxes					0.01
Total Supplement Amount					2,440.70
NET COST OF SUPPLEMENT					2,440.70

Clalm #:

Workfile ID:

049964022-0001

48645d39

### **Supplement of Record 1 with Summary**

2016 HOND Odyssey SE 4D VAN 6-3.5L Gasoline Sequential MPI Silver

### **CUMULATIVE EFFECTS OF SUPPLEMENT(S)**

Estimate

1,851.35

MARCUS BARR

Supplement S01

2,440.70

ANTHONY DEL

SESTO

Workfile Total:

\$ 4,292.05

TOTAL ADJUSTMENTS:

\$ 1,000.00

**NET COST OF REPAIRS:** 

\$ 3,292.05

- THIS IS NOT AN AUTHORIZATION TO REPAIR. ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL BY LIBERTY MUTUAL/SAFECO INSURANCE COMPANY.
- Please present this Appraisal to the repair facility before repairs begin.
- In the event of a supplement, please submit to https://supplements.libertymutual.com.
- Once the supplement has been reviewed a member of our appraisal team will contact you within 2-3 business days to discuss supplement details.
- To expedite the supplement process a vehicle must be in the shop for repairs with Initial teardown completed based on this appraisal.

Appraisal Written by: Anthony Del Sesto 317-805-2505

Appraiser Licensing Information:

NPN: 8275097

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AUTOMOBILE PARTS NOT MADE BY THE ORIGINAL MANUFACTURER. PARTS USED IN THE REPAIR OF YOUR VEHICLE BY OTHER THAN THE ORIGINAL MANUFACTURER ARE REQUIRED TO BE AT LEAST EQUAL IN LIKE, KIND AND QUALITY IN TERMS OF FIT, QUALITY AND PERFORMANCE TO THE ORIGINAL MANUFACTURER PARTS THEY ARE REPLACING.

Workfile ID:

049964022-0001

48645d39

### Supplement of Record 1 with Summary

2016 HOND Odyssey SE 4D VAN 6-3.5L Gasoline Sequential MPI Silver

ANY PERSON WHO KNOWINGLY AND WITH INTENT TO INJURE, DEFRAUD, OR DECEIVE ANY INSURER FILES A STATEMENT OF CLAIM OR AN APPLICATION CONTAINING ANY FALSE, INCOMPLETE, OR MISLEADING INFORMATION IS GUILTY OF A FELONY OF THE THIRD DEGREE(FLORIDA STATUTES TITLE XLVI, CHAPTER 817.234). FAILURE TO USE THE INSURANCE PROCEEDS IN ACCORDANCE WITH THE SECURITY AGREEMENT, IF ANY, COULD BE A VIOLATION OF S. 812.014, FLORIDA STATUTES. IF YOU HAVE ANY QUESTIONS, CONTACT YOUR LENDING INSTITUTION. IF A CHARGE FOR SHOP SUPPLIES OR HAZARDOUS OR OTHER WASTE REMOVAL IS INCLUDED ON THIS ESTIMATE, PLEASE NOTE THE FOLLOWING: "THIS CHARGE REPRESENTS COSTS AND PROFITS TO THE MOTOR VEHICLE REPAIR FACILITY FOR MISCELLANEOUS SHOP SUPPLIES OR WASTE DISPOSAL." IF A CHARGE FOR NEW TIRES OR A NEW OR REMANUFACTURED LEAD-ACID BATTERY IS INCLUDED ON THIS ESTIMATE, PLEASE NOTE THE FOLLOWING: A \$1.00 FEE FOR EACH NEW MOTOR VEHICLE TIRE SOLD AT RETAIL IS IMPOSED ON ANY PERSON ENGAGING IN THE BUSINESS OF MAKING RETAIL SALES OF NEW MOTOR VEHICLE TIRES WITHIN THE STATE OF FLORIDA. FLORIDA STATUTES TITLE XXIX CHAPTER 403.718. A \$1.50 FEE FOR EACH NEW OR REMANUFACTURED LEAD-ACID BATTERY SOLD AT RETAIL IS IMPOSED ON ANY PERSON ENGAGING IN THE BUSINESS OF MAKING RETAIL SALES OF NEW OR REMANUFACTURED LEAD-ACID BATTERIES WITHIN THE STATE OF FLORIDA. FLORIDA STATUTES TITLE XXIX 403.7185.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. THE AFTERMARKET CRASH PARTS USED IN THE PREPARATION OF THIS ESTIMATE ARE WARRANTED BY THE MANUFACTURER OR DISTRIBUTOR OF SUCH PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

049964022-0001

48645d39

Workfile ID:

### Supplement of Record 1 with Summary

2016 HOND Odyssey SE 4D VAN 6-3.5L Gasoline Sequential MPI Silver

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all Items are derived from the Guide ARG4429, CCC Data Date 07/01/2022, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2022 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

#### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

#### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

#### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Workfile ID:

049964022-0001

48645d39

#### Supplement of Record 1 with Summary

2016 HOND Odyssey SE 4D VAN 6-3.5L Gasoline Sequential MPI Silver

# THIS IS NOT AN AUTHORIZATION TO REPAIR. ALL SUPPLEMENTS REQUIRE PRIOR **APPROVAL**

Please present this Appraisal to the repair facility before repairs begin.

We reserve the right to inspect any additional damage.

- \*\* For supplement requests, please follow the instructions below:
- \*\*\*\* If the ORIGINAL APPRAISAL was completed by a LIBERTY MUTUAL/SAFECO STAFF APPRAISER or an INDEPENDENT APPRAISER, please contact the appraiser directly; their email address and phone number can be located in the header of the appraisal or in the "APPRAISER INFORMATION" section at the top of the appraisal. \*\*\*\* Instructions if the ORIGINAL APPRAISAL was completed by a LIBERTY

**MUTUAL/SAFECO GUARANTEED REPAIR NETWORK SHOP\*\*\*\*\*\***:

\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\* SHOPS USING CCC ESTIMATING SOFTWARE

\*\*\*\*\*\*\*

- --- PREFERRED METHOD --- Your facility can pull down the original estimate and add your supplement request using THE WORKFILE VIA ESTIMATE SHARE (AWE WORKFILE RETRIEVAL - instructions are listed below) If you are unable to complete these steps, the workfile can also be sent to you.
- --- NON- PREFERRED METHOD --- Call the Liberty Mutual/Safeco Supplement Hotline at 855-837-1529 OR Email LIBERTYSUPP@CCCIS.COM with your shop name, a contact number. Note that you are a CCC One shop requesting a Liberty Mutual open shop supplement assignment. Please use the following subject line on your request "NEW CCC SUPPLEMENT FILE REQUEST FOR (INSERT CLAIM NUMBER)". After contacting CCC, they will send the original work file to your CCC One estimating system. Open and complete your supplement, LOCK it & upload with the attached photos and documentation.... The supplement has to be LOCKED to transfer through CCC to Liberty Mutual/Safeco. However, you can email as noted above.
- \*\*\*\*\* FOR NON-CCC SHOPS OR IF YOUR SUPPLEMENT IS ALREADY COMPLETED IN CCC\*\*\* Email your written supplement PDF, photos and supporting documents to LIBERTYSUPP@CCCIS.COM for processing. Please use the subject line "NEW SUPPLEMENT REQUEST FOR NON CCC SHOP (INSERT CLAIM NUMBER)". To avoid a service delay, please include your shop name, and contact name and phone number. NOTE: You will not be able to merge or upload a supplement that was written prior to completing the download.

\*

\*\*\*\*\*\*

If you have RENTAL COVERAGE or are entitled to a Rental due to this loss, Rental will be allowed for the reasonable period necessary to repair your vehicle, subject to any

Claim #: Workfile ID: 049964022-0001

48645d39

#### **Supplement of Record 1 with Summary**

2016 HOND Odyssey SE 4D VAN 6-3.5L Gasoline Sequential MPI Silver

applicable policy provisions, laws or regulations.

If a rental vehicle has not been pre-authorized or you have any questions regarding your rental coverage or eligibility, please contact your adjuster prior to securing a rental vehicle.

\*\*\*\*\*

Liberty Mutual/Safeco offers body shops fast and convenient service online through our Claim Information Portal. You can check claim status, obtain payment details, view liability status, and much more.

Visit CLAIMINFOPORTAL.LIBERTYMUTUAL.COM to register and login.

Customers and body shops may also contact a claims representative at the phone numbers below:

Liberty Mutual Insurance 1-800-225-2467

Safeco Insurance 1-800-332-3226

\*

\*\*\*\*\*\*\*

THE INSURER GUARANTEES THAT IT WILL REPLACE ANY PART IDENTIFIED IN THIS ESTIMATE WHICH IS NOT A NEW ORIGINAL EQUIPMENT MANUFACTURER PART, INCLUDING RECYCLED PARTS MANUFACTURED BY THE ORIGINAL EQUIPMENT MANUFACTURER OR NEW PARTS NOT MANUFACTURED BY THE ORIGINAL EQUIPMENT MANUFACTURER, IF A DEFECT IS DISCOVERED.

THIS GUARANTEE WILL BE IN EFFECT FOR AS LONG AS YOU OWN THE VEHICLE DESCRIBED IN THIS ESTIMATE, BUT IT IS NOT TRANSFERABLE TO ANY OTHER PARTY AT ANY TIME. THIS GUARANTEE COVERS THE COST OF THE PART, LABOR TO INSTALL, AND PAINT AND MATERIALS, IF REQUIRED, AS WELL AS THE COST OF RENTAL OF A TEMPORARY REPLACEMENT VEHICLE DURING THE REPAIRS. THIS GUARANTEE DOES NOT COVER CONSEQUENTIAL DAMAGES.

IF A DEFECT IS DISCOVERED IN ANY RECYCLED PARTS MANUFACTURED BY THE ORIGINAL EQUIPMENT MANUFACTURER OR NEW PARTS NOT MANUFACTURED BY THE ORIGINAL EQUIPMENT MANUFACTURER THAT ARE USED IN REPAIR OF YOUR VEHICLE, CONTACT YOUR ADJUSTER OR AGENT IMMEDIATELY, AND WE WILL REPLACE THE PART WITH A NEW ORIGINAL EQUIPMENT MANUFACTURER PART.

\*

\*\*\*\*\*\*

AWE WORKFILE RETREVAL INSTRUCTIONS: In your CCC ONE Estimating, please select ACTION: IMPORT WORKFILE COPY, DOWNLOAD COPY OF WORKFILE FROM

049964022-0001

48645d39

Workfile ID:

## **Supplement of Record 1 with Summary**

2016 HOND Odyssey SE 4D VAN 6-3.5L Gasoline Sequential MPI Silver

CCC <Click NEXT>. Then select the INSURANCE COMPANY listed in the appraisal (LM option), enter the CLAIM NUMBER and WORKFILE ID <Click NEXT>. This will push the assignment to your CCC ONE inbox. Open and complete your supplement, LOCK it & upload with the attached photos and documentation...

\*

\*\*\*\*\*

049964022-0001

48645d39

# Workfile ID:

# **Supplement of Record 1 with Summary**

2016 HOND Odyssey SE 4D VAN 6-3.5L Gasoline Sequential MPI Silver

### **ALTERNATE PARTS SUPPLIERS**

Line	Supplier	Description	Price
3	KEYSTONE-JACKSONVILLE, FL	#HO1000293PP	\$ 500.00
	4101 Bulls Bay Highway	Non OEM CAPA Bumper cover w/o park sensor	
	JACKSONVILLE FL 32219	Quote: 1330637230	
	(904) 354-2400	Expires: 08/14/22	
5	KEYSTONE-JACKSONVILLE, FL	#HO1036119	\$ 38.00
	4101 Bulls Bay Highway	Non OEM Center grille	
	JACKSONVILLE FL 32219	Quote: 1334984788	
	(904) 354-2400	Expires: 08/20/22	
8	KEYSTONE-JACKSONVILLE, FL	#HO1047100	\$ 39.00
	4101 Bulls Bay Highway	Non OEM RT Trim molding w/o fog lamps upper	
	JACKSONVILLE FL 32219	Quote: 1334984788	
	(904) 354-2400	Expires: 08/20/22	
9	KEYSTONE-JACKSONVILLE, FL	#HO1046100	\$ 39.00
	4101 Bulls Bay Highway	Non OEM LT Trim molding w/o fog lamps upper	
,	JACKSONVILLE FL 32219	Quote: 1334984788	
	(904) 354-2400	Expires: 08/20/22	
10	KEYSTONE-JACKSONVILLE, FL	#HO1047101	\$ 30.00
	4101 Bulls Bay Highway	Non OEM RT Trim molding w/o fog lamps lower	
	JACKSONVILLE FL 32219	Quote: 1334984788	
	(904) 354-2400	Expires: 08/20/22	
11	KEYSTONE-JACKSONVILLE, FL	#HO1046101	\$ 30.00
	4101 Bulls Bay Highway	Non OEM LT Trim molding w/o fog lamps lower	
	JACKSONVILLE FL 32219	Quote: 1334984788	
	(904) 354-2400	Expires: 08/20/22	
15	KEYSTONE-JACKSONVILLE, FL	#HO1200220C	\$ 143.00
	4101 Bulls Bay Highway	Non OEM CAPA Grille	
	JACKSONVILLE FL 32219	Quote: 1330637230	
	(904) 354-2400	Expires: 08/14/22	
26	KEYSTONE-JACKSONVILLE, FL	#HO1228142OE	\$ 60.00
	4101 Bulls Bay Highway	Opt OEM Splash shield	
	JACKSONVILLE FL 32219	Quote: 1334984788	
	(904) 354-2400	Expires: 08/20/22	
28	KEYSTONE-JACKSONVILLE, FL	#HO1230174PP	\$ 800.00
	4101 Bulls Bay Highway	Non OEM CAPA Hood (ALU)	
	JACKSONVILLE FL 32219	Quote: 1334984788	

Clalm #:

049964022-0001 48645d39

Workfile ID:

# Supplement of Record 1 with Summary

2016 HOND Odyssey SE 4D VAN 6-3.5L Gasoline Sequential MPI Silver

(904) 354-2400

Expires: 08/20/22