






NOTES:

- 1 - DRAWING ACCORDING TO ISO STANDARDS, SEE TSS 002513.
- 2 - DIMENSIONS AND SPECIFICATIONS SIGNED WITH ▼▽⊕, SEE TSS 002470.
- 3 - REQUIREMENTS ABOUT HAZARDOUS SUBSTANCES ACCORDING TO TSS 02420.⊕
- 4 - HFC MANDATORY REQUIREMENTS ACCORDING TO TSS 002369.▼
- 5 - MANGANIC PHOSPHATIZING ACCORDING TO DIN 50942.
COATING THICKNESS = 0,0005mm & 0,0015mm.
- 6 - ROUGHNESS AND DIMENSIONS BEFORE SURFACE TREATMENT (PHOSPHATE).
- 7 - MEASUREMENT PROCEDURE OF CRITICAL DIMENSIONS: TSS 002601.
- 8 - ASSEMBLY REQUIREMENTS ACCORDING TO TSS 002596.
- 9 - IDENTIFICATION IN THIS AREA (MARK OR BLIND HOLE).
- 10 - LASER ENGRAVING AREA.

28,0	2,90
24,0	2,35
"A"	"M"

[illegible]