

Relatorio Tecnico SGMed Inspector

Escopo: 21JN101A

Resumo Executivo

Mudancas encontradas: 24 | Eventos avaliados: 989

O Que Mudou

Parametro	Esquerda	Direita	Categoria	Severidade
Date / time	08/04/26 06:38:30	09/04/26 07:37:40	operational	medium
Hi limit	414.66	501.84	metrological	high
Lo limit	81.01	107.75	metrological	high
Standard dens override	858	854.2	metrological	high
Flow rate 1	90.01	119.72	metrological	critical
Flow rate 2	107.62	142.68	metrological	critical
Flow rate 3	126.92	170.22	metrological	critical
Flow rate 4	154.89	206.99	metrological	critical
Flow rate 5	186.43	252.2	metrological	critical
Flow rate 6	226.28	294.66	metrological	critical
Flow rate 7	271.72	326.34	metrological	critical
Flow rate 8	316.71	392.83	metrological	critical
Flow rate 9	376.96	456.22	metrological	critical
MF/error 1	1.00221	1.00175	metrological	critical
MF/error 2	1.00205	1.00183	metrological	critical
MF/error 3	1.00207	1.00162	metrological	critical
MF/error 4	1.00196	1.00146	metrological	critical
MF/error 5	1.00177	1.00114	metrological	critical
MF/error 6	1.00169	1.00109	metrological	critical
MF/error 7	1.00137	1.00097	metrological	critical

Cromatografia / GC

Componentes com mudança: nenhum componente com mudança

Componentes lidos no arquivo carregado: nenhum componente lido

Perfil esperado: Metano, Etano, Propano, Hexano+, Nitrogênio, CO2

Componentes esperados ainda ausentes: Metano, Etano, Propano, Hexano+, Nitrogênio, CO2

Leitura dos Eventos

Run 2 Flow rate alarm from Normal to Low Low [80] (486x) - Run 2

Run 2 Flow rate alarm from Low Low to Normal [80] (460x) - Run 2

User administrator (Web: 10.0.1.50) has logged in (14x) - Sem run específico

User administrator (Web: 10.0.1.50) has been automatically logged off (12x) - Sem run específico

'Print snapshot report' executed by administrator (2000) (3x) - Sem run específico

Run 2 Flow rate alarm from Normal to Low Low [80] (435x) - Repeticao em janela curta no run 2

Run 2 Flow rate alarm from Low Low to Normal [80] (410x) - Repeticao em janela curta no run 2

User administrator (Web: 10.0.1.50) has logged in (8x) - Repeticao em janela curta

User administrator (Web: 10.0.1.50) has been automatically logged off (8x) - Repeticao em janela curta

Parameter Product 1 standard density override was changed from 854.4 to 858 by CommDrivers (10000) (1x) - Repeticao em janela curta