Εργαστήριο Μικροϋπολογιστών 7^η Άσκηση

Ομάδα: Δ12 Βακαλόπουλος Θεόδωρος, ΑΜ: 03114013 Μαυρομμάτης Ιάσων, ΑΜ: 03114771 Νικητοπούλου Δήμητρα, ΑΜ: 03114954

Άσκηση 1

Ο κώδικας της άσκησης φαίνεται παρακάτω:

```
.include "m16def.inc"
.def reg = r18
.def flag = r21
.def temp = r17
.org 0x00
rimp main
.org 0x10
rjmp ISR_TIMER1_OVF
.DSEG
_tmp_:.byte 2
.CSEG
main:
  ldi reg, low(RAMEND)
  out SPL, reg
  ldi reg, high(RAMEND)
  out SPH, reg
  ser reg
  out DDRA, reg
                            //PortA as output
  clr reg
  out DDRB, reg
                            //PortB as input
  ldi r24 ,(1 << PC7) | (1 << PC6) | (1 << PC5) | (1 << PC4)
  out DDRC,r24
  ldi r24,0xfc;111111100, PD7-2 output
  out DDRD, r24
  ldi r26,low(_tmp_) ;r26-r27 -> X
  ldi r27,high(_tmp_)
  clr reg
  st X+,reg
  st X,reg
  sei
initialize:
  rcall lcd_init
```

```
read_sensors:
  in reg,PINB
  cpi reg,0x00
                 ;reading sensors
  breq read_sensors
  ldi reg, (1<<TOIE1)
  out TIMSK, reg
                       ;timer1
  ldi reg, (1<<CS12)|(0<<CS11)|(1<<CS10)
  out TCCR1B, reg
       ldi reg, 0x67 ;Initialise start point of timer1 at 67(hex)
  out TCNT1H, reg ;so as to cause an interrupt after 5s
  ldi reg, 0x69
  out TCNT1L, reg
  ldi r24, 0x0E ;show cursor
       rcall lcd_command
read shift:
  clr flag
             ;0,1,2->wrong combination,3->right
  clr temp
               ;indicates number of keys pressed
  ldi r24, 10 ;Initialise for 0.01s delay
  rcall scan_keypad_rising_edge
  rcall keypad_to_ascii
  cpi r24,0x00
  breq read_shift
       push r24
  rcall lcd_data
       pop r24
  inc temp
  cpi r24,'4'
  brne read1st
  inc flag
read1st:
  ldi r24, 10 ;Initialise for 0.01s delay
  rcall scan_keypad_rising_edge
  rcall keypad_to_ascii
  cpi r24,0x00
  breq read1st
       push r24
  rcall lcd_data
  pop r24
       inc temp
  cpi r24,'1'
  brne read2nd
       inc flag
read2nd:
  ldi r24, 10 ;Initialise registers for 0.01s delay
  rcall scan_keypad_rising_edge
  rcall keypad_to_ascii
```

```
cpi r24,0x00
   breq read2nd
        push r24
   rcall lcd_data
        ldi r24, 0x0C
       reall led command
   pop r24
        inc temp
  cpi r24,'2'
   brne wrong
  inc flag
  cpi flag,0x03
   brne wrong
right:
        ldi r25, HIGH(500)
  ldi r24, LOW(500) ;Initialise registers for 0.5s delay
   rcall wait_msec ;Wait for the last digit to show
        reall led_init
  rcall ALARM_O
  ldi r24,'F'
  rcall lcd_data
  ldi r24,'F'
  reall led data
  ldi r25, HIGH(3000)
  ldi r24, LOW(3000) ;Initialise registers for 3s delay
  rcall wait_msec
loop_forever:
       rjmp loop_forever
wrong:
        ldi r25, HIGH(500)
  ldi r24, LOW(500); Initialise registers for 0.5s delay
   rcall wait_msec ;Wait for the last digit to show
   reall led_init
        rcall ALARM_O
  ldi r24,'N'
  rcall lcd_data
                 ;on-off Leds forever
again:
   ser reg
   out PORTA,reg
  ldi r25, HIGH(400)
  ldi r24, LOW(400) ;Initialise registers for 0.4s delay
   rcall wait_msec
  ldi r25, HIGH(100) ;Initialise registers for 0.1s delay
  ldi r24, LOW(100)
  clr reg
   out PORTA,reg
   rcall wait_msec
```

```
ISR_TIMER1_OVF:
  cpi flag,0x03
  breq leave
  cpi temp,0x03
  breq leave
       rcall lcd_init
  rcall ALARM_O
  ldi r24,'N'
  rcall lcd_data
on_off:
  ser reg
  out PORTA,reg
  ldi r25, HIGH(400)
  ldi r24, LOW(400); Initialise registers for 0.4s delay
  rcall wait msec
  ldi r25, HIGH(100) ;Initialise registers for 0.1s delay
  ldi r24, LOW(100)
  clr reg
  out PORTA,reg
  rcall wait_msec
  jmp on_off
leave:
  ret
ALARM_O:
  ldi r24,'A'
  reall led data
  ldi r24,'L'
  rcall lcd_data
  ldi r24,'A'
  rcall lcd_data
  ldi r24,'R'
  rcall lcd_data
  ldi r24,'M'
  rcall lcd_data
  ldi r24,''
  rcall lcd_data
  ldi r24,'O'
  rcall lcd_data
  ret
wait_msec:
   push r24
   push r25
   ldi r24, low(998)
  ldi r25, high(998)
   rcall wait_usec
   pop r25
```

```
pop r24
   sbiw r24, 1
   brne wait_msec
wait usec:
   sbiw r24,1
  nop
   nop
  nop
  nop
   brne wait_usec
  ret
write_2_nibbles:
  push r24
  in r25,PIND
  andi r25,0x0f
  andi r24,0xf0
  add r24, r25
  out PORTD, r24
  sbi PORTD, PD3
  cbi PORTD, PD3
  pop r24
  swap r24
  andi r24,0xf0
  add r24, r25
  out PORTD ,r24
  sbi PORTD, PD3
  cbi PORTD, PD3
  ret
lcd_data:
  sbi PORTD, PD2
  rcall write_2_nibbles
  ldi r24,43
  ldi r25,0
  rcall wait_usec
  ret
lcd_command:
  cbi PORTD, PD2
  rcall write_2_nibbles
  ldi r24,39
  ldi r25,0
  rcall wait_usec
  ret
lcd_init:
  ldi r24,40
  ldi r25,0
```

```
rcall wait_msec
  ldi r24,0x30
  out PORTD ,r24
  sbi PORTD, PD3
  cbi PORTD, PD3
  ldi r24,39
  ldi r25,0
  rcall wait_usec
  ldi r24,0x30
  out PORTD, r24
  sbi PORTD, PD3
  cbi PORTD, PD3
  ldi r24 ,39
  ldi r25,0
  rcall wait_usec
  ldi r24,0x20
  out PORTD, r24
  sbi PORTD, PD3
  cbi PORTD, PD3
  ldi r24,39
  ldi r25,0
  rcall wait_usec
  ldi r24,0x28
  rcall lcd_command
  ldi r24 ,0x0c
  rcall lcd_command
  ldi r24 ,0x01
  rcall lcd_command
  ldi r24 ,low(1530)
  ldi r25 ,high(1530)
  rcall wait_usec
  ldi r24,0x06
  reall led command
  ret
scan_row:
  ldi r25,0x08
  back:
  lsl r25
  dec r24
  brne back
  out PORTC, r25
  nop
  nop
  in r24, PINC
  andi r24, 0x0f
  ret
scan_keypad:
  ldi r24,0x01
```

```
rcall scan_row
   swap r24
   mov r27,r24
   ldi r24,0x02
   rcall scan_row
   add r27,r24
   ldi r24,0x03
   rcall scan_row
   swap r24
   mov r26,r24
   ldi r24,0x04
   rcall scan_row
   add r26,r24
   movw r24,r26
   ret
scan_keypad_rising_edge:
   mov r22, r24
   rcall scan_keypad
   push r24
   push r25
   mov r24, r22
   clr r25
   rcall wait_msec
   rcall scan_keypad
   pop r23
   pop r22
   and r24,r22
   and r25,r23
   ldi r26,low(_tmp_) ;r26-r27 -> X
   ldi r27,high(_tmp_)
  ld r23,X+
  ld r22,X
   st X,r24
   st -X,r25
   com r23
   com r22
   and r24,r22
   and r25,r23
   ret
keypad_to_ascii:
  movw r26, r24
  ldi r24 ,'*'
  sbrc r26,0
  ret
  ldi r24 ,'0'
  sbrc r26,1
  ret
  ldi r24 ,'#'
```

```
sbrc r26,2
ret
ldi r24, 'D'
sbrc r26,3
ret
ldi r24 ,'7'
sbrc r26,4
ret
ldi r24 ,'8'
sbrc r26,5
ret
ldi r24 ,'9'
sbrc r26,6
ret
ldi r24 ,'C'
sbrc r26,7
ret
ldi r24 ,'4'
sbrc r27,0
ret
ldi r24 ,'5'
sbrc r27,1
ret
ldi r24,'6'
sbrc r27,2
ret
ldi r24, 'B'
sbrc r27,3
ret
ldi r24 ,'1'
sbrc r27,4
ret
ldi r24 ,'2'
sbrc r27,5
ret
ldi r24 ,'3'
sbrc r27,6
ret
ldi r24 ,'A'
sbrc r27,7
ret
clr r24
ret
```

Σχόλια:

• Οι ρουτίνες που χρησιμοποιήθηκαν για το διάβασμα του πληκτρολογίου, την αρχικοποίηση της οθόνης και τη μεταφορά εντολών και δεδομένων προς την οθόνη έχουν παρθεί αυτούσιες από την εκφώνηση.

- Αρχικά το πρόγραμμα αναμένει διαρκώς το πάτημα κάποιου push button μεταξύ PB0 και PB7 που αντιστοιχούν στους αισθητήρες για την ενεργοποίηση του συναγερμού.
- Μόλις ενεργοποιηθεί κάποιο push button αρχικοποιείται ο χρονιστής ώστε να προκαλέσει διακοπή ύστερα από 5sec. Στη συνέχεια διαβάζονται από τα πληκτρολόγιο 3 χαρακτήρες. Εφόσον η εισαγωγή των χαρακτήρων γίνει εντός των 5sec (δηλαδή δεν έχει προκαλέσει διακοπή ο χρονιστής) και αντιστοιχούν στο σωστό συνδυασμό απενεργοποιείται ο συναγερμός και εμφανίζεται το μήνυμα ALARM OFF. Αν ο συνδυασμός είναι λανθασμένος ή δεν ολοκληρωθεί η εισαγωγή 3 χαρακτήρων εντός του προβλεπόμενου χρόνου ενεργοποιείται ο συναγερμός και εμφανίζεται το μήνυμα ALARM ON.
- Αν η ρουτίνα keypad_to_ascii επιστρέψει μέσω του καταχωρητή r24 την τιμή
 0 συνεπάγεται ότι δεν έχει διαβαστεί κανένας αριθμός οπότε συνεχίζουμε να διαβάζουμε μέχρι να δοθεί κάποιος αριθμός.
- Στη ρουτίνα εξυπηρέτησης της διακοπής του χρονιστή ελέγχουμε αν το flag έχει την τιμή 3 που σημαίνει ότι δόθηκε σωστός συνδυασμός ή αν ο καταχωρητής temp έχει την τιμή 3 που σημαίνει ότι δόθηκαν 3 χαρακτήρες οπότε η διαχείριση της ενεργοποίησης ή μη του συναγερμού γίνεται από το κύριο πρόγραμμα. Σε κάθε άλλη περίπτωση (δηλαδή αν δεν έχουν δοθεί 3 χαρακτήρες εντός των 5sec) η ρουτίνα εξυπηρέτησης ενεργοποιεί το συναγερμό.
- Το αναβοσβήσιμο των leds στην περίπτωση ενεργοποίησης του συναγερμού επιτυγχάνεται με μία συνεχόμενη επαναληπτική διαδικασία όπου κάθε φορά ανάβουμε τα leds για 400ms και στη συνέχεια τα σβήνουμε για 100ms.
- Ανεξάρτητα από την ενεργοποίηση του συναγερμού ή μη το σύστημα επανέρχεται μόνο με reset.

Άσκηση 2

Ο κώδικας της άσκησης φαίνεται παρακάτω:

```
.include "m16def.inc"
.def reg = r18
.def hund = r19
.def deca = r17
.def units = r16
.def cnt = r20
.def flag = r21
.def temp = r22
.def mask = r23
reset:
  ldi reg, low(RAMEND)
  out SPL, reg
  ldi reg, high(RAMEND)
  out SPH, reg
  clr reg
  out DDRA, reg
                            ;PortA as input
```

```
ser reg
        out DDRD,reg
main:
  rcall lcd_init
                 ;0->positive
   clr flag
        ldi mask,0x80
        ldi cnt,0x08
   in reg,PINA
        mov temp,reg
        and temp, mask
        cpi temp,0x00
   breq loopA
  ldi flag,0x01
loopA:
        cpi temp, 0x00
        breq pr0
        ldi r24, '1'
        rcall lcd_data
       jmp step
pr0:
        ldi r24, '0'
        rcall lcd_data
step:
        CLC
  ror mask
        mov temp,reg
        and temp, mask
   dec cnt
   brne loopA
   ldi r24,'='
   rcall lcd_data
   cpi reg,0x00
   breq print0
   cpi reg,0xff
   breq print0
   cpi flag,0x00
   breq positive
  ldi r24,'-'
   rcall lcd_data
   com reg
  jmp BCD
positive:
   ldi r24,'+'
   rcall lcd_data
BCD:
   clr hund
   clr deca
   clr units
loopB:
               ;Convert hex number to decimal
   subi reg,0x64 ;Subtract 1 hundred
```

```
brcs case1
  inc hund
               ;hundreds++
  jmp loopB
case1:
  ldi temp,0x64
  add reg,temp ;Restore one extra subtraction
  loopC:
  subi reg,0x0a ;Subtract 1 ten
  brcs case2
  inc deca
               :tens++
  jmp loopC
case2:
  ldi temp,0x0a
  add reg,temp ;Restore one extra subtraction
  mov units,reg ; what is left is the units
  ldi flag,0x00 ;hund=0
  cpi hund,0x00
  breq dig2
  ldi flag,0x01
  mov r24,hund
       ldi reg,0x30
       add r24,reg
  rcall lcd_data
dig2:
  cpi flag,0x00
  brne show
  cpi deca,0x00
  breq dig1
show:
  mov r24,deca
       ldi reg,0x30
       add r24,reg
  reall led data
dig1:
  mov r24,units
       ldi reg,0x30
       add r24,reg
  reall led data
  ldi r25, HIGH(1000)
  ldi r24, LOW(1000)
                         ;Initialise registers for 1s delay
  rcall wait_msec
  jmp main
print0:
  ldi r24,'0'
  rcall lcd_data
  ldi r25, HIGH(1000)
  ldi r24, LOW(1000)
                               ;Initialise registers for 1s delay
  rcall wait_msec
       jmp main
```

```
wait_msec:
  push r24
   push r25
  ldi r24, low(998)
  ldi r25, high(998)
  rcall wait_usec
   pop r25
   pop r24
  sbiw r24, 1
   brne wait_msec
  ret
wait_usec:
   sbiw r24,1
   nop
   nop
   nop
  nop
  brne wait_usec
  ret
write_2_nibbles:
  push r24
  in r25, PIND
  andi r25,0x0f
  andi r24,0xf0
  add r24, r25
  out PORTD ,r24
  sbi PORTD, PD3
  cbi PORTD, PD3
  pop r24
  swap r24
  andi r24,0xf0
  add r24, r25
  out PORTD, r24
  sbi PORTD, PD3
  cbi PORTD, PD3
  ret
lcd_data:
  sbi PORTD, PD2
  rcall write_2_nibbles
  ldi r24 ,43
  ldi r25,0
  rcall wait_usec
  ret
lcd_command:
  cbi PORTD, PD2
  rcall write_2_nibbles
  ldi r24 ,39
```

```
ldi r25,0
  rcall wait_usec
  ret
lcd_init:
  ldi r24,40
  ldi r25,0
  reall wait msec
  ldi r24,0x30
  out PORTD, r24
  sbi PORTD, PD3
  cbi PORTD, PD3
  ldi r24,39
  ldi r25,0
  rcall wait_usec
  ldi r24 ,0x30
  out PORTD, r24
  sbi PORTD, PD3
  cbi PORTD, PD3
  ldi r24,39
  ldi r25,0
  rcall wait_usec
  ldi r24,0x20
  out PORTD ,r24
  sbi PORTD, PD3
  cbi PORTD, PD3
  ldi r24,39
  ldi r25,0
  rcall wait usec
  ldi r24 .0x28
  reall led command
  ldi r24 ,0x0c
  reall led command
  ldi r24,0x01
  rcall lcd_command
  ldi r24 ,low(1530)
  ldi r25 ,high(1530)
  rcall wait usec
  ldi r24,0x06
  rcall lcd_command
  ret
```

Σχόλια:

- Στον καταχωρητή flag αποθηκεύουμε το πρόσημο του αριθμού που δίνεται ως είσοδος. Συγκεκριμένα απομονώνουμε το MSB εφόσον ο αριθμός δίνεται σε μορφή συμπληρώματος ως προς 1 και αν είναι 0 πρόκειται για θετικό οπότε θέτουμε flag = 0 αλλιώς flag = 1.
- Στη συνέχεια απομονώνουμε ένα-ένα bit του αριθμού εισόδου και το εκτυπώνουμε. Ανάλογα με την τιμή του flag εκτυπώνουμε το σωστό πρόσημο

και αν πρόκειται για αρνητικό θεωρούμε το συμπλήρωμά του ως προς 1 (δηλαδή παίρνουμε την απόλυτη τιμή του). Στη συνέχεια μετατρέπουμε το δυαδικό αριθμό σε BCD με τη μέθοδο των επαναλαμβανόμενων αφαιρέσεων και εκτυπώνουμε τα δεκαδικά ψηφία αποφεύγοντας την εκτύπωση περιττών μηδενικών με κατάλληλους ελέγχους.

Για να περιλαμβάνει η υλοποίηση και τη διπλή αναπαράσταση του μηδενός εκτελούμε στην αρχή δύο επιπρόσθετους ελέγχους για να διαπιστώσουμε αν ο αριθμός εισόδου είναι 0x00 ή 0xff οπότε και εκτυπώνουμε απευθείας 0 ως αποτέλεσμα.

Άσκηση 3

Ο κώδικας της άσκησης φαίνεται παρακάτω:

```
.include "m16def.inc"
.def reg = r20
.def temp = r21
.def Min = r16
.def Second = r17
.def tens = r18
.def units = r19
.org 0x00
rjmp reset
reset:
  ldi reg, low(RAMEND)
  out SPL, reg
  ldi reg, high(RAMEND)
  out SPH, reg
  clr reg
  out DDRB, reg
                      ;PortB as input
  ldi r24 ,0xfc ;111111100, PD7-2 output
  out DDRD, r24
main:
  rcall lcd_init
  clr Min
  clr Second
  rcall display_init_clk
start:
  in reg, PINB
  mov temp, reg
  andi temp, 0x80
```

cpi temp, 0x80

```
breq main
next:
  mov temp, reg
  andi temp, 0x01
  cpi temp, 0x01
                      ;Check for PB0 press
  brne start
  rcall inc_clock_and_display
  rjmp start
;This routine displays the following message to LCD display
               "00 MIN:00 SEC"
display_init_clk:
  ldi r24, '0'
  rcall lcd_display
       ldi r24, '0'
  rcall lcd_display
  ldi r24, ''
  rcall lcd_display
  ldi r24, 'M'
  rcall lcd_display
  ldi r24, 'I'
  rcall lcd_display
  ldi r24, 'N'
  rcall lcd_display
  ldi r24, ':'
  rcall lcd_display
  ldi r24, '0'
  rcall lcd_display
       ldi r24, '0'
  rcall lcd_display
  ldi r24, ''
  rcall lcd_display
  ldi r24, 'S'
  rcall lcd_display
  ldi r24, 'E'
  rcall lcd_display
  ldi r24, 'C'
  rcall lcd_display
ret
inc_clock_and_display:
  push temp
```

```
push reg
  inc Second
  cpi Second, 0x3C
  brne display
  clr Second
                     ;If Sec=60(10) Sec=0 and Min=Min+1
  inc Min
  cpi Min, 0x3C
  brne display
  clr Min
                  ;If Min=60(10) Min=0
display:
  ldi r24, LOW(1000)
  ldi r25, HIGH(1000)
  rcall wait msec
                     ;Wait for 1s
       rcall lcd_init
  mov reg, Min
  rcall hex_to_bcd
                      ;Convert minutes to BCD
  mov temp, tens
  ldi reg, 0x30
                    ;Convert to ASCII code
  add temp, reg
  mov r24, temp
  rcall lcd_display
                      ;Display
  mov temp, units
                    ;Convert to ASCII code
  add temp, reg
  mov r24, temp
  rcall lcd_display
                      ;Display minutes
  ;Display "MIN:"
  ldi r24, ''
  rcall lcd_display
  ldi r24, 'M'
  rcall lcd_display
  ldi r24, 'I'
  rcall lcd_display
  ldi r24, 'N'
  rcall lcd_display
  ldi r24, ':'
  rcall lcd_display
  mov reg, Second
  rcall hex_to_bcd
                     ;Convert seconds to BCD
  mov temp, tens
  ldi reg, 0x30
                    ;Convert to ASCII code
  add temp, reg
  mov r24, temp
```

```
rcall lcd_display
                       ;Display
  mov temp, units
       out PORTA, units
       ldi reg, 0x30
  add temp, reg
                     ;Convert to ASCII code
  mov r24, temp
  rcall lcd_display
                      ;Display seconds
  ;Display "SEC"
  ldi r24, ''
  rcall lcd_display
  ldi r24, 'S'
  rcall lcd_display
  ldi r24, 'E'
  rcall lcd_display
  ldi r24, 'C'
  rcall lcd_display
  pop reg
  pop temp
ret
;This routine takes a hex number as input stored in reg register
;and returns the BCD representation of this number
;The units are stored in units register and the tens in tens register
hex to bcd:
   push temp
   clr tens
   clr units
loopA:
   subi reg, 0x0A; Subtract 1 ten
   brcs case1
   inc tens
               ;tens++
  jmp loopA
case1:
   ldi temp,0x0A
   add reg,temp ;Restore one extra subtraction
   mov units, reg
        pop temp
ret
wait_msec:
   push r24
   push r25
```

```
ldi r24, low(998)
  ldi r25, high(998)
  rcall wait_usec
  pop r25
  pop r24
   sbiw r24, 1
  brne wait_msec
  ret
wait_usec:
   sbiw r24,1
  nop
  nop
  nop
  nop
  brne wait_usec
  ret
write_2_nibbles:
  push r24
  in r25,PIND
  andi r25,0x0f
  andi r24,0xf0
  add r24, r25
  out PORTD, r24
  sbi PORTD, PD3
  cbi PORTD, PD3
  pop r24
  swap r24
  andi r24 ,0xf0
  add r24,r25
  out PORTD, r24
  sbi PORTD, PD3
  cbi PORTD,PD3
  ret
lcd_display:
  sbi PORTD, PD2
  rcall write_2_nibbles
  ldi r24,43
  ldi r25,0
  rcall wait_usec
  ret
lcd_command:
```

cbi PORTD, PD2 rcall write_2_nibbles ldi r24 ,39 ldi r25,0 rcall wait_usec ret lcd_init: ldi r24,40 ldi r25,0 rcall wait_msec ldi r24,0x30 out PORTD, r24 sbi PORTD, PD3 cbi PORTD, PD3 ldi r24 ,39 ldi r25,0 rcall wait_usec ldi r24,0x30 out PORTD, r24 sbi PORTD, PD3 cbi PORTD, PD3 ldi r24,39 ldi r25,0 rcall wait_usec ldi r24,0x20 out PORTD, r24 sbi PORTD, PD3 cbi PORTD, PD3 ldi r24,39 ldi r25,0 rcall wait_usec ldi r24,0x28 rcall lcd_command ldi r24 ,0x0c rcall lcd_command ldi r24,0x01 rcall lcd_command ldi r24 ,low(1530) ldi r25 ,high(1530) rcall wait_usec ldi r24,0x06 reall led_command

ret

Σχόλια:

- Ο κώδικας ελέγχει πρώτα αν είναι πατημένο το push button PB7 που αντιστοιχεί στο πλήκτρο reset του χρονομέτρου. Αν είναι πατημένο αρχικοποιείται ξανά η οθόνη και εμφανίζεται η αρχική ένδειξη "00 MIN:00 SEC".
- Στη συνέχεια ελέγχεται αν είναι ενεργοποιημένο το πλήκτρο για τη λειτουργία του χρονομέτρου που αντιστοιχεί στο push button PB0. Αν δεν είναι ενεργοποιημένο οι ενδείξεις παραμένουν σταθερές στην οθόνη και επαναλαμβάνονται διαρκώς οι παραπάνω έλεγχοι.
- Εφόσον το χρόνομετρο βρίσκεται σε λειτουργία καλείται η ρουτίνα inc_clock_and_display η οποία αρχικά αυξάνει τα δευτερόλεπτα κατά ένα εφόσον δεν υπερβαίνουν την τιμή 59. Διαφορετικά μηδενίζει τα δευτερόλεπτα και αυξάνει τα λεπτά κατά ένα, ενώ αν το χρονόμετρο βρίσκεται στο σημείο 59:59 επανέρχεται στο 00:00. Στη συνέχεια προκαλείται καθυστέρηση ενός δευτερολέπτου με τη βοήθεια της ρουτίνας wait_msec.
- Επιπλέον η ρουτίνα inc_clock_and_display μετατρέπει τα λεπτά και τα δευτερόλεπτα σε BCD με κλήση της ρουτίνας hex_to_bcd και εκτυπώνει το κατάλληλο μήνυμα στην οθόνη ""XX MIN:XX SEC".