

DROID RECOVERY

How to Boot into Recovery Mode & Fastboot Mode on Android

BLU C5L Max Recovery and Fastboot Mode

🐦 Twitter

(<https://twitter.com/intent/tweet?text=How to Boot BLU%20C5L%20Max into Recovery Mode&url=https%3A%2F%2Fdroidrecovery.com%2Fblu-c5l-max-recovery-mode%2F&via=>)

📘 Facebook

(<https://www.facebook.com/sharer/sharer.php?u=https%3A%2F%2Fdroidrecovery.com%2Fblu-c5l-max-recovery-mode%2F>)

👍 Reddit

(<https://www.reddit.com/submission?url=https%3A%2F%2Fdroidrecovery.com%2Fblu-c5l-max-recovery-mode%2F>)

Want to Boot BLU C5L Max into Recovery Mode or Fastboot Mode or Bootloader Mode? Then follow the instructions listed on this page to successfully Boot BLU C5L Max to Fastboot Mode or Recovery Mode.

BLU C5L Max Recovery Mode allows the users to perform advanced operations like flashing Root Package (<http://bit.ly/2ppJvQE>), and other zip mods, wipe user cache and data, and many more.

BLU C5L Max Fastboot Mode allows the user to flash Custom Image files and Custom Recovery like TWRP, CWM, Philz, etc. on to the device. Let's now proceed and see How to reboot BLU C5L Max into Recovery Mode and Fastboot Mode.

Also: BLU G91 Max Recovery Mode and Fastboot Mode (<https://droidrecovery.com/blu-g91-max-recovery-mode/>)

Boot BLU C5L Max into Recovery Mode

Below are the methods using which you can boot BLU C5L Max into Recovery Mode.

Boot BLU C5L Max Recovery Mode using Hardware Buttons

1. First of all, power off your phone.
2. Now, press and hold the **Volume Up** and **Power button** together for a few seconds.





(<https://droidrecovery.com/wp-content/uploads/phone-14-volume-up-power-1.png>)


3. Release the keys as soon as you see the BLU logo and wait for few seconds.
4. If Android Robot appears, press the **Volume Up** and **Power button**.



(<https://droidrecovery.com/wp-content/uploads/Android-Bot-Red-Exclamation.jpg>)

5. Now, your phone should boot into Recovery Mode.

```
Android Recovery
10/CP1A.190711.020/6J22
user/release-keys
Use volume up/down and power.
```



(<https://droidrecovery.com/wp-content/uploads/recovery.png>)

Boot BLU C5L Max into Recovery using ADB command

1. First of all, make sure you have installed [BLU C5L Max USB Driver \(/out/?I=d3RIUFBSRndIS2NsbStOdFU5MFRBSm5SY0JhekpWbithMIJpQVZON0dyTExFbVp3cm9pckZON1NtUION2ZYenUrRWU3d3NZRmRrek9JMWc0cklYdFE9PQ==\)](#) and ADB and Fastboot Drivers on your Windows PC.
2. Enable "*USB Debugging*" on your phone from *Developer Options*. If *Developer Options* is missing; go to **Settings > About Phone** and tap on **Build Number** for about 7-10 times.
3. Connect your device to PC and open *Command Prompt (CMD)*.
4. Enter the below command to boot BLU C5L Max into Recovery Mode.

```
adb reboot recovery
```

Boot BLU C5L Max into Fastboot Mode / Bootloader Mode

Below are the methods using which you can boot BLU C5L Max into Bootloader Mode or Fastboot Mode.

Boot BLU C5L Max Bootloader Mode/Fastboot Mode using Hardware Buttons

1. Power off your Phone.

2. Now, press and hold the **Volume Up** and **Power button** together for a few seconds.





(<https://droidrecovery.com/wp-content/uploads/phone-14-volume-up-power-1.png>)


3. Release the keys as soon as you see the BLU logo and wait for few seconds.
4. If Android Robot appears, press the **Volume Up** and **Power button**.



(<https://droidrecovery.com/wp-content/uploads/Android-Bot-Red-Exclamation.jpg>)

5. Now, your phone should boot into Recovery Mode.

```
Android Recovery
10/QP1A.190711.020/6J22
user/release-keys
Use volume up/down and power.
Reboot system now
Reboot to bootloader
Enter fastboot
Apply update from ADR
```



6. In the next step, select "**Enter fastboot**" using Volume keys and press the Power button to confirm.
7. Now, your phone should boot into Fastboot Mode.



(<https://droidrecovery.com/wp-content/uploads/fastboot-mode.png>)

Boot BLU C5L Max Bootloader Mode/Fastboot Mode using ADB command

Assuming ADB and Fastboot Drivers installed on PC, and USB Debugging enabled on Phone enter the below command after connecting it to PC.

Open *Command Prompt (CMD)* on your PC and enter the below command.

```
adb reboot bootloader
```

Related Tutorials

[How to Factory Reset BLU C5L Max \(/out/?](#)

[I=cVNyRmVMZmFoekk4Y1FpZmNKUikyanVCM1h1d3djWGhqN0U1T3plc0dNL3RRYjNKB2Y5K21iY2RNZ2U5aUc2bWlhRIB4SWZ3WnY3YINRVkNWM2YzcXc9PQ==\)">](#)

