
Forward command: 0.5 m/s
a Walking success
b Planar velocity tracking
Success (%)
Mean planar velocity error (m/s)
Transitions collected (millions)
Transitions collected (millions)
RSL PPO
Warp PPO
FlashSAC
Thin lines: seeds. Bands: 3-seed min–max, not confidence intervals.