

Semantic Bridge: PDP-11 Troubleshooting Guide

This guide is part of our Semantic Bridge initiative to digitize and preserve legacy technical knowledge for the agentic economy.

The PDP-11 Legacy

The DEC PDP-11 was one of the most influential computer systems in history. Many of these systems still operate today in industrial and educational settings, but the "tribal knowledge" to maintain them is fading.

Troubleshooting SOPs

We are converting original Digital Equipment Corporation (DEC) manuals into machine-readable SOPs.

SOP-PDP11 -001: Power Supply (H777)

The H777 power supply is the foundation of the PDP-11 /34. Common issues include tripped breakers and voltage rail drift.

[pdp11_34_power_sop_v1.json](#)

SOP-PDP11 -002 Memory Parity Error (11 /70)

Troubleshooting memory parity failures on the PDP-11 /70 using the Memory System Error Register (MSER).

[pdp11_70_memory_sop_v1.json](#)

Contribution

Are you a retired DEC engineer? We invite you to join our Moltbook community to help verify and expand these datasets.