# Enhanced Cpk Data Sheet - Enclosures MD

Rev: A.3

Instructions

| | |
|---|---|
| 파란 필수입력란 | 검토 |
| 참조값 입력란(선택) | ABS |
| 참조값 없음 | A |
| 참조값 변경됨 | 260320 260324 260323 260325 260321 260320 260321 260318 260319 260321 260319 260319 260321 260320 260320 260320 260321 260318 260321 260320 260320 260321 260320 260320 260321 260320 260318 260307 260316 260317 260317 260317 |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Part Number | **KY-17208** | Supplier | **Samsteck** | Tool # / Build / DOE Name | **A Trial / MP / PPAP** | | |
| Part Description | **E-Center** | Inspector | **K J Oh** | Notes/Comments | Date : 20251208(Mon) / Operator : 20250731(Thu) | | |
| Revision | **A1** | Date | **2026년 / 3월26일 / 4주일째 260326** | ASM/CMM Program version | **MP** | | |

## MEASURING SPECIFICATIONS

| FAI | SPC | Description | Target Cpk | Tolerance Type | Nominal | USL for sets (when query) | LSL for sets (when query) | TOL | Inspection Method | Gage Required | LSL | USL |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 2-1 | B | Straightness | 1.33 | DON'T | | 0.008 | | | CMM | NO | 0.008 | |
| 2-2 | B | Straightness | 1.33 | DON'T | | 0.008 | | | CMM | NO | 0.008 | |
| 2-3 | B | Straightness | 1.33 | DON'T | | 0.008 | | | CMM | NO | 0.008 | |
| 2-4 | B | Straightness | 1.33 | DON'T | | 0.008 | | | CMM | NO | 0.008 | |
| 3 | C | Runout(A guide) | 1.33 | DON'T | | 0.012 | | | CMM | NO | 0.012 | |
| 5-4 | D | Distance | 1.33 | Tolerance | 0.005 | 0.015 | -0.015 | | CMM | NO | 0.015 | 0.995 |
| 5-5 | D | Distance | 1.33 | Tolerance | 0.005 | 0.015 | -0.015 | | CMM | NO | 0.015 | 0.995 |
| 6-x | D | Distance | 1.33 | Tolerance | 0.219 | 0.23 | -0.03 | | CMM | NO | 0.189 | 0.249 |
| 6-x | F | Distance | 1.33 | Tolerance | 0.72 | 0.77 | -0.02 | | CMM | NO | 0.700 | 0.740 |
| 6-x | F | Distance | 1.33 | Tolerance | 0.72 | 0.77 | -0.02 | | CMM | NO | 0.700 | 0.740 |
| 6-x | F | Distance | 1.33 | Tolerance | 0.72 | 0.77 | -0.02 | | CMM | NO | 0.700 | 0.740 |
| 6-x | F | Distance | 1.33 | Tolerance | 0.72 | 0.77 | -0.02 | | CMM | NO | 0.700 | 0.740 |
| 7 | D | Distance | 1.33 | Tolerance | 0.219 | 0.23 | -0.03 | | CMM | NO | 0.189 | 0.249 |
| 8 | H | Distance | 1.33 | Tolerance | 0.8 | 0.818 | -0.018 | | CMM | NO | 0.818 | 0.889 |
| 9-1(S1) | I | Distance | 1.33 | Tolerance | 0.1 | 0.135 | -0.035 | | CMM | NO | 0.135 | 0.065 |
| 9-2(S2) | I | Distance | 1.33 | Tolerance | 0.105 | 0.135 | -0.035 | | CMM | NO | 0.135 | 0.065 |
| 9-3(S3) | I | Distance | 1.33 | Tolerance | 0.1 | 0.135 | -0.035 | | CMM | NO | 0.135 | 0.065 |
| 9-4(S4) | I | Distance | 1.33 | Tolerance | 0.1 | 0.135 | -0.035 | | CMM | NO | 0.135 | 0.065 |
| 9-5(S5) | I | Distance | 1.33 | Tolerance | 0.1 | 0.135 | -0.035 | | CMM | NO | 0.135 | 0.065 |
| 9-6(S6) | I | Distance | 1.33 | Tolerance | 0.1 | 0.135 | -0.035 | | CMM | NO | 0.135 | 0.065 |
| 9-7(S7) | I | Distance | 1.33 | Tolerance | 0.1 | 0.135 | -0.035 | | CMM | NO | 0.135 | 0.065 |
| 9-8(S8) | I | Distance | 1.33 | Tolerance | 0.1 | 0.135 | -0.035 | | CMM | NO | 0.135 | 0.065 |
| 11 | K | Parallelism | 1.33 | DON'T | | 0.035 | | | CMM | NO | 0.035 | |
| 12-C1 | L | Distance | 1.33 | Tolerance | 0.52 | 0.53 | -0.03 | | CMM | NO | 0.490 | 0.550 |
| 12-C2 | L | Distance | 1.33 | Tolerance | 0.52 | 0.53 | -0.03 | | CMM | NO | 0.490 | 0.550 |
| 12-C3 | L | Distance | 1.33 | Tolerance | 0.52 | 0.53 | -0.03 | | CMM | NO | 0.490 | 0.550 |
| 12-C4 | L | Distance | 1.33 | Tolerance | 0.52 | 0.53 | -0.03 | | CMM | NO | 0.490 | 0.550 |
| 13-1(P1) | M | Distance | 1.33 | Tolerance | 0.23 | 0.252 | -0.036 | | CMM | NO | 0.194 | 0.266 |
| 13-2(P2) | M | Distance | 1.33 | Tolerance | 0.23 | 0.252 | -0.036 | | CMM | NO | 0.194 | 0.266 |
| 14-1(P1) | N | Distance | 1.33 | Tolerance | 14.264 | 14.334 | -0.036 | | CMM | NO | 14.228 | 14.300 |
| 14-2(P2) | N | Distance | 1.33 | Tolerance | 14.264 | 14.334 | -0.036 | | CMM | NO | 14.228 | 14.300 |
| 15-P1 | O | Distance | 1.33 | Tolerance | 1.84 | 1.893 | -0.053 | | CMM | NO | 1.787 | 1.893 |
| 15-P2 | O | Distance | 1.33 | Tolerance | 1.84 | 1.893 | -0.053 | | CMM | NO | 1.787 | 1.893 |
| 16-1(S-C) | O | Distance | 1.33 | Tolerance | 1.88 | 1.933 | -0.053 | | CMM | NO | 1.827 | 1.933 |
| 16-1(S-D) | O | Distance | 1.33 | Tolerance | 1.88 | 1.933 | -0.053 | | CMM | NO | 1.827 | 1.933 |
| 20 | T | Distance | 1.33 | Tolerance | 13.884 | 13.934 | -0.050 | | CMM | NO | 13.834 | 13.934 |
| 21 | U | Distance | 1.33 | Tolerance | 0.565 | 0.597 | -0.032 | | CMM | NO | 0.533 | 0.597 |
| 22 | V | Distance | 1.33 | Tolerance | 15.438 | 15.488 | -0.050 | | CMM | NO | 15.388 | 15.488 |
| 23 | W | Distance | 1.33 | Tolerance | 13.393 | 13.443 | -0.050 | | CMM | NO | 13.343 | 13.443 |
| 24 | X | Distance | 1.33 | Tolerance | 15.324 | 15.374 | -0.050 | | CMM | NO | 15.274 | 15.374 |
| 25-1(P1) | Y | Distance | 1.33 | Tolerance | 0.53 | 0.578 | -0.048 | | CMM | NO | 0.482 | 0.578 |
| 25-2(P2) | Y | Distance | 1.33 | Tolerance | 0.53 | 0.578 | -0.048 | | CMM | NO | 0.482 | 0.578 |
| 26-1 | Z | Distance | 1.33 | Tolerance | 0.239 | 0.252 | -0.036 | | CMM | NO | 0.216 | 0.288 |
| 26-2 | Z | Distance | 1.33 | Tolerance | 0.239 | 0.252 | -0.036 | | CMM | NO | 0.216 | 0.288 |
| 27 | AA | Distance | 1.33 | Tolerance | 14.228 | 14.278 | -0.050 | | CMM | NO | 14.178 | 14.278 |
| 28 | AB | Distance | 1.33 | Tolerance | 1.84 | 1.893 | -0.053 | | CMM | NO | 1.787 | 1.893 |
| 29 | AC | Distance | 1.33 | Tolerance | 0.52 | 0.53 | -0.03 | | CMM | NO | 0.490 | 0.550 |
| 31 | AE | Distance | 1.33 | Tolerance | 0.239 | 0.252 | -0.036 | | CMM | NO | 0.216 | 0.288 |
| 33 | AG | Distance | 1.33 | Tolerance | 1.107 | 0.029 | -0.029 | | CMM | NO | 1.162 | 1.102 |
| 34 | | Distance | | Tolerance | 13.974 | 0.05 | -0.05 | | CMM | NO | 13.924 | 14.024 |
| 35-1(P1) | | Distance | | Tolerance | 0.08 | 0.01 | -0.03 | | CMM | NO | 0.100 | 0.060 |
| 35-2(P2) | | Distance | | Tolerance | 0.08 | 0.01 | -0.03 | | CMM | NO | 0.100 | 0.060 |
| 36 | | Distance | | Tolerance | 11.277 | 0.03 | -0.03 | | CMM | NO | 11.307 | 11.247 |
| 37-1(C1) | BF | Distance | 1.33 | Tolerance | 0.1 | 0.135 | -0.035 | | CMM | NO | 0.135 | 0.065 |
| 37-2(C2) | BF | Distance | 1.33 | Tolerance | 0.1 | 0.135 | -0.035 | | CMM | NO | 0.135 | 0.065 |
| 38-1(C1) | BE | Distance | 1.33 | Tolerance | 0.5 | 0.53 | -0.03 | | CMM | NO | 0.490 | 0.550 |
| 38-2(C2) | BE | Distance | 1.33 | Tolerance | 0.5 | 0.53 | -0.03 | | CMM | NO | 0.490 | 0.550 |
| 39 | | Distance | | Tolerance | 14.48 | 0.02 | -0.03 | | CMM | NO | 14.509 | 14.480 |
| 40 | | Distance | | Tolerance | 2.489 | 0.03 | -0.03 | | CMM | NO | 2.519 | 2.489 |
| 41 | | Distance | | Tolerance | 2.689 | 0.03 | -0.03 | | CMM | NO | 2.719 | 2.689 |
| 46 | | Distance | | Tolerance | 0.239 | 0.252 | -0.036 | | CMM | NO | 0.216 | 0.288 |
| 48 | | Distance | | Tolerance | 12.972 | 0.02 | -0.02 | | CMM | NO | 12.972 | 12.992 |
| 47 | AL | Distance | 1.33 | Tolerance | 14.909 | 0.03 | -0.03 | | CMM | NO | 14.879 | 14.909 |
| 50 | | Distance | | Tolerance | 8.001 | 0.02 | -0.02 | | CMM | NO | 8.021 | 8.001 |
| 51 | AS | Distance | 1.33 | Tolerance | 1.48 | 0.02 | -0.02 | | CMM | NO | 1.460 | 1.480 |
| 52 | AW | Distance | 1.33 | Tolerance | 2.44 | 0.03 | -0.03 | | CMM | NO | 2.473 | 2.443 |
| 53 | | Distance | | Tolerance | 0.239 | 0.252 | -0.036 | | CMM | NO | 0.216 | 0.288 |
| 54-P1 | | True Position | | DON'T | | 0.075 | | | CMM | NO | 0.075 | |
| 54-P2 | | True Position | | DON'T | | 0.075 | | | CMM | NO | 0.075 | |
| 55-P1 | | True Position | | DON'T | | 0.075 | | | CMM | NO | 0.075 | |
| 55-P2 | | True Position | | DON'T | | 0.085 | | | CMM | NO | 0.085 | |
| 56-1(P1) | | Distance | | Tolerance | 0.809 | 0.03 | -0.03 | | CMM | NO | 0.779 | 0.839 |
| 56-2(P2) | | Distance | | Tolerance | 0.809 | 0.03 | -0.03 | | CMM | NO | 0.779 | 0.839 |
| 57 | AM | Distance | | Tolerance | 16.769 | 0.03 | -0.03 | | CMM | NO | 16.739 | 16.799 |
| 66 | | Angle | | Tolerance | 0 | 3 | -3 | | CMM | NO | -3.000 | 3.000 |
| 67 | | Distance | | Tolerance | 0.437 | 0.45 | -0.03 | | CMM | NO | 0.407 | 0.467 |
| 68 | | Distance | | Tolerance | 1.479 | 1.5 | -0.3 | | CMM | NO | 1.179 | 1.800 |
| 69 | | Distance | | Tolerance | 1.479 | 1.5 | -0.3 | | CMM | NO | 1.179 | 1.800 |
| 69-2 | | Distance | | Tolerance | 1.479 | 1.5 | -0.3 | | CMM | NO | 1.179 | 1.800 |
| 70-1 | AN-1 | Distance | 1.33 | Tolerance | 0.23 | 0.25 | -0.02 | | CMM | NO | 0.210 | 0.250 |
| 70-2 | AN-2 | Distance | 1.33 | Tolerance | 0.23 | 0.25 | -0.02 | | CMM | NO | 0.210 | 0.250 |
| 80 | | Distance | | Tolerance | 10.381 | 0.02 | -0.03 | | CMM | NO | 10.351 | 10.401 |
| 81 | | Distance | | Tolerance | 17.766 | 0.03 | -0.03 | | CMM | NO | 17.736 | 17.796 |
| 82 | | Distance | | Tolerance | 2.878 | 0.03 | -0.03 | | CMM | NO | 2.718 | 2.838 |
| 83 | | Distance | | Tolerance | 1.153 | 0.03 | -0.03 | | CMM | NO | 1.123 | 1.183 |
| 84 | | Distance | | Tolerance | 1.103 | 0.03 | -0.03 | | CMM | NO | 1.143 | 1.073 |
| 85 | | Distance | | Tolerance | 0.878 | 0.03 | -0.03 | | CMM | NO | 0.848 | 0.908 |
| 86-A1 | BN | Distance | 1.33 | Tolerance | 16.48 | 0.03 | -0.03 | | CMM | NO | 16.450 | 16.510 |
| 86-A2 | BN | Distance | 1.33 | Tolerance | 16.48 | 0.03 | -0.03 | | CMM | NO | 16.450 | 16.510 |
| 86-A3 | BN | Distance | 1.33 | Tolerance | 16.48 | 0.03 | -0.03 | | CMM | NO | 16.450 | 16.510 |
| 86-A4 | BN | Distance | 1.33 | Tolerance | 16.48 | 0.03 | -0.03 | | CMM | NO | 16.450 | 16.510 |
| 86-A5 | BN | Distance | 1.33 | Tolerance | 16.48 | 0.03 | -0.03 | | CMM | NO | 16.450 | 16.510 |
| 86-A6 | BN | Distance | 1.33 | Tolerance | 16.48 | 0.03 | -0.03 | | CMM | NO | 16.450 | 16.510 |
| 87 | | Distance | | Tolerance | 0.824 | 0.03 | -0.03 | | CMM | NO | 0.794 | 0.854 |
| 88-A1 | BO | Distance | 1.33 | Tolerance | 0.392 | 0.02 | -0.03 | | CMM | NO | 0.362 | 0.412 |
| 88-A2 | BO | Distance | 1.33 | Tolerance | 0.392 | 0.02 | -0.03 | | CMM | NO | 0.362 | 0.412 |
| 88-A3 | BO | Distance | 1.33 | Tolerance | 0.392 | 0.02 | -0.03 | | CMM | NO | 0.362 | 0.412 |
| 88-A4 | BO | Distance | 1.33 | Tolerance | 0.392 | 0.02 | -0.03 | | CMM | NO | 0.362 | 0.412 |
| 88-A5 | BO | Distance | 1.33 | Tolerance | 0.392 | 0.02 | -0.03 | | CMM | NO | 0.362 | 0.412 |
| 88-A6 | BO | Distance | 1.33 | Tolerance | 0.392 | 0.02 | -0.03 | | CMM | NO | 0.362 | 0.412 |
| 89 | | Distance | | Tolerance | 9.704 | 0.03 | -0.03 | | CMM | NO | 9.734 | 9.674 |
| 90-1 | BR-1 | Distance | 1.33 | Tolerance | 0.773 | 0.03 | -0.03 | | CMM | NO | 0.743 | 0.803 |
| 90-2 | BR-2 | Distance | 1.33 | Tolerance | 0.773 | 0.03 | -0.03 | | CMM | NO | 0.743 | 0.803 |
| 97-1 | BH-1 | Distance | 1.33 | Tolerance | 15.168 | 0.02 | -0.03 | | CMM | NO | 15.138 | 15.188 |
| 97-2 | BH-2 | Distance | 1.33 | Tolerance | 15.168 | 0.02 | -0.03 | | CMM | NO | 15.138 | 15.188 |
| 98-X1 | BI-1(X) | Distance | 1.33 | Tolerance | 5.451 | 0.01 | -0.01 | | CMM | NO | 5.440 | 5.460 |
| 98-X2 | BI-2(X) | Distance | 1.33 | Tolerance | 5.451 | 0.01 | -0.01 | | CMM | NO | 5.440 | 5.460 |
| 98-Y1 | BH-1 | Distance | 1.33 | Tolerance | 15.168 | 0.02 | -0.03 | | CMM | NO | 15.138 | 15.188 |
| 98-Y2 | BH-2 | Distance | 1.33 | Tolerance | 15.168 | 0.02 | -0.03 | | CMM | NO | 15.138 | 15.188 |
| 98-Z1 | BI-1(Y) | Distance | 1.33 | Tolerance | 5.451 | 0.01 | -0.01 | | CMM | NO | 5.440 | 5.460 |
| 98-Z2 | BI-2(Y) | Distance | 1.33 | Tolerance | 5.451 | 0.01 | -0.01 | | CMM | NO | 5.440 | 5.460 |
| 100-1(P1) | | Distance | | Tolerance | 0.002 | 0.01 | -0.009 | | CMM | NO | -0.007 | 0.011 |
| 100-2(P2) | | Distance | | Tolerance | 0.002 | 0.01 | -0.009 | | CMM | NO | -0.007 | 0.011 |
| 101-1(P1) | | Distance | | Tolerance | 0.005 | 0.002 | -0.009 | | CMM | NO | -0.004 | 0.007 |
| 101-2(P2) | | Distance | | Tolerance | 0.005 | 0.002 | -0.009 | | CMM | NO | -0.004 | 0.007 |
| 102-1(P1) | | Distance | | Tolerance | 0.009 | 0.002 | -0.009 | | CMM | NO | 0.000 | 0.011 |
| 102-2(P2) | | Distance | | Tolerance | 0.009 | 0.002 | -0.009 | | CMM | NO | 0.000 | 0.011 |
| 103-1(P1) | | Distance | | Tolerance | 0.007 | 0.01 | -0.004 | | CMM | NO | 0.003 | 0.011 |
| 103-2(P2) | | Distance | | Tolerance | 0.007 | 0.01 | -0.004 | | CMM | NO | 0.003 | 0.011 |
| 104-1(P1) | | Distance | | Tolerance | 0.008 | 0.002 | -0.009 | | CMM | NO | -0.001 | 0.010 |
| 104-2(P2) | | Distance | | Tolerance | 0.008 | 0.002 | -0.009 | | CMM | NO | -0.001 | 0.010 |
| 105-1(P1) | | Distance | | Tolerance | 0.009 | 0.002 | -0.009 | | CMM | NO | 0.000 | 0.011 |
| 105-2(P2) | | Distance | | Tolerance | 0.009 | 0.002 | -0.009 | | CMM | NO | 0.000 | 0.011 |
| 106-1(P1) | | Distance | | Tolerance | 0.007 | 0.01 | -0.004 | | CMM | NO | 0.003 | 0.011 |
| 106-2(P2) | | Distance | | Tolerance | 0.007 | 0.01 | -0.004 | | CMM | NO | 0.003 | 0.011 |
| 107-1(P1) | | Distance | | Tolerance | 0.002 | 0.01 | -0.009 | | CMM | NO | -0.007 | 0.011 |
| 107-2(P2) | | Distance | | Tolerance | 0.002 | 0.01 | -0.009 | | CMM | NO | -0.007 | 0.011 |
| 108-1(P1) | | Distance | | Tolerance | 0.009 | 0.002 | -0.009 | | CMM | NO | 0.000 | 0.011 |
| 108-2(P2) | | Distance | | Tolerance | 0.009 | 0.002 | -0.009 | | CMM | NO | 0.000 | 0.011 |
| 109-1(P1) | | Distance | | Tolerance | 0.007 | 0.01 | -0.004 | | CMM | NO | 0.003 | 0.011 |
| 109-2(P2) | | Distance | | Tolerance | 0.007 | 0.01 | -0.004 | | CMM | NO | 0.003 | 0.011 |
| 110-1(P1) | | Distance | | Tolerance | 0.008 | 0.002 | -0.009 | | CMM | NO | -0.001 | 0.010 |
| 110-2(P2) | | Distance | | Tolerance | 0.008 | 0.002 | -0.009 | | CMM | NO | -0.001 | 0.010 |
| 111-1 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-2 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-3 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-4 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-5 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-6 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-7 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-8 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-9 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-10 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-11 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-12 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-13 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-14 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-15 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-16 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-17 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 111-18 | | Distance | | Tolerance | 0.03 | 0.03 | -0.03 | | CMM | NO | 0.060 | 0.000 |
| 112 | | Parallelism | | DON'T | | 0.045 | | | CMM | NO | 0.045 | |
| 116-1 | BK-1 | Distance | 1.33 | Tolerance | 15.302 | 0.02 | -0.03 | | CMM | NO | 15.272 | 15.322 |
| 116-2 | BK-2 | Distance | 1.33 | Tolerance | 15.302 | 0.02 | -0.03 | | CMM | NO | 15.272 | 15.322 |
| 118-1 | BJ-1 | Distance | 1.33 | Tolerance | 0.32 | 0.02 | -0.02 | | CMM | NO | 0.300 | 0.340 |
| 118-2 | BJ-2 | Distance | 1.33 | Tolerance | 0.32 | 0.02 | -0.02 | | CMM | NO | 0.300 | 0.340 |
| 119-1 | BO-1 | Distance | 1.33 | Tolerance | 0.32 | 0.02 | -0.02 | | CMM | NO | 0.300 | 0.340 |
| 119-2 | BO-2 | Distance | 1.33 | Tolerance | 0.32 | 0.02 | -0.02 | | CMM | NO | 0.300 | 0.340 |
| 117-1 | BP-1 | Distance | 1.33 | Tolerance | 0.32 | 0.02 | -0.02 | | CMM | NO | 0.300 | 0.340 |
| 117-2 | BP-2 | Distance | 1.33 | Tolerance | 0.32 | 0.02 | -0.02 | | CMM | NO | 0.300 | 0.340 |

## MEASURED DATA

| FAI | Maximum | Minimum | Mean | Std Dev | Cp | Cu | Cu Level | UCPL | LCPL | Cpk | Yield | Val1 | Val2 | Val3 | Val4 | Val5 | Val6 | Val7 | Val8 | Val9 | Val10 | Val11 | Val12 | Val13 | Val14 | Val15 | Val16 | Val17 | Val18 | Val19 | Val20 | Val21 | Val22 | Val23 | Val24 | Val25 | Val26 | Val27 | Val28 | Val29 | Val30 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 2-1 | 0.002 | 0.000 | 0.001 | 0.000 | 1.564 | 44.324 | Level 5 | 1.564 | | 1.564 | 100% | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 |
| 2-2 | 0.002 | 0.002 | 0.002 | 0.000 | 0.313 | 28.395 | Level 5 | 0.313 | | 0.313 | 100% | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 |
| 2-3 | 0.002 | 0.002 | 0.002 | 0.000 | 0.787 | 39.377 | Level 5 | 0.787 | | 0.787 | 100% | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 |
| 2-4 | 0.002 | 0.002 | 0.002 | 0.000 | 0.862 | 39.477 | Level 5 | 0.862 | | 0.862 | 100% | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 | 0.002 |
| 3 | 0.012 | 0.012 | 0.012 | 0.000 | 0.000 | 47.557 | Level 5 | 0.000 | | 0.000 | 100% | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 | 0.012 |
| 5-4 | 0.009 | 0.009 | 0.009 | 0.000 | 0.000 | 44.076 | Level 5 | 0.000 | 0.000 | 0.000 | 100% | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 |
| 5-5 | 0.009 | 0.009 | 0.009 | 0.000 | 0.000 | 44.076 | Level 5 | 0.000 | 0.000 | 0.000 | 100% | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 | 0.009 |
| 6-x | 0.219 | 0.219 | 0.219 | 0.000 | 1.264 | 32.705 | Level 5 | 1.264 | 1.264 | 1.264 | 100% | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 | 0.219 |
| 6-x | 0.719 | 0.719 | 0.720 | 0.000 | 1.168 | 29.105 | Level 5 | 0.952 | 1.168 | 0.952 | 100% | 0.720 | 0.719 | 0.719 | 0.720 | 0.720 | 0.720 | 0.721 | 0.720 | 0.719 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720 | 0.720