# **MECANISMES**



### Base Ed1



1 X Base ED1 09x02x0.5



3 X BeamSTRESS\_ERHRHDE\_BU02x01x01 3 X ScrewFL-RHRHD\_BU00.25



3 X ScrewFL-RHRHD\_BU01.50





3 X NutRH BU01.00x00.50

# Model3 - Manibela Biela - Pas 1/5



1 X BeamSTRESS\_BU09x01x01



4 X BeamSTRESS ERHRHDE BU05x01x01



2 X ScrewFL-RHRHD\_BU03.25





4 X ScrewFL-RHRHD\_BU00.25 2 X NutRH\_BU01.00x00.50



#### Model3 - Manibela Biela - Pas 2/5



1 X BeamSTRESS BU05x01x01




2 X BeamSTRESS\_BU01x01x01




1 X BeamSTRESS\_ERHRHDE\_BU05x01x01 2 X NutRH\_BU01.00x00.50















## Model3 - Manibela Biela - Pas 3/5



1 X Base Motor 05x05x0.5



2 X ScrewFL-RHRHD\_BU01.50






1 X Motor Stepper



2 X NutRH BU01.00x00.50



2 X ScrewFL-RHRHD\_BU00.25 2 X Beam STR ESS ERHRH DE



## Model3 - Manibela Biela - Pas 4/5



1 X WasherFXD\_BU05.00x00.25



1 X ScrewFL-RHRHD\_BU01.50




1 X ScrewFL-RHRHD\_BU00.25 1 X NutRH\_BU01.00x00.50



1 X Adaptador Motor 01x01x01





#### Model3 - Manibela Biela - Pas 5/5



1 X NutRH\_BU01.00x00.50



1 X Brace STR STD ERR BU08x01x00.25



2 X ScrewFL-RHRHD\_BU01.50



1 X Spacer FRE BU00.50x01.00 1 X Spacer FRE BU00.25x01.00



00



