
WT Repair Rework



Polish bore of shaft until groove is removed; if bore is larger than $\, \phi.321'', \,$ recommend replacing shaft. If larger than $\, \phi.325'', \,$ replace shaft. There may be some pitting in bore of shaft; some small pits are okay and do not have to be removed by polishing.

