
## **RPT Repair Rework**



Polish bore of shaft until groove is removed; if bore is larger than  $\, \phi.507''$ , recommend replacing shaft. If larger than  $\, \phi.511''$ , replace shaft. There may be some pitting in bore of shaft; some small pits are okay and do not have to be removed by polishing.

