THE TIMES, FRIDAY, MARCH 16, 2600

OPINION

Walta Aviation

The inquiry report into the ill-fated fight of a Piper Lance wireraft from Derba to Multa na Devember 3, 1996 has put the stance for the tragedy on mistaken decisions taken by Carmelo Martolo, pilot and owerer of the anceaft.

Pive passengers and the pilot diest in

showed that had the Department of Civil Aviation been adeequipment and staff, it could have quately equipped with the necessary surely prevented the tragady from tak-The report

ts fate on December 5 of that year.

ing place. The Djerba-Malta flight was not Sunaviation's first to be run on that route. Hundreds of flights were made by the single-engined Piper Lance since the company acquired the aircraft and registered it in Malta in 1990.

lished annually by Matta International Airport in the years before the accident A look at some of the statistics pubshould have alerted staff at the Department of Civil Aviation that all was not normal with Sunaviation's operations.

review, in 1993, the single-engined Piper Operating 189 flights and carrying 502 According to MIA's annual statistical rying 177 passengers. A year later, in Lance, 9HABU operated 71 flights car-1994, these numbers shot up dramatipassengers should have served as an craft, could, somehow, have been used on eyeopener that the single-engined aircally, to 189 flights and 502 passengers

It is true, as the report said, that the statistics and only Excelair appeared.

Netwithstanding this information, 10

grounded Excelair's aircraft for some tolo was allowed to continue flying his Piper Lance's flights and should have even should have noticed the frequency of the time, but it is still inexplicable how Bar-Piper Lance. Somebody, somewhere, And Warnings taken action immediately. SSME DCA statistics (in February 1995), the Piper months after the publication of MIA's sengers to Tunisia and Italy until it met The report stated: "On the strength of ation that Bartolo was making use of the aircraft (single-engined Piper Lance) Lance was still flying and carrying pasevidence collected there was a clear indi-

from the DCA because of what seems to The public deserves an explanation What action, if any, did the DCA take be a lack of control.

or the transportation of passengers for

reward, notwithstanding that Sunaviaion did not have the required air service

icence. Police investigations and other

The inquiry report also noted that Barolo, as managing director of Sunavia-

locuments on record confirm this fact.

fused and confused both companies to

ion and another air company, Excelair,

suit his purpose, particularly when Exce-

air faced difficulties"

Excelair had an air-taxi licence while

Sunaviation did not. One of the conditions for the issuing of an air-taxi licence is that the aircraft must be powered by

ties that the Piper Lance was being used Department of Civil Aviation "did not duct effective investigations of their own According to the inquiry report, the inform the aircraft manufacturer of the incident as required to do in terms of ICAO regulations"; and "failed to conwhen it should have known from statisfor the carriage of passengers?

These two shortcomings also deserve an explanation from the Department of into Bartolo's investigations

> craft, a Piper Navajo and ReimsCessna Caravan. The fusion and confusion of Ey alair and Sunaviation emerged in the b statistical review for 1995 when Shadistion, having done so well in

two engines. Excelair had two such air-

A that there should be a is the inquiry board's revision of licensing regulations obliging all pilots of Maltese-registered nircraft Civil Aviation recommenda revision of lice Also WOTEY

1994, disappeared altogether from the

to register their licences with the DCA

Carmel Attard

I don't think that it had to be a tragedy for this kind of recommendation to be Aireraff Registration was started 30 made, considering that the Maltuse (

National Accident Investigation Board and a revision be made of the Air Accident Regulations of 1956, probably formulated after the worst air disaster we had in Malta when an Avro York crashed on the cliffs of Wied iz-Zurrieg killing over 50 passengers and crew on board be set up, independently from the DCA, The beard also recommended that

the exigencies and efficiency required in of Civil Aviation, forming part of the I would add that the report by the board of inquiry regarding the disappearance of the Piper Lance has, perhaps indirectly, shown that the Department bureaucratic public service cannot meet earlier that year. in the 11 months before the tragedy

tion in Malta be regulated by qualified The DCA should be dismantled and regulatory powers in amation be passed on to a new Malta Aviation Authority set up on the same lines as foreign aviation authorities. Only in this way can aviastaff paid well for their responsibilities the industry of aviation. and specialisation.

A Malta Aviation Authority would become renowned for since its Leption complement the professiv that the Maka Internatio in February 1992.

an air-taxi service.