



FX0L | assembly FX0L

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 1

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FX0R | assembly FX0R

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 2

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FX1 | assembly FX1

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 3

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FX2 | assembly FX2

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 4

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FX3 | assembly FX3

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 5

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (-3.00, -39.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FBT | assembly FBT

Plywood 6 mm | tile 1/1, 1/2 | REV4 | page 6

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FBT | assembly FBT

Plywood 6 mm | tile 1/1, 2/2 | REV4 | page 7

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 225.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FBWR | assembly FBWR

Plywood 6 mm | tile 1/1, 1/2 | REV4 | page 8

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FBWR | assembly FBWR

Plywood 6 mm | tile 1/1, 2/2 | REV4 | page 9

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 225.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FBWL | assembly FBWL

Plywood 6 mm | tile 1/1, 1/2 | REV4 | page 10

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FBWL | assembly FBWL

Plywood 6 mm | tile 1/1, 2/2 | REV4 | page 11

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 225.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FBC | assembly FBC

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 12

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%





Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FMF | assembly FMF

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 13

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%



Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FMT | assembly FMT

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 14

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%





Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FMGR | assembly FMGR

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 15

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%





Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FMGL | assembly FMGL

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 16

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FNG1 | assembly FNG1

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 17

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FNG2 | assembly FNG2

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 18

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FNG3 | assembly FNG3

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 19

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FNG4 | assembly FNG4

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 20

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.




100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (-9.48, -100.43) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WLRI | assembly WLRI

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 22

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (-9.48, -100.43) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JF | assembly JF

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 23

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (-8.50, -50.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JB | assembly JB

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 24

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (-8.48, -50.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JLOW | assembly JLOW

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 25

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (-50.00, -15.15) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JTOP | assembly JTOP

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 26

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (-50.00, -15.15) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


TROOT | assembly TROOT

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 27

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (-9.15, -38.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


GLEG_L | assembly GLEG_L

Plywood 6 mm | tile 1/2, 1/1 | REV4 | page 28

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (-97.00, -77.00) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


GLEG_L | assembly GLEG_L

Plywood 6 mm | tile 2/2, 1/1 | REV4 | page 29

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (73.00, -77.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


GLEG_R | assembly GLEG_R

Plywood 6 mm | tile 1/2, 1/1 | REV4 | page 30

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (-97.00, -77.00) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


GLEG_R | assembly GLEG_R

Plywood 6 mm | tile 2/2, 1/1 | REV4 | page 31

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (73.00, -77.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


GLEG_N | assembly GLEG_N

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 32

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (-90.00, -8.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F09 | assembly FSL0

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 33

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F10 | assembly FSL0

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 34

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F11 | assembly FSL1

Foam 5 mm | tile 1/1, 1/2 | REV4 | page 35

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F11 | assembly FSL1

Foam 5 mm | tile 1/1, 2/2 | REV4 | page 36

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F12 | assembly FSL1

Foam 5 mm | tile 1/1, 1/2 | REV4 | page 37

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F12 | assembly FSL1

Foam 5 mm | tile 1/1, 2/2 | REV4 | page 38

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F13 | assembly FSL0

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 39

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F14 | assembly FSL0

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 40

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F15 | assembly FSL0

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 41

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F16 | assembly FSL1

Foam 5 mm | tile 1/1, 1/2 | REV4 | page 42

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F16 | assembly FSL1

Foam 5 mm | tile 1/1, 2/2 | REV4 | page 43

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F17 | assembly FSL1

Foam 5 mm | tile 1/1, 1/2 | REV4 | page 44

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F17 | assembly FSL1

Foam 5 mm | tile 1/1, 2/2 | REV4 | page 45

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F18 | assembly FSL1

Foam 5 mm | tile 1/1, 1/2 | REV4 | page 46

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F18 | assembly FSL1

Foam 5 mm | tile 1/1, 2/2 | REV4 | page 47

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F19 | assembly FSL2

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 48

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F20 | assembly FSL2

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 49

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F21 | assembly FSL2

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 50

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F22 | assembly FSL2

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 51

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F23 | assembly FSU2

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 52

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F24 | assembly FSU2

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 53

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F25 | assembly FSU1

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 54

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F26 | assembly FSU1

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 55

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F27 | assembly FSL3

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 56

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F28 | assembly FSL3

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 57

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F29 | assembly FSL3

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 58

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F30 | assembly FSL3

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 59

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_F33 | assembly FSL2

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 60

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WLIN_F01 | assembly WLIN

Foam 5 mm | tile 1/3, 1/2 | REV4 | page 61

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WLIN_F01 | assembly WLIN

Foam 5 mm | tile 2/3, 1/2 | REV4 | page 62

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (175.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WLIN_F01 | assembly WLIN

Foam 5 mm | tile 3/3, 1/2 | REV4 | page 63

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (345.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WLIN_F01 | assembly WLIN

Foam 5 mm | tile 1/3, 2/2 | REV4 | page 64

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WLIN_F01 | assembly WLIN

Foam 5 mm | tile 2/3, 2/2 | REV4 | page 65

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (175.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WLIN_F01 | assembly WLIN

Foam 5 mm | tile 3/3, 2/2 | REV4 | page 66

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (345.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WRIN_F02 | assembly WRIN

Foam 5 mm | tile 1/3, 1/2 | REV4 | page 67

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WRIN_F02 | assembly WRIN

Foam 5 mm | tile 2/3, 1/2 | REV4 | page 68

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (175.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WRIN_F02 | assembly WRIN

Foam 5 mm | tile 3/3, 1/2 | REV4 | page 69

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (345.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WRIN_F02 | assembly WRIN

Foam 5 mm | tile 1/3, 2/2 | REV4 | page 70

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WRIN_F02 | assembly WRIN

Foam 5 mm | tile 2/3, 2/2 | REV4 | page 71

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (175.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WRIN_F02 | assembly WRIN

Foam 5 mm | tile 3/3, 2/2 | REV4 | page 72

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (345.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WROUT_F03 | assembly WROUT

Foam 5 mm | tile 1/2, 1/3 | REV4 | page 73

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WROUT_F03 | assembly WROUT

Foam 5 mm | tile 2/2, 1/3 | REV4 | page 74

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (175.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WROUT_F03 | assembly WROUT

Foam 5 mm | tile 1/2, 2/3 | REV4 | page 75

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WROUT_F03 | assembly WROUT

Foam 5 mm | tile 2/2, 2/3 | REV4 | page 76

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (175.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WROUT_F03 | assembly WROUT

Foam 5 mm | tile 1/2, 3/3 | REV4 | page 77

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 455.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WROUT_F03 | assembly WROUT

Foam 5 mm | tile 2/2, 3/3 | REV4 | page 78

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (175.00, 455.00) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WLOUT_F04 | assembly WLOUT

Foam 5 mm | tile 1/2, 1/3 | REV4 | page 79

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WLOUT_F04 | assembly WLOUT

Foam 5 mm | tile 2/2, 1/3 | REV4 | page 80

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (175.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WLOUT_F04 | assembly WLOUT

Foam 5 mm | tile 1/2, 2/3 | REV4 | page 81

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WLOUT_F04 | assembly WLOUT

Foam 5 mm | tile 2/2, 2/3 | REV4 | page 82

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (175.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WLOUT_F04 | assembly WLOUT

Foam 5 mm | tile 1/2, 3/3 | REV4 | page 83

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 455.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_WLOUT_F04 | assembly WLOUT

Foam 5 mm | tile 2/2, 3/3 | REV4 | page 84

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (175.00, 455.00) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_TRF_F05 | assembly TRF

Foam 5 mm | tile 1/1, 1/2 | REV4 | page 85

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_TRF_F05 | assembly TRF

Foam 5 mm | tile 1/1, 2/2 | REV4 | page 86

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_TLF_F06 | assembly TLF

Foam 5 mm | tile 1/1, 1/2 | REV4 | page 87

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_TLF_F06 | assembly TLF

Foam 5 mm | tile 1/1, 2/2 | REV4 | page 88

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 230.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_TRF_F07 | assembly TRF

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 89

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


SKIN_TLF_F08 | assembly TLF

Foam 5 mm | tile 1/1, 1/1 | REV4 | page 90

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (5.00, 5.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FK_F | assembly FK_F

Plywood 6 mm | tile 1/1, 1/2 | REV4 | page 91

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FK_F | assembly FK_F

Plywood 6 mm | tile 1/1, 2/2 | REV4 | page 92

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 225.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FK_A | assembly FK_A

Plywood 6 mm | tile 1/1, 1/2 | REV4 | page 93

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FK_A | assembly FK_A

Plywood 6 mm | tile 1/1, 2/2 | REV4 | page 94

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 225.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FK_DL | assembly FK_DL

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 95

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FK_DR | assembly FK_DR

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 96

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FLL_F | assembly FLL_F

Plywood 6 mm | tile 1/1, 1/2 | REV4 | page 97

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FLL_F | assembly FLL_F

Plywood 6 mm | tile 1/1, 2/2 | REV4 | page 98

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 225.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FLL_A | assembly FLL_A

Plywood 6 mm | tile 1/1, 1/2 | REV4 | page 99

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FLL_A | assembly FLL_A

Plywood 6 mm | tile 1/1, 2/2 | REV4 | page 100

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 225.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FLL_DT | assembly FLL_DT

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 101

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FLL_DB | assembly FLL_DB

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 102

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FLR_F | assembly FLR_F

Plywood 6 mm | tile 1/1, 1/2 | REV4 | page 103

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.

Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FLR_F | assembly FLR_F

Plywood 6 mm | tile 1/1, 2/2 | REV4 | page 104

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 225.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FLR_A | assembly FLR_A

Plywood 6 mm | tile 1/1, 1/2 | REV4 | page 105

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%



Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FLR_A | assembly FLR_A

Plywood 6 mm | tile 1/1, 2/2 | REV4 | page 106

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 225.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FLR_DT | assembly FLR_DT

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 107

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FLR_DB | assembly FLR_DB

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 108

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


AR | assembly AR

Foam 5 mm | tile 1/2, 1/1 | REV4 | page 109

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


AR | assembly AR

Foam 5 mm | tile 2/2, 1/1 | REV4 | page 110

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%



Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


AL | assembly AL

Foam 5 mm | tile 1/2, 1/1 | REV4 | page 111

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


AL | assembly AL

Foam 5 mm | tile 2/2, 1/1 | REV4 | page 112

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


TRC | assembly TRC

Foam 5 mm | tile 1/2, 1/1 | REV4 | page 113

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


TRC | assembly TRC

Foam 5 mm | tile 2/2, 1/1 | REV4 | page 114

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


TLC | assembly TLC

Foam 5 mm | tile 1/2, 1/1 | REV4 | page 115

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


TLC | assembly TLC

Foam 5 mm | tile 2/2, 1/1 | REV4 | page 116

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FF1 | assembly FF1

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 117

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FF3 | assembly FF3

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 118

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FGPS | assembly FGPS

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 119

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FGPR | assembly FGPR

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 120

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FGPL | assembly FGPL

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 121

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FEQ | assembly FEQ

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 122

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FEC0 | assembly FEC0

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 123

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FEC1 | assembly FEC1

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 124

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FES0 | assembly FES0

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 125

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FES1 | assembly FES1

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 126

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FTM0 | assembly FTM0

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 127

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%



Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FTM1 | assembly FTM1

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 128

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%





Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FF0R | assembly FF0R

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 129

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%





Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FF0U | assembly FF0U

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 130

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%





Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FF0L | assembly FF0L

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 131

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FF2R | assembly FF2R

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 132

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FF2U | assembly FF2U

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 133

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


FF2L | assembly FF2L

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 134

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.




100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%



Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


TRS | assembly TRS

Plywood 6 mm | tile 2/2, 1/1 | REV4 | page 136

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


TLS | assembly TLS

Plywood 6 mm | tile 1/2, 1/1 | REV4 | page 137

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


TLS | assembly TLS

Plywood 6 mm | tile 2/2, 1/1 | REV4 | page 138

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


MTR | assembly MTR

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 139

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


MTL | assembly MTL

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 140

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCR_I | assembly LCR_I

Plywood 6 mm | tile 1/4, 1/1 | REV4 | page 141

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCR_I | assembly LCR_I

Plywood 6 mm | tile 2/4, 1/1 | REV4 | page 142

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCR_I | assembly LCR_I

Plywood 6 mm | tile 3/4, 1/1 | REV4 | page 143

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (340.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCR_I | assembly LCR_I

Plywood 6 mm | tile 4/4, 1/1 | REV4 | page 144

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (510.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCR_O | assembly LCR_O

Plywood 6 mm | tile 1/3, 1/1 | REV4 | page 145

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCR_O | assembly LCR_O

Plywood 6 mm | tile 2/3, 1/1 | REV4 | page 146

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCR_O | assembly LCR_O

Plywood 6 mm | tile 3/3, 1/1 | REV4 | page 147

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (340.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCR_DF | assembly LCR_DF

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 148

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCR_DA | assembly LCR_DA

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 149

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBR_I | assembly WBR_I

Plywood 6 mm | tile 1/2, 1/1 | REV4 | page 150

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBR_I | assembly WBR_I

Plywood 6 mm | tile 2/2, 1/1 | REV4 | page 151

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBR_O | assembly WBR_O

Plywood 6 mm | tile 1/3, 1/1 | REV4 | page 152

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBR_O | assembly WBR_O

Plywood 6 mm | tile 2/3, 1/1 | REV4 | page 153

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBR_O | assembly WBR_O

Plywood 6 mm | tile 3/3, 1/1 | REV4 | page 154

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (340.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBR_DF | assembly WBR_DF

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 155

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBR_DA | assembly WBR_DA

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 156

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCL_I | assembly LCL_I

Plywood 6 mm | tile 1/4, 1/1 | REV4 | page 157

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCL_I | assembly LCL_I

Plywood 6 mm | tile 2/4, 1/1 | REV4 | page 158

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCL_I | assembly LCL_I

Plywood 6 mm | tile 3/4, 1/1 | REV4 | page 159

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (340.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCL_I | assembly LCL_I

Plywood 6 mm | tile 4/4, 1/1 | REV4 | page 160

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (510.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCL_O | assembly LCL_O

Plywood 6 mm | tile 1/3, 1/1 | REV4 | page 161

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCL_O | assembly LCL_O

Plywood 6 mm | tile 2/3, 1/1 | REV4 | page 162

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCL_O | assembly LCL_O

Plywood 6 mm | tile 3/3, 1/1 | REV4 | page 163

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (340.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCL_DF | assembly LCL_DF

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 164

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


LCL_DA | assembly LCL_DA

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 165

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBL_I | assembly WBL_I

Plywood 6 mm | tile 1/2, 1/1 | REV4 | page 166

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBL_I | assembly WBL_I

Plywood 6 mm | tile 2/2, 1/1 | REV4 | page 167

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBL_O | assembly WBL_O

Plywood 6 mm | tile 1/3, 1/1 | REV4 | page 168

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBL_O | assembly WBL_O

Plywood 6 mm | tile 2/3, 1/1 | REV4 | page 169

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBL_O | assembly WBL_O

Plywood 6 mm | tile 3/3, 1/1 | REV4 | page 170

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (340.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBL_DF | assembly WBL_DF

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 171

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WBL_DA | assembly WBL_DA

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 172

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JR1 | assembly JR1

Plywood 6 mm | tile 1/2, 1/1 | REV4 | page 173

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JR1 | assembly JR1

Plywood 6 mm | tile 2/2, 1/1 | REV4 | page 174

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JR2 | assembly JR2

Plywood 6 mm | tile 1/2, 1/1 | REV4 | page 175

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JR2 | assembly JR2

Plywood 6 mm | tile 2/2, 1/1 | REV4 | page 176

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JR3 | assembly JR3

Plywood 6 mm | tile 1/2, 1/1 | REV4 | page 177

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JR3 | assembly JR3

Plywood 6 mm | tile 2/2, 1/1 | REV4 | page 178

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JL1 | assembly JL1

Plywood 6 mm | tile 1/2, 1/1 | REV4 | page 179

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JL1 | assembly JL1

Plywood 6 mm | tile 2/2, 1/1 | REV4 | page 180

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JL2 | assembly JL2

Plywood 6 mm | tile 1/2, 1/1 | REV4 | page 181

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JL2 | assembly JL2

Plywood 6 mm | tile 2/2, 1/1 | REV4 | page 182

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JL3 | assembly JL3

Plywood 6 mm | tile 1/2, 1/1 | REV4 | page 183

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


JL3 | assembly JL3

Plywood 6 mm | tile 2/2, 1/1 | REV4 | page 184

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%





Tile origin: (170.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WRRM_1 | assembly WRRM_1

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 185

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WRRM_2 | assembly WRRM_2

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 186

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WRRO_1 | assembly WRRO_1

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 187

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WRRO_2 | assembly WRRO_2

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 188

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WLRM_1 | assembly WLRM_1

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 189

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WLRM_2 | assembly WLRM_2

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 190

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%




Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WLRO_1 | assembly WLRO_1

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 191

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%





Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.


WLRO_2 | assembly WLRO_2

Plywood 6 mm | tile 1/1, 1/1 | REV4 | page 192

Solid lines: CUT. Orange dashed lines: bevel/score reference; do not cut through.



100 mm CHECK BAR - print at actual size / 100%



Tile origin: (0.00, 0.00) mm. Overlap: 10 mm. Align matching outline in overlap.
Turn off Fit/Shrink. Measure the bar before cutting. Read the assembly and grain instructions.