

glasstech, inc.

Service Bulletin

Customer Service Department

TELEPHONE: 419-661-9000 FAX: 419-661-9639

INTERNET: <http://www.glasstech.com>

E-mail: service@glasstech.com

FCH Burner Circuit Modification

Reference 021

In the event of an over-temperature limit burner shutdown, the current configuration of the burner circuit allows possible re-light of the system with the air valve still in the high fire (zone temperature control) position, since it takes several seconds for this valve to close down to the initial light-off position.

A time delay relay needs to be added to the circuit of each burner to prevent an attempted re-light of the burner until the air valve has had enough time to close to the light-off position.

A kit is being forwarded to the affected customers to be installed as soon as possible. This kit includes time delay relays and drawings.

Install the relay inside the panel door as noted on the drawings and wire them as specified on the drawings. Be sure to apply the joint compound paste that's included between the back of the relay and the door.

For any questions contact Glasstech.