

glasstech, inc.

Service Bulletin

Customer Service Department

TELEPHONE: 419-661-9000 FAX: 419-661-9639

INTERNET: <http://www.glasstech.com>

E-mail: service@glasstech.com

Forced Convection Furnace (FCH2) Burner Combustion Safety Circuit Modification

Reference 025

Startup operation of the Forced Convection Furnace gas burner combustion system could result in high intermittent currents within the combustion safety circuit. These high intermittent currents could stress components of the safety circuit, with the possible result of premature component failure. To minimize this possibility, Glasstech has modified the safety circuit to incorporate an additional relay for the purpose of safely conducting any current drawn during operation of the system. Revised schematic drawings of the gas panel circuitry and the necessary relay for this modification will be shipped to each affected furnace for field installation.

If any questions occur regarding this modification or its implementation, please contact the Glasstech Customer Service Department at the numbers listed above.