

glasstech, inc.

Service Bulletin

Customer Service Department

TELEPHONE: 419-661-9000 FAX: 419-661-9639

INTERNET: <http://www.glasstech.com>

E-mail: service@glasstech.com

Galil 700 Series Multi-Axis Motion Controller Replacement For Bender Axis Control

Reference 028

The Galil 700 Series Motion Controller as used on bender section axis control for mold lift and ring shuttles is no longer available. As replacements are needed, these systems will need to be retrofitted with Galil 1500 Series motion controllers. These two components are compatible but require subtle differences in their implementation, such as wiring. Because the 700 Series units are obsolete and unsupported by their manufacturer, we strongly urge consideration of retrofitting the newer 1500 Series units before unplanned downtime occurs. In order to assure a smooth installation, please contact Glasstech Aftermarket Sales Department for retrofit quotation information on fitting these replacement motion controllers to your furnace.

If any technical questions occur regarding the new units or their implementation, please contact the Glasstech Customer Service Department at the numbers listed above.