

glasstech, inc.

Service Bulletin

Customer Service Department

TELEPHONE: 419-661-9000 FAX: 419-661-9639

INTERNET: <http://www.glasstech.com>

E-mail: service@glasstech.com

Pacific Scientific Motion Controller Replacement For Shuttle Doors and Wing Wrap Actuators

Reference 029

The Pacific Scientific Motion Controller as used on bender section shuttle doors and Deep Bend IV wing wrap actuators is no longer available. As replacements are needed, these systems will need to be retrofitted with Galil 1500 series motion controllers and Allen Bradley motors. These components are compatible with the Glasstech mechanical and control systems. Because these units are obsolete and unsupported by their manufacturer, we strongly urge consideration of retrofitting the newer devices before unplanned downtime occurs. In order to assure a smooth installation, please contact Glasstech Aftermarket Sales Department for retrofit quotation information on fitting these replacement components to your furnace.

If any technical questions occur regarding the new components or their implementation, please contact the Glasstech Customer Service Department at the numbers listed above.