

glasstech, inc.

Service Bulletin

Customer Service Department

TELEPHONE: 419-661-9000 FAX: 419-661-9639

Glasstech SCR Heating Controllers

Reference 004

Glasstech supplied SCR heating controllers (part numbers E-RRL4CSSAAA481 and E-RRL4CSSAAA482) used in place of mercury contactors are fitted with two correctly rated 63 amp fast acting fuses in parallel. The SCR manufacturer has advised Glasstech that in the event of these controllers blowing fuses on a frequent basis, the fuses can be replaced in pairs with 80 FE Fast Acting fuses without degrading the safety of the circuit.

These fuses may be obtained from Glasstech, Inc., or from Glasstech Limited at a cost of 19.05 US Dollars per fuse, plus freight and handling.

If you experience such frequent fuse failures, Glasstech would ask that you collect the following information to aid in the manufacturer identifying the root cause of these nuisance fuse failures:

1. The time and date that each fuse failure occurred or was discovered.
2. The zone and element number of the SCR heating controller that underwent the failure. An alternative identification is the element wire number affixed to the large wire connected to the bottom of the SCR controller, and prefixed with a Z.
3. Periodic surface temperature readings of each fuse, or millivolt drop across each fuse while the SCR heating controller is conducting. The fuses may be identified as left or right fuses associated with the units identified in the manner noted in 2. above. This information will be especially useful if taken near the end of full power heat-up or heavy production.
4. Current readings for the individual furnace elements, taken with a digital clamp-on meter, and identified as in 2. above.

If you have any questions on this or any other matters, please do not hesitate to contact Glasstech Customer Service.