

Service Bulletin

Customer Service Department

TELEPHONE: 419-661-9000 FAX: 419-661-9639

INTERNET: <http://www.glasstech.com>

Belt Driven Hot Fan Replacement

Reference #040

For those customers that are currently using belt driven hot fans and are replacing them with direct drive hot fans the following conditions should be observed:

- The original belt driven hot fans have (4) pole motors, the new direct drive hot fans have (2) pole motors.
- The original belt driven hot fans have a motor drive shaft to fan shaft speed ratio due to the drive belt configuration. For the direct drive hot fans, the motor drive shaft and the fan speed are the same.
- Due to the aforementioned differences the following drive parameters may require modification:
 - o Motor Name Plate RPM
 - o Motor Name Plate Hertz
 - o Motor Name Plate Volts
 - o Motor Name Plate Amp
 - o Maximum Speed 54.3 Hz (same as Max. Freq.)
 - o Motor Poles 2
 - o Accel Time [1] 10 sec
 - o Accel Time [2] 10 sec
 - o Decel Time [1] 10 sec
 - o Decel Time [2] 10 sec
 - o Minimum Frequency 7 Hz
 - o Maximum Frequency 54.3 Hz (same as Max. Speed)
- Consult the manufacturer's drive manual for information on changing parameter values.
- Glasstech part number for the affected hot fans are:
 - o **Belt Driven:** 053N-210-P040-D & 053N-220-P034-D
 - o **Direct Drive:** S-FAN7HDF6F0B71, S-FANPHDF6F0B71,
 S-FANPHDF6G0C41 & S-FANPHDF6H0C11