

Service Bulletin

Customer Service Department

TELEPHONE: 419-661-9000 FAX: 419-661-9639

INTERNET: <http://www.glasstech.com>


Epson LQ-570 Printers

Reference #041

The Epson LQ-570 printer driver will cause excessive amounts of Virtual Memory usage after four or more hours of continuous usage. Windows® by default does not set the Utility Manager to Automatic. The following procedure outlines the sets necessary to configure the Utility Manager to prevent the excessive use of Virtual Memory.

- Using Windows Explorer, go the following:
C:\Documents and Settings\All Users\Start Menu\Programs\Startup

- You should see the Epson Status Monitor Shortcut. If you do not, please re-load the Epson printer driver from the original CD that came with your printer.



- Using Explorer go to:
Control Panel \ Administrative Tools\ Services
 - Under the Name Bar, scroll down to:
Utility Manager.
 - Right click on Utility Manager, using the mouse, and select properties.
 - If the Utility Manager is not set to Automatic, change the Startup type to Automatic.
 - Select Apply, to save the change.
 - Restart Computer.

