

Plaza Infiniti

***** Automobile Status Report

Prepared For



MATTEO CIRAMI

6362848381 mcirami@gmail.com

2013 Infiniti G37x

Date April 04, 2018

VIN JN1CV6AR1DM358157

Mileage 30271

RO# 242165

Service Advisor

Jim Kennedy jkennedy@plazamotors.com 314-919-8391

> **Plaza Infiniti** 11830 Olive Blvd Creve Coeur, MO 63141

Plaza Infiniti Service Commitment

Excellence at every turn... and every straightaway

Our dealership's primary goal is to make every visit to our store truly exceptional. You visit our service department regularly, and we have developed a number of ways to make your visit more comfortable and informative. We know that you want straight answers, and that's the only way we will deliver it to you.

We understand that your knowledge of your vehicle and its necessary repairs is probably not on par with the understanding that your technician has. In order to be sure that his findings and reporting is as clear and concise as possible, we use this Vehicle Information Booklet as a tool to help us communicate your vehicle's condition to you.

Our technicians are the most qualified to work on your vehicle. They have trained extensively, and partake in continuing education regularly to be sure that they are up to date on any changes and improvements handed down from the manufacturer. Our service advisors strive to make your experience with us truly exceptional. They are here to attend to your automotive needs as well as communicate effectively between your technician and you.

Please make yourself comfortable in our waiting area. Watch some TV, use your laptop with our free WI-FI access or just relax and enjoy the quiet. Our courtesy shuttle can take you home if you prefer.

We appreciate your business and will continue to strive for excellence in everything we do for you. If for any reason you don't feel that every visit is truly exceptional, please let us know immediately.

Multi-Point Inspection Form

RO# 242165 **MATTEO CIRAMI**

VIN JN1CV6AR1DM358157

Requires immediate attention

Advisor Jim Kennedy **Technician** Shawn Wiegand Created On 4/4/2018 9:04 AM

Checked and OK at this time	e May Require Future Attention
Interior / Ext	erior
Bulbs and Lights	Sh
Windshield Washer Spra / Wiper Blades / Includin	
Windshield / Window Co	ndition Mi
Upholstery / Carpet / Flo Trim	
Emergency Brake Adjust	tment U-
Horn Operation	Tra
Fuel Tank Cap Gasket	(CI
Clutch Operation (if equ	Le lipped)
Cabin/HEPA Filter (if equ	
Under Hoo	od Ins
Fluids: Oil / Coolant / Pov Fluid / Washer	ver Steering / Brake
Engine Air Filter	
Belts / Tensioners (condi	tion and
Cooling System Hoses / F	Heater Hoses / Air
Radiator Core / Air Cond (if equipped)	LR
Battery Perform	mance A
Battery Terminals / Cable	
Check Condition of Batte	l I RE

Test if Applicable)

uture Attern	Requires infinediate attention
	Under Vehicle
	Shock Absorbers / Suspension
	Steering Gear Box / Linkage and Boots / Ball Joints / Dust Covers
	Muffler / Exhaust Pipes / Mountings
	Engine Oil and/or Fluid Leaks
	Drive Shaft Boots / Constant Velocity Boots / U-joints / Transmission Linkage (if equipped)
	Transmission / Differential / Transfer Case (Check Fluid Level, Fluid Condition and Fluid Leaks)
	Fuel Lines and Connections / Fuel Tank Band / Fuel Tank Vapor Vent System Hoses
	Inspect Nuts and Bolts on Body Chassis
	Tread Depth (measured in 1/32")
2000	
	LF <u>4, 5</u>
	RF <u>4, 5</u>
	LR <u>4, 5</u>
	RR <u>4</u>
	Abnormal Wear Pattern of Tires
	LF
	RF
	LR
	RR
Checl	k Brake Linings (measured in millimeters)
	LF <u>7, 8</u>
	RF <u>7, 8</u>
	LR <u>6</u>
	RR <u>6</u>

Additional Service Recommendations

Red: requires immediate attention.

In the process of inspecting your vehicle for safety and reliability, your technician **Shawn W** made the following observations and recommends that you do the necessary repairs to resolve these issues.

Yellow: in need of attention soon.

Fuel Induction Service

Item Description

This service increases fuel economy, reduces emissions, and restores lost power. A specialized tool applies a combination of highly effective cleaners to do a complete and thorough cleaning of deposits from the fuel injectors, fuel lines, and intake valves and ports. Complete removal of combustion chamber deposits corrects the necessary balance of fuel and air needed for optimal performance and improved throttle response.



Tires - 4: HANKOOK TIRES P225-55R17

Item Description

A tire is a round component made of rubber and reinforced with chords or belts made of several choices of materials. The tire is filled with air or nitrogen and surrounds a wheel's rim to transfer a vehicle's load from the axle through the wheel to the ground and to provide traction on the road's surface. With only four small contact patches between you and the road you want them to be as good as they can possibly be.

Reason

According to most states' laws, tires are legally worn out when they have worn down to 2/32" of remaining tread depth. As a tire wears it's important to realize that the tire's ability to perform in rain and snow will be reduced. With 2/32" of remaining tread depth, resistance to hydroplaning in the rain at highway speeds has been significantly reduced, and traction in snow has been virtually eliminated.





Tires

If rain and wet roads are a concern, you should consider replacing your tires when they reach approximately 4/32" of remaining tread depth.

If snow-covered roads are a concern, you should consider replacing your tires when they reach approximately 6/32" of remaining tread depth to maintain good mobility. Because tread depth is such an important element for snow traction, winter tires usually start with noticeably deeper tread depths than typical All-Season or summer tires. Some winter tires even have a second series of "wear bars" molded in their tread pattern indicating approximately 6/32" remaining tread depth to warn you when your tires no longer meet the desired tread depth.

Alignment

Item Description

Alignment is one of the key maintenance factors in getting the most tread life and performance from your tires. In addition, wheel alignment provides safe, predictable vehicle control as well as a smooth and comfortable ride that's free of pulling or vibration. Today's modern suspensions require a precise four-wheel alignment that can only be achieved through a modern alignment system. This applies to both front and rear wheel drive vehicles. Aligning a car or truck involves the adjustment of the vehicle's suspension, not the tires and wheels. The direction and the angles that the tires point in after the alignment is complete, however, are critically important. There are four factors involved in setting the alignment to specification: caster, camber, toe and ride height.

Reason

If not done, you will see uneven or rapid tire wear, pulling or drifting away from a straight line, and wandering on a straight level road. It can also cause extra load on certain suspension components, making them more likely to fail.





Alignment

Repair Estimate

Service Advisor Jim Kennedy (500759) jkennedy@plazamotors.com 314-919-8391

PREPARED FOR MATTEO CIRAMI

(225) 731-1682

Date 04/04/2018 10:19 AM 2013 INFINITI G37x VIN JN1CV6AR1DM358157 Mileage 30,271 RO# 242165

Service Name	Price
[Primary]: EN001: C/S: SEEMS TO BE LOSING FUEL FASTER THEN IT SHOULD. HAVEN'T NOTICED ANY DRIPS ANYWHERE. ESPECIALLY WHEN IT SHOWS AROUND A QUARTER TANK LEFT, THE NEXT TIME I GET IN THE CAR ALL OF A SUDDEN THE FUEL LIGHT IS ON AND THE NEEDLE IS ON EMPTY.	0.00
[Primary]: MULTI : PERFORM MULTI POINT INSPECTION	0.00
[Primary]: VPS035 : VALVOLINE TRANSMISSION FLUSH	201.11
[Primary]: MA23 : Fluid, Differential (Front) - Replace	117.04
[Primary]: MA24 : Fluid, Differential (Rear) - Replace	101.14
[Primary]: RAINX : INSTALL INFINITI MAINTENANCE ADVANTAGE WIPERS	
Fuel Induction Service	161.27
Tires - 4: HANKOOK TIRES P225-55R17	607.20
Alignment	114.95
Printed on April 04, 2018	
Quote expires on June 03, 2018	

Total	1498.49
Tax	68.7
Shop Charges	75.0
Subtotal	1354.7