Turbine ID#: Manufacturer/Model:

# Tower Defect Summary (Base Tower)

Weld Count	0°	90°	180°	270°
1	T123 _s_1 _w_1_1.png	T123 _s_2 _w_1_2.png	T123 _s_3 _w_1_3.png	T123 _s_4 _w_1_1.png
2	T123 _s_1 _w_2_1.png	T123 _s_2 _w_2_1.png	T123 _s_3 _w_2_1.png	T123 _s_4 _w_2_1.png
3	T123 _s_1 _w_3_1.png	T123 _s_2 _w_3_1.png	T123 _s_3 _w_3_1.png	T123 _s_4 _w_3_1.png
4	T123 _s_1 _w_4_1.png	T123 _s_2 _w_4_1.png	T123 _s_3 _w_4_1.png	T123 _s_4 _w_4_1.png
5	T123 _s_1 _w_5_1.png	T123 _s_2 _w_5_1.png	T123 _s_3 _w_5_1.png	T123 _s_4 _w_5_1.png
6	T123 _s_1 _w_6_1.png	T123 _s_2 _w_6_1.png	T123 _s_3 _w_6_1.png	T123 _s_4 _w_6_2.png
7	T123 _s_1 _w_7_1.png	T123 _s_2 _w_7_1.png	T123 _s_3 _w_7_1.png	T123 _s_4 _w_7_1.png
8	T123 _s_1 _w_8_1.png	T123 _s_2 _w_8_1.png	T123 _s_3 _w_8_1.png	T123 _s_4 _w_8_1.png
9	T123 _s_1 _w_9_1.png	T123 _s_2 _w_9_3.png	T123 _s_3 _w_9_1.png	T123 _s_4 _w_9_1.png
10	T123 _s_1 _w_10_1.png	T123 _s_2 _w_10_1.png	T123 _s_3 _w_10_1.png	T123 _s_4 _w_10_1.png
11	T123 _s_1 _w_11_1.png	T123 _s_2 _w_11_1.png	T123 _s_3 _w_11_3.png	T123 _s_4 _w_11_1.png
12	T123 _s_1 _w_12_1.png	T123 _s_2 _w_12_1.png	T123 _s_3 _w_12_1.png	T123 _s_4 _w_12_1.png
13	T123 _s_1 _w_13_1.png	T123 _s_2 _w_13_1.png	T123 _s_3 _w_13_1.png	T123 _s_4 _w_13_1.png
14	T123 _s_1 _w_14_1.png	T123 _s_2 _w_14_1.png	T123 _s_3 _w_14_1.png	T123 _s_4 _w_14_1.png
15	T123 _s_1 _w_15_1.png	T123 _s_2 _w_15_1.png	T123 _s_3 _w_15_1.png	T123 _s_4 _w_15_1.png

# Tower Defect Summary (Mid Tower)

Weld Count	0°	90°	180°	270°
1	<b>♥</b> T123 _s_1 _w_1_1.png	T123 _s_2 _w_1_2.png	T123 _s_3 _w_1_3.png	T123 _s_4 _w_1_1.png
2	<b>♥</b> T123 _s_1 _w_2_1.png	T123 _s_2 _w_2_1.png	T123 _s_3 _w_2_1.png	T123 _s_4 _w_2_1.png
3	<b>♥</b> T123 _s_1 _w_3_1.png	T123 _s_2 _w_3_1.png	T123 _s_3 _w_3_1.png	T123 _s_4 _w_3_1.png
4	T123 _s_1 _w_4_1.png	T123 _s_2 _w_4_1.png	T123 _s_3 _w_4_1.png	T123 _s_4 _w_4_1.png
5	<b>♥</b> T123 _s_1 _w_5_1.png	T123 _s_2 _w_5_1.png	T123 _s_3 _w_5_1.png	T123 _s_4 _w_5_1.png
6	<b>♥</b> T123 _s_1 _w_6_1.png	T123 _s_2 _w_6_1.png	T123 _s_3 _w_6_1.png	T123 _s_4 _w_6_2.png
7	<b>♥</b> T123 _s_1 _w_7_1.png	T123 _s_2 _w_7_1.png	T123 _s_3 _w_7_1.png	T123 _s_4 _w_7_1.png
8	<b>♥</b> T123 _s_1 _w_8_1.png	T123 _s_2 _w_8_1.png	T123 _s_3 _w_8_1.png	T123 _s_4 _w_8_1.png
9	<b>♥</b> T123 _s_1 _w_9_1.png	T123 _s_2 _w_9_3.png	T123 _s_3 _w_9_1.png	T123 _s_4 _w_9_1.png
10	T123 _s_1 _w_10_1.png	T123 _s_2 _w_10_1.png	T123 _s_3 _w_10_1.png	T123 _s_4 _w_10_1.png
11	T123 _s_1 _w_11_1.png	T123 _s_2 _w_11_1.png	T123 _s_3 _w_11_3.png	T123 _s_4 _w_11_1.png
12	T123 _s_1 _w_12_1.png	T123 _s_2 _w_12_1.png	T123 _s_3 _w_12_1.png	T123 _s_4 _w_12_1.png
13	T123 _s_1 _w_13_1.png	T123 _s_2 _w_13_1.png	T123 _s_3 _w_13_1.png	T123 _s_4 _w_13_1.png
14	T123 _s_1 _w_14_1.png	T123 _s_2 _w_14_1.png	T123 _s_3 _w_14_1.png	T123 _s_4 _w_14_1.png
15	T123 _s_1 _w_15_1.png	T123 _s_2 _w_15_1.png	T123 _s_3 _w_15_1.png	T123 _s_4 _w_15_1.png

Turbine ID#:
Manufacturer/Model:

# Tower Defect Summary (Top Tower)

Weld Count	0°	90°	180°	270°
1	T123 _s_1 _w_1_1.png	T123 _s_2 _w_1_2.png	T123 _s_3 _w_1_3.png	T123 _s_4 _w_1_1.png
2	T123 _s_1 _w_2_1.png	T123 _s_2 _w_2_1.png	T123 _s_3 _w_2_1.png	T123 _s_4 _w_2_1.png
3	T123 _s_1 _w_3_1.png	T123 _s_2 _w_3_1.png	T123 _s_3 _w_3_1.png	T123 _s_4 _w_3_1.png
4	T123 _s_1 _w_4_1.png	T123 _s_2 _w_4_1.png	T123 _s_3 _w_4_1.png	T123 _s_4 _w_4_1.png
5	T123 _s_1 _w_5_1.png	T123 _s_2 _w_5_1.png	T123 _s_3 _w_5_1.png	T123 _s_4 _w_5_1.png
6	T123 _s_1 _w_6_1.png	T123 _s_2 _w_6_1.png	T123 _s_3 _w_6_1.png	T123 _s_4 _w_6_2.png
7	T123 _s_1 _w_7_1.png	T123 _s_2 _w_7_1.png	T123 _s_3 _w_7_1.png	T123 _s_4 _w_7_1.png
8	T123 _s_1 _w_8_1.png	T123 _s_2 _w_8_1.png	T123 _s_3 _w_8_1.png	T123 _s_4 _w_8_1.png
9	T123 _s_1 _w_9_1.png	T123 _s_2 _w_9_3.png	T123 _s_3 _w_9_1.png	T123 _s_4 _w_9_1.png
10	T123 _s_1 _w_10_1.png	T123 _s_2 _w_10_1.png	T123 _s_3 _w_10_1.png	T123 _s_4 _w_10_1.png
11	<b>⊘</b> T123 _s_1 _w_11_1.png	T123 _s_2 _w_11_1.png	T123 _s_3 _w_11_3.png	T123 _s_4 _w_11_1.png
12	<b>⊘</b> T123 _s_1 _w_12_1.png	T123 _s_2 _w_12_1.png	T123 _s_3 _w_12_1.png	T123 _s_4 _w_12_1.png
13	<b>⊘</b> T123 _s_1 _w_13_1.png	T123 _s_2 _w_13_1.png	T123 _s_3 _w_13_1.png	T123 _s_4 _w_13_1.png
14	<b>⊘</b> T123 _s_1 _w_14_1.png	T123 _s_2 _w_14_1.png	T123 _s_3 _w_14_1.png	T123 _s_4 _w_14_1.png
15	<b>♥</b> T123 _s_1 _w_15_1.png	T123 _s_2 _w_15_1.png	T123 _s_3 _w_15_1.png	T123 _s_4 _w_15_1.png

Wind Farm Location:

Site Manager:

Turbine ID#: Manufacturer/Model:

### Tower Identification Guide Red

- Compare identified defects to common defects in identification guide
  If identified defect does not match any common defects, estimate severity or contact blade repair company
  Reference Defect Severity Guide to determine risk assessment

### Serious Damages



Serious damages, actions need to be taken right away.