

TECHNICAL BULLETIN 2021-04-04

TB-00004-External


Туре	Dryers cover tightening torque - Operator instructions
Technical support	Niko Ojapalo
Heat pump types	P, RE & S series

DESCRIPTION

Castel dryer cover tightening at operation

If the operation temperatures of heat pump are relatively high, it can lead that after a while (after x amounts of running and stops / cold to hot) the dryers cover might come a bit loose and cause small leak. Therefore, is recommended that operator follow at inspections that cover tightening stays at 31 Nm. If the cover stays at recommended tightness without re tightening, good. If due to the operation temperatures and start stop cycle requires re-tightening interwall, then can be added to the regular inspection list.

Coppie serraggio / Wrenching Torque:



Serraggio incrociato a 180° / Cross-tighten the bolts at 180°

FILTRI/FILTERS
4411/..A - B - A4
4412/..A - B
4414/..A - B - AF

As sealing is changed as changing the dryers rocks, it is recommended to use the original green sealing. It is not recommended to use the thin sealing that comes with some dryer's rocks. That might cause refrigerant leakage at use.

As also, it is recommended to use oil at installation of new sealing to the cover. The oil decreases the possibility of incorrect assembly. When the gasket is greased, it will improve its adhesion and elasticity, and adhere better to the surfaces.

Suggerimenti d'installazione / Installation tips:



Oilon Oy Street address: Metsä-Pietilänkatu 1 Postal code: 15800 City: Lahti Country: Finland Phone: +358 3 85 761 E-mail: info@oilon.com Business ID: F127344313 Oilon US Inc. Street address: 91 Genesis Parkway 31799(mail), 31792(visitors) City: Thomasville, Georgia Country: United States Phone: +1 229 236 6546 E-mail: info@oilon.com Business ID: OOO Oilon Russia
Street address:
Tallinskoe (Staro-Panovo)
shosse 206 Letter 206 A room 1-H
Postal code: 198205
City: St. Petersburg
Country: Russia
Phone: +7 812 449 0265
E-mail: spboffice@oilon.com
Business ID:

Oilon Brasil Energia Ltda.
Street address:
Rua José Maria Barbosa
31. Salas 181-182, Jd. Portal da Colina
Postal code: 18047-380
City: Sorocaba , São Paulo
Country: Brasil
Phone: +55 15 3228 4600
E-mail: southamerica@oilon.com
Business ID:14.565.710/0001-73

Oilon Burners (Wuxi) Co. Ltd.
Street address:
No. 111-3, Xi Mei Road,
Wuxi, Wuxi development zone
Postal code: 214142
City: Wuxi Jiangu Province
Country: China
Phone: +86 510 8534 2010
E-mail: info@oilon.com
Business ID: