

Tolerances:
$.000X = \pm .001$
$.000 \times = +.002$
0X = +.003

T)	(	Ŋ		E		43	S		1	V
- Abr	Ш	N	1	9	Ε	R	S	1	T	γ

## Clemson University Physics and Astronomy Research Lab

Part: CRS-Bottom Plate	<b>Description:</b> X-Ray Cabinet								
Material: AISI 1020 - Cold Rolled	<b>Date:</b> 7/9/2015								
Drawn By: Alexander Sheldon	Scale: 1:4								