Single Stage Rocket Launch Checklist

1.	Equipment inventory:				
		Motors:			
		11.	Estes F-15-4		
		12.	Aerotech F-67-4		
		Igniters			
		Parachute	2S		
		11.	Nylon (36,48,58)"		
		12.	30" Dino Chutes		
		Recovery	Wadding		
		Kevlar Sh	ock Chord		
		Tools:			
		11.	Long Needle Nose P	liers	
		12.	Screwdriver		
		13.	Sandpaper		
		14.	Scissors		
		Launch St	and		
		Launch Co	Controller		
		Batteries	Batteries(D-Cells)		
		Electroni	Electronics Bay Dummy Payload (Equivalent Weight of Electronics Bay)		
		Duct Tape	-	- J	
		Masking T			
		Hasking i	ape		
			lkhead and secure		
		screws	1 1 1 1 1 1 1		
3. Tie shock chord to bulkhead					
-	eyebolt and motor mount eyebolt 4. Attach parachute swivel and				
	quick link				
			achute to quick		
	ink		-		
			very wadding in		
		er body	pody		
			to position		
<pre>wadding all around shock chord 7. Fold parachute</pre>					
_			nute ock chord and		
		ce into lov			
			chute into lower		