Calibration checkerboard - 10 mm squares - 9 x 6 inner corners



PRINT AT 'ACTUAL SIZE' / 100% (NOT 'fit to page'), laser printer, matte paper.
Then MEASURE 9 squares (90 mm) with a vernier and enter (measured / 9) as square size.
Glue flat on a rigid board (acrylic/aluminium). Any bend or wrinkle = wrong scale.
In the software: Calibration > corners across = 9, down = 6.
For production accuracy, a glass/ceramic checkerboard (certified) is recommended.
Note: on a backlight the paper becomes transparent - switch backlight OFF and use room light for checkerboard calibration, or use an opaque printed board.

Check print: this ruler must be exactly 100 mm