

Technical Requirements:

- 1. Surface of samples should be smooth enough without cracks.
- 2. The R10 arc at two ends, and the  $\Phi10$  section should be smooth,
- it should be produced by CNC lathes by one time.
- 3. The same batch of samples should be produced by same material.
- 4. Surface of the samples should not be processed by any means.

											- 美特斯工业系统(中国)有限公司
标记 设 计	 分区	更改文件号标准化	签 名	年、月、日		7Å Ľ11	l= \-	1	¥ E	11. /51	扭转试样(φ10)
		W. H			ļ	<b>介</b> 段	标i	١	重量	比 例	
审 核					S					1:1.5	
工艺		批准				共	张		第	张	