MAIN-C1 | 1:1 planar template

CB01 | R005 reference geometry | millimeters | 2026-10-15

PRINT AT 100% / ACTUAL SIZE. Disable fit-to-page. Verify BOTH 100 mm bars before use. Dashed circle = factory-cover reference; solid contours = custom plate. Lines are reference marks, not extra cut paths.



Record: date _____ measured horizontal _____ vertical _____ mm

Trace the real rear foam inner/outer edges and mark any overlap with the aperture. Mark cover center, gouges, unsupported spans and interference.

Paper checks planar relationships only; it cannot prove thickness, compression, stiffness, handle engagement or water performance.

100 mm horizontal check

DIV-C1 | 1:1 planar template

CB01 | R005 reference geometry | millimeters | 2026-10-15

PRINT AT 100% / ACTUAL SIZE. Disable fit-to-page. Verify BOTH 100 mm bars before use. Dashed circle = factory-cover reference; solid contours = custom plate. Lines are reference marks, not extra cut paths.



Record: date _____ measured horizontal _____ vertical _____ mm

Trace the real rear foam inner/outer edges and mark any overlap with the aperture. Mark cover center, gouges, unsupported spans and interference.

Paper checks planar relationships only; it cannot prove thickness, compression, stiffness, handle engagement or water performance.

100 mm horizontal check

MAIN-C2 | 1:1 planar template

CB01 | R005 reference geometry | millimeters | 2026-10-15

PRINT AT 100% / ACTUAL SIZE. Disable fit-to-page. Verify BOTH 100 mm bars before use. Dashed circle = factory-cover reference; solid contours = custom plate. Lines are reference marks, not extra cut paths.



Record: date _____ measured horizontal _____ vertical _____ mm

Trace the real rear foam inner/outer edges and mark any overlap with the aperture. Mark cover center, gouges, unsupported spans and interference.

Paper checks planar relationships only; it cannot prove thickness, compression, stiffness, handle engagement or water performance.

100 mm horizontal check

DIV-C2 | 1:1 planar template

CB01 | R005 reference geometry | millimeters | 2026-10-15

PRINT AT 100% / ACTUAL SIZE. Disable fit-to-page. Verify BOTH 100 mm bars before use. Dashed circle = factory-cover reference; solid contours = custom plate. Lines are reference marks, not extra cut paths.



Record: date _____ measured horizontal _____ vertical _____ mm

Trace the real rear foam inner/outer edges and mark any overlap with the aperture. Mark cover center, gouges, unsupported spans and interference.

Paper checks planar relationships only; it cannot prove thickness, compression, stiffness, handle engagement or water performance.

100 mm horizontal check