

DC Motor	Servo Motor	Stepper Motor
Continuous rotation	Limited / controlled rotation	Moves in steps
Speed controlled by voltage	Controlled by PWM signal	Controlled by pulses
No position control	Precise position control	Step-wise position control
No feedback	Uses feedback	No feedback
Simple structure	Complex structure	Medium complexity
Low accuracy	Very high accuracy	High accuracy
Low cost	High cost	Moderate cost
Used in fans, wheels	Used in robots, arms	Used in 3D printers, CNC