

Motor (Final) Survey Report

This report is issued without prejudice, in respect of cause, nature and extent of loss / damage and subject to the terms and conditions of the insurance policy & insurer admitting liability.

Claim No.: 2017003124C050717001

Date 21-03-2025

Surveyor Details

(a) Professional Fee on Estimate of Rs.: 800.00

(b) Reinspection Charges: 0.00

(c) Date of Visits: N/A

Halting Charges (Final + Re-inspection): N/A Conveyance Charges - Final: Rs. 200.00

Total Distance (km): 0 Rate per km: Rs. 0.00

Conveyance Charges - Re-inspection: Rs. 0.00

Total Distance (km): 0
Rate per km: Rs. 0.00
Number of Photos: 0 nos.
Rate per Photograph: Rs. 0.00

Toll Tax: 0

TOTAL: Rs. 1000.00

Add CGST @ 9%: Rs. 90.00 Add SGST @ 9%: Rs. 90.00 Add IGST @ 18%: Rs. 0.00 NET TOTAL: Rs. 1180.00

Rs. One Thousand One Hundred Eighty Only.

BANK & OTHER DETAILS (Ahmedabad)

NAME OF BANK: Bank of Baroda BRANCH NAME: IBB Jaipur Branch

BRANCH ADDRESS: IBB Jaipur Branch, Jaipur - 302001

BANK A/C NUMBER: 24750200006187

IFSC CODE: BARBOJAIINT MICR CODE: 302012013 ID No.: 2300013333

GSTIN (UIIC): 24AAACU5552C3ZN

Insurance Details

Policy No.: 2017003124P114551018 Insured Dec Value: 1062000 Period: 14-Dec-24 to 13-Dec-25

Insured Name: MRS PRABHLEEN KAUR

Insured Address: W/O KARANVIR SINGH R/O H NO 120 FACTORY AREA NEAR DHARAMSHALA PTA 147001 PATIALA

PUNJAB

Insurer Office Address: Not Available

Insured Phone: Not Available

Vehicle Particulars

(i) Owner Name.: PRABHLEEN KAUR(ii) Registered No.: PB11DB9739(iii) Date of Registration: 24/12/2022(iv) Chassis No.: MZBEP813LNN463066

(v) Engine No.: D4FANM734562

(vi) Maker/Model Name: SELTOS D1.5 6MT HTK PLUS

(vii) Body Type: STATION WAGON(viii) Vechile Category: LMV(ix) Fitness Upto.: 23/12/2037

Driver Particulars

(i) Name of Driver: SURINDER KUMAR
(ii) License No.: PB-1119950026614
(iii) Date of Issue: 2024-06-06
(iv) Valid up to: 2029-06-05
(v) License Type: LMV & MCWG

Accident Particulars

(i) Date & Time of Accident: 2025-02-20 (ii) Place of Accident: MALERKOTLA

(iii) Place of Survey:

Cause of Accident

ACCORDING TO VERSION OF INSURED AND CLAIM FORM.....A ALTO CAR COMING FROM WRONG SIDE HIT LEFT OF OUR CAR AND DAMAGE BODY

Estimate Damage Report									
Part	Material	Est Cost	Assess Cost	Tax	Tax Amt	Total Amt	Rate of Dep.	Dep.Amt	Final Amt
Grill		1000	800	18%	₹144.00	₹944.00	0.00%	₹0.00	₹944.00
Diggi / Back Door	Metal	1000	800	5%	₹40.00	₹840.00	15.00%	₹714.00	₹126.00
Left Fender	Metal	1000	800	5%	₹40.00	₹840.00	15.00%	₹714.00	₹126.00
	Total	₹3000	₹2400		₹224	₹2624		₹1428	₹1196

Estimate Labour Report								
Desc	Estimate Cost	Assessed Cost	Tax	Tax Amount	Total Amount	Rate of Dep.	Dep.Amt	Final Amount
LABOUR	18880	11000	18%	₹1980.00	₹12980.00	0.00%	0.00%	₹12980.00
Total	₹18880	₹11000		₹1980	₹12980			₹12980

Summary			
Estimate :-	Assessed For :-		
Total Labour Charges: ₹18880.00	Total Labour Charges: ₹12980.00		
Total Cost of Parts: ₹3000.00	Total Spare Parts: ₹1196.00		
	Less Excess (-): 1000		
Total: ₹21880.00	Total: ₹13176.00		

Remarks

- 1. The rates allowed above combination of authorised dealer prices.
- 2. The cause, nature and circumstances leading to accident appears, genuine, believable and losses recommended/assessed are corroborating with this accident.
- 3. The damages as observed were found to be fresh and consistent with the nature of accident as reported.
- 4. The R.C. and the D.L. were verified from the original documents and found in order.
- 5. The loss or damage or liability has arisen proximately caused by the insured perils.
- 6. The prices are recommended exclusive of all taxes, duties, octroi etc.



Photos

Photos