
Aergo
Setup
New
Save
Load
Cut
Copy
Paste
Start
Simulate
Stop
Pause
Resume
PROGRAM
WELD
(3)
AVAILABLE
PICK
WELD
(2)
AUTOMATIC PARAMETERS
Scene Scan
Click to set
(5)
Welding Trajectory
Click to set
(6)
(4)
(1)
(8)
(7)
eload Visualization
Scan Scene
ADVANCED
(9)
Confirm