AERODROME OBSTACLES
1. Lit TWR, 178FT AGL BRG 245 MAG 260M FM HLS.
2. Lit TWR, 115FT AGL BRG 100 MAG 40M FM HLS.

ATS AND AERODROME COMMUNICATION FACILITIES
FIA	MELBOURNE CENTRE	123.35 On Ground

CTAF 119.1

NOISE ABATEMENT PROCEDURES
Avoid over flying houses North of the heliport.

ADDITIONAL INFORMATION
A Fly Neighbourly protection area has been established around Cape Woolamai, Observation Point and Summerland Peninsula. Refer to ERSA GEN Special Procedures FN 12 for detailed information.

CHARTS RELATED TO THE AERODROME
WAC 3469, 3470.

PINKENBA

ELEV 13

FULL NOTAM SERVICE NOT AVBL

QLD		UTC +10	YAAP
272608S	1530644E	VAR 11 DEG E	UNCR

AD OPR Airbus Helicopters Australia Pacific, 701 MacArthur Ave, Central Pinkenba, QLD, 4008. Email: hsemanager.aap@airbus.com. PH 0438 367 990. Website: www.airbusgroupap.com.au.

REMARKS
1. Private property, PPR unless in the case of an EMERG.
2. HJ OPS only.

ATS AND AERODROME COMMUNICATION FACILITIES
FIA	BRISBANE CENTRE	125.7
ACD	BRISBANE DELIVERY	118.85
APP	BRISBANE APPROACH	124.7 125.6
ATIS	BRISBANE ATIS	113.2 125.5
TWR	BRISBANE TOWER	118.0 120.5

LOCAL TRAFFIC REGULATIONS
Overnight HEL parking AVBL on the grassed area with prior permission.

FLIGHT PROCEDURES
1. ARR ACFT FM the SE, 327DEG MAG or as directed by ATC.
2. DEP ACFT to the SE 147DEG MAG or as directed by ATC based on onward flight route.
3. CTC Brisbane TWR on the ground prior to DEP on 07 3866 3694 for status and/or CLR.

NOISE ABATEMENT PROCEDURES
APCH and DEP FM and to the SE over water to avoid local nearby properties, or as advised by Brisbane TWR.

ADDITIONAL INFORMATION
1. No H pad marking or concrete pad is present.
2. CAUTION: HLS is within 0.5NM of the Helitech and Holt St HLS and within 2NM of YBBN CTR airspace.
3. Windsock located on corner of concrete garage abeam HLS.
4. Bird hazard exists.

CHARTS RELATED TO THE AERODROME
WAC 3340.