BROWSE BASIN

AVFAX CODE 9907 **FULL NOTAM SERVICE NOT AVBL**

WA		UTC +8	YBRB
135709S	1231823E	VAR 1 DEG E	UNCR

ATS AND AERODROME COMMUNICATION FACILITIES

HF	NORTH WESTERN	8843

CTAF 123.45

CHARTS RELATED TO THE AERODROME

1. WAC 3108.
2. Also refer to AIP Departure and Approach Procedures.

BRUNY ISLAND

ELEV 26

FULL NOTAM SERVICE NOT AVBL

TAS		UTC +10	YBYI
431406S	1472247E	VAR 16 DEG E	UNCR

AD OPR Bruny Island Aviation Trust, 3959 Bruny Island Main Road, Bruny Island, TAS, 7150. Email: info@brunyisland.com. Mobile 0427 931 271. Website: www.brunyisland.com.

REMARKS

1. AD Charges: by donation.
2. PH AD OPR prior to ARR for RWY conditions.

PHYSICAL CHARACTERISTICS

14/32 21c Unrated. Gravel. RWY LEN 650M. Slope level. WID 10 RWS 25

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	HOBART CENTRE	(2)	125.55
UNICOM	BRUNY ISLAND UNICOM		126.7 (1)

(1) CS “Bruny UNICOM” when AVBL.
(2) Outside HB TWR and APP HR ML CENTRE.

LOCAL TRAFFIC REGULATIONS

Confirm PRKG SFC conditions following rain.

CTAF 126.7

FLIGHT PROCEDURES

Right hand CCTS on RWY 14 due to terrain.

ADDITIONAL INFORMATION

1. Trees on both APCH paths with high GND near the RWY 14 APCH.
2. Caution: Turbulence.
3. Splay areas below ALA recommended MNM due to hangar and perimeter trees.
4. Wildlife hazard exists.

CHARTS RELATED TO THE AERODROME

WAC 3556.