7. Caution:
   a. RWY sweeper and barrier crew may be OPR AD.
   b. Due to terrain shielding taxiing ACFT and/or ground vehicles operating at one end of the airfield cannot hear taxiing ACFT and/or ground vehicles operating at the other end on the CTAF.
   c. Uncontrolled Intersection: TWY B1 and TWY E1 intersect with a vehicle access road. Carriage of a radio is not required by vehicles crossing at this INT. Watch for vehicles approaching FM both sides. Exercise caution during CTAF HR and during periods of low VIS
8. An airfield inspection service can be requested from ARFF on the CTAF if required to establish the presence of other operators. ACFT with multiple antennae must use upper antennae in preference.
9. ACFT wash facility AVBL for select MIL ACFT only. CTC PEA ABOC PH: (08) 9571 7888 for activation instructions.

CHARTS RELATED TO THE AERODROME

1. WAC 3351, 3462.
2. MIL Aerodrome Obstruction Chart Type A: DEC 2024.
3. Also refer to AIP Departure and Approach Procedures.

PENFIELD

ELEV 1150

FULL NOTAM SERVICE NOT AVBL

VIC		UTC +10	YPEF
373048S	1444154E	VAR 12 DEG E	UNCR

AD OPR Penfield Enterprises Pty Ltd, 295 Settlement Road, Sunbury, VIC, 3429. PH AD Owners 0418 373 246.

REMARKS

1. Private airfield, PPR CTC owner or manager 0418 373 246 or 0417 381 551.
2. Radio is mandatory and must be used.
3. After several days of heavy rain, contact AD MGR for RWY condition.
4. Twin engine ACFT by approval of owner.
5. Landing and overnight PRKG fees apply - all ACFT.

HANDLING SERVICES AND FACILITIES

Nil fuel AVBL.

PASSENGER FACILITIES

WC.

AERODROME OBSTACLES

1. Pine trees in TKOF splay RWY 36 and on APCH to RWY 18.
2. Concrete traffic bollards across the end of RWY 18, at the end of the over run area.

PHYSICAL CHARACTERISTICS

15/33	25c	Unrated. Grass. RWY LEN 750M.	WID 30	RWS 45
18/36	40c	Unrated. Grass. RWY LEN 1,230M.	WID 30	RWS 45

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	135.7 On Ground

LOCAL TRAFFIC REGULATIONS

1. TKOF from RWY ends (noise abatement) except for TGL.
2. Use taxiways for RWY 18/36 and RWY 15.
3. For RWY 33 taxi via taxiway for RWY 18 heading to the intersection, then backtrack RWY 33.
4. Precautionary search training not permitted. Noise abatement.
5. All ACFT must park facing W on flight line. Entry is E of flight line and egress W of flight line.
6. Overnight PRKG AVBL.

Information may be continued on the next page: PTO

FLIGHT PROCEDURES

1. All CCTS to the W at 2,000FT AMSL and W of Riddell Road.
2. Ultra-light ACFT (MAX 55KTS) CCTS to the W but E of Riddell Road.
3. Do not overfly pine forest W of RWY intersection below 1,700FT AMSL. Paintball may be in progress.
4. Straight in approaches or base joins not permitted.

CTAF 121.6

ADDITIONAL INFORMATION

1. Airfield used for ab Initio training. Students may be operating in solo CCTS.
2. CAUTION: Note close proximity of CTA (S, E and above 2,500FT AMSL also Riddell Creek Airport 2.2NM N with CCTS to E.
3. Birds in the VCY of AD and RWY.

CHARTS RELATED TO THE AERODROME

WAC 3469, 3470.

PENNY

ELEV 1563

FULL NOTAM SERVICE NOT AVBL



WA		UTC +8	YPEN
284942S	1184948E	VAR 0 DEG E	UNCR

AD OPR Penny Operations Pty Ltd, Level 13, 58 Mounts Bay Road, Perth, WA 6000. PO Box 2714, Cloisters Square PO, WA, 6850.
Email: wesleyclaycomb@rameliusresources.com.au. PH ARO/AD MGR 0455 555 306 H24. PH 08 9940 3777. Website: www.rameliusresources.com.au.

REMARKS

1. PPR.
2. HJ only.

HANDLING SERVICES AND FACILITIES

Parking allocation and ground handling services by prior arrangement with AD MGR.

APRONS AND TAXIWAYS

1. TWY A unrated. Gravel. WID 15M.
2. APN unrated. Gravel.

PHYSICAL CHARACTERISTICS

18/36	59c	PCR 90/F/B/1.57 MPa/T Gravel. RWY LEN 1,800M. Slope 0.24% down to N.	WID 30	RWS 90

AERODROME AND APPROACH LIGHTING

RWY 18/36 PTBL(1) BY PRIOR ARRANGEMENT

(1) E-Flares for emergencies only. 90 MIN PN.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 124.8

LOCAL TRAFFIC REGULATIONS

1. All fixed wing must make MAX RAD turns at MNM speed at turn pads to avoid SFC damage.
2. All ACFT to use idle power for movements on the APN with the exception of breakaway thrust to initiate taxi.
3. RWS not available for flight operations.

CTAF 126.7

CHARTS RELATED TO THE AERODROME

WAC 3351.

PERCH PLATFORM

ELEV 80

AVFAX CODE 9710

FULL NOTAM SERVICE NOT AVBL

VIC		UTC +10	YUPE
383409S	1471921E	VAR 13 DEG E	UNCR

AD OPR ESSO Australia Pty Ltd., Garretts Road, Longford, VIC, 3851. PH 03 5143 4200.