RAYNER PLACE HELIPORT

ELEV 1660
FULL NOTAM SERVICE NOT AVBL

NSW UTC +10 YRYP
345146S 1485602E VAR 12 DEG E UNCR
AD OPR Paul Schofield Aviation, Rayner Place, Yass, NSW, 2582. PH 0418 265 155.

REMARKS
PPR for all OPS.

HANDLING SERVICES AND FACILITIES
Paul Schofield Aviation - 2200-0700 UTC DLY.

METEOROLOGICAL INFORMATION PROVIDED
AWIS FREQ 123.65 (requires three one-second pulses to activate) - Report faults to AD OPR.

ATS AND AERODROME COMMUNICATION FACILITIES
FIA MELBOURNE CENTRE 124.1 In circuit area

LOCAL TRAFFIC REGULATIONS
1. APCH/DEP OPS when possible to and FM the SE.
2. Keep well clear of all houses to the W of heliport.

CTAF 126.7

CHARTS RELATED TO THE AERODROME
WAC 3456, 3457.

RAYWOOD

ELEV 450
FULL NOTAM SERVICE NOT AVBL



VIC UTC +10 YRYW
363230S 1441428E VAR 11 DEG E UNCR
AD OPR Bendigo Gliding Club Inc, PO Box 846, Bendigo, VIC, 3552.
Email: secretary@bendigogliding.org.au. PH 0492 923 215.
Website: www.bendigogliding.org.au.

REMARKS
1. PPR.
2. Aerotow and winch launching OPS.
3. Gliding OPS HJ DLY.

HANDLING SERVICES AND FACILITIES
Nil fuel AVBL.

PHYSICAL CHARACTERISTICS
09/27 30c Unrated. Grass. RWY LEN 900M. WID 90
18/36 43c Unrated. Grass. RWY LEN 1,300M. WID 90

ATS AND AERODROME COMMUNICATION FACILITIES
FIA MELBOURNE CENTRE 126.8

FLIGHT PROCEDURES
1. Gliders and tugs may fly contra CCTS.
2. Gliders and tugs normally operate inside and below standard 1000FT circuit.
3. RWY 09 not available if gliders launching on RWY 36.
4. RWY 36 not available if gliders launching on RWY 09.

CTAF 119.3

CHARTS RELATED TO THE AERODROME
WAC 3469, 3470.

Information may be continued on the next page: PTO