**CTAF** 132.1

**NOISE ABATEMENT PROCEDURES**

1. Noise sensitive area.
2. All ACFT required to be familiar with YLMQ procedure document on website.
3. Avoid all built up areas.
4. Avoid golf course to east.
5. No flight below 1,000FT AMSL.

**ADDITIONAL INFORMATION**

1. HEL OPS.
2. Frequent EMERG service OPS.
3. Microlight and gyrocopters operate from this AD. Gyrocopters may occupy RWY for longer than normal due to building up rotor speed.
4. PJE occur HJ on airfield from FL150, Pilots advised to monitor CTAF and BN CEN for DZ status.
5. Refer to YLMQ Westpac Rescue Helicopter for Helicopter Emergency Medical Service OPS.

**CHARTS RELATED TO THE AERODROME**

1. WAC 3456.
2. Also refer AIP Departure and Approach Procedures.

## LAKELAND DOWNS

**ELEV 935**

**FULL NOTAM SERVICE NOT AVBL**




| | | | |
|---|---|---|---|
| QLD | | UTC +10 | YLND |
| 155009S | 1445051E | VAR 6 DEG E | UNCR |

AD OPR Cook Shire Council, PO Box 3, Cooktown, QLD, 4895.
Email: cooktownap@cook.qld.gov.au. PH 07 4069 5360. Mobile 0417 628 080.

**ATS AND AERODROME COMMUNICATION FACILITIES**

| | | |
|---|---|---|
| FIA | BRISBANE CENTRE | 134.65 |

**FLIGHT PROCEDURES**

Right hand circuits operating on RWY 34 due to wind turbines located to the NW, as close as 2.3NM to a height of 700FT AGL.

**CTAF** 126.7


**CHARTS RELATED TO THE AERODROME**

WAC 3112.

## LAKES ENTRANCE

**ELEV 220**

**FULL NOTAM SERVICE NOT AVBL**




| | | | |
|---|---|---|---|
| VIC | | UTC +10 | YLKE |
| 375108S | 1475655E | VAR 13 DEG E | UNCR |

AD OPR Victoria Helicopters Pty Ltd, PO Box 834 Bairnsdale, VIC, 3875.
Email: info@ylke.com.au. PH 0419 567 590. Website: https://ylke.com.au/.

**REMARKS**

1. PPR FM AD OPR via website.
2. LDG fees apply, refer to website.

**PASSENGER FACILITIES**

WC.

**ATS AND AERODROME COMMUNICATION FACILITIES**

| | | |
|---|---|---|
| FIA | MELBOURNE CENTRE | 124.0 Circuit Area |

Information may be continued on the next page: PTO

### FLIGHT PROCEDURES
1. RWY 08 right hand CCTS.
2. Pilots are requested to avoid overflying residential buildings west of AD.
3. Preferred RWY 08 for TKOF and RWY 26 for LDG.

**CTAF** 126.7

### ADDITIONAL INFORMATION
1. Animal hazard exists.
2. HEL OPS west end of AD.
3. Frequent coastal HEL OPS from Loch Sport to Lake Tyres between 500 and 1,500FT AMSL.
4. Caution: standing water or soft movement areas after rain.
5. Caution: YGRL (Great Lakes Airfield) ALA 2NM to the east.

### CHARTS RELATED TO THE AERODROME
WAC 3470.

## LAKESIDE AIRPARK
**ELEV 175**

**FULL NOTAM SERVICE NOT AVBL**

QLD UTC +10 YLAK
204106S 1483730E VAR 8 DEG E UNCR

AD OPR Garry Poole, PO Box 3000, Caboolture, QLD, 4510. Email: office@cpd4510.com.
PH 0418 711 224.

### REMARKS
1. PPR.
2. Daylight OPS only.

### ATS AND AERODROME COMMUNICATION FACILITIES
FIA BRISBANE CENTRE 135.5 On Ground

**CTAF** 126.7

### ADDITIONAL INFORMATION
1. Phone or email for hazards/map file.
2. Feral animals some hours.
3. Wet weather shortens NE end.

### CHARTS RELATED TO THE AERODROME
WAC 3234, 3235.

## LATROBE VALLEY
**ELEV 180**

**AVFAX CODE 3050**

VIC UTC +10 YLTV
381226S 1462813E VAR 13 DEG E CERT

AD OPR Latrobe Airport Community Asset Committee, PO Box 264, Morwell, VIC, 3840.
PH 03 5128 5777: 0409 436 287. ARO 0408 038 285. Fax 03 5128 5672.
Website: www.latrobe.vic.gov.au.

