HANDLING SERVICES AND FACILITIES
Nil fuel AVBL. For closest fuel see Albury (YMAY) FAC entry.

PASSENGER FACILITIES
AC (Mitta Pub 02 6072 3542). Telstra 4G (only) mobile phone coverage.

AERODROME OBSTACLES
Fences and trees both ends.

PHYSICAL CHARACTERISTICS
14/32 30c Unrated. Gravel. RWY LEN 910M. WID 15

ATS AND AERODROME COMMUNICATION FACILITIES
FIA MELBOURNE CENTRE 125.2 3000FT

LOCAL TRAFFIC REGULATIONS
1. PRKG N of hangar only.
2. Carriage and use of radio is required by AD OPR.

FLIGHT PROCEDURES
1. High terrain in circuit area. All CCTS left hand.
2. Right turn after DEP RWY 32.
3. Cancel SAR ABV 2,000FT AGL.

CTAF 126.7

ADDITIONAL INFORMATION
1. Bird, wombat and kangaroo hazard exists.
2. Windshear.
3. Ice in winter.
4. Caution: Strip runs parallel to Omeo Highway.

CHARTS RELATED TO THE AERODROME
WAC 3470.

MITTAGONG **ELEV 1840**

FULL NOTAM SERVICE NOT AVBL

NSW UTC +10 YMIG
342654S 1503012E VAR 13 DEG E UNCR

AD OPR Mittagong Aero Club, PO Box 157, Bowral, NSW, 2576. PH Club President 0414 603 644: Treasurer 0414 863 102: Secretary 0418 643 082. Website: www.mittagongaeroclub.com.

REMARKS
1. Private airfield. Visitors welcome. PPR.
2. Refer website for visitor information.
3. Landing and overnight parking fees apply to all non-member ACFT refer website for schedule of charges.
4. Car park area locked when no member is present.

ATS AND AERODROME COMMUNICATION FACILITIES
FIA MELBOURNE CENTRE 121.2

LOCAL TRAFFIC REGULATIONS
1. No training activity by visiting aircraft (circuits, touch and go, stop and go, fullstop, precautionary search and landing exercises, practice forced landing etc).
2. Preferred RWY (weather conditions permitting): Takeoff RWY 06 - Landing RWY 24.

FLIGHT PROCEDURES
1. Right CCTS RWY 24, due to terrain.
2. Pilots are request to avoid overflying residential buildings and to avoid aerobatics within 3NM of the airfield.

CTAF 126.7

ADDITIONAL INFORMATION

Caution:

a. Windshear on take-off and landing RWY 24 with strong SW winds.
b. Rising terrain departing RWY 24.
c. Animal hazards (kangaroos).

CHARTS RELATED TO THE AERODROME

WAC 3456.

MOAMA

ELEV 310

FULL NOTAM SERVICE NOT AVBL

NSW		UTC +10	YMMO
360428S	1444552E	VAR 11 DEG E	UNCR

AD OPR Michael Jones, 120 Milgate Rd, Moama, NSW, 2731. PH 0418 953 727.

PHYSICAL CHARACTERISTICS

16/34	28c	Unrated. Sand. RWY LEN 850M. RWY unusable after heavy rain.	WID 30

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	126.8 Circuit Area

FLIGHT PROCEDURES

Right hand circuits RWY 34.

CTAF 119.1

ADDITIONAL INFORMATION

RWY 16/34 becomes unserviceable after heavy rain.

CHARTS RELATED TO THE AERODROME

WAC 3469, 3470.

MODEWARRE

ELEV 420

FULL NOTAM SERVICE NOT AVBL

VIC		UTC +10	YMOD
381538S	1440531E	VAR 12 DEG E	UNCR

AD OPR F. Cumming, 220 Connies Lane, Buckley, VIC, 3240. PH 0418 476 234.

REMARKS

PPR.

PHYSICAL CHARACTERISTICS

03/21	21c	Unrated. Grass. RWY LEN 650M.	WID 17
15/33	26c	Unrated. Grass. RWY LEN 800M.	WID 17

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	126.8 1500FT

CTAF 119.0

ADDITIONAL INFORMATION

1. One of five airfields in the immediate vicinity.
2. Beware of animals.
3. RWY becomes soft in wet conditions.
4. Model ACFT OPS may occur WI 500M RAD of ARP, SFC - 1,500FT AGL. OPR CTC phone: 0438 918 240.

CHARTS RELATED TO THE AERODROME

WAC 3649, 3470.

Information may be continued on the next page: PTO