ADDITIONAL INFORMATION

Caution:

a. Windshear on take-off and landing RWY 24 with strong SW winds.
b. Rising terrain departing RWY 24.
c. Animal hazards (kangaroos).

CHARTS RELATED TO THE AERODROME

WAC 3456.

MOAMA

ELEV 310

FULL NOTAM SERVICE NOT AVBL

NSW		UTC +10	YMMO
360428S	1444552E	VAR 11 DEG E	UNCR

AD OPR Michael Jones, 120 Milgate Rd, Moama, NSW, 2731. PH 0418 953 727.

PHYSICAL CHARACTERISTICS

16/34	28c	Unrated. Sand. RWY LEN 850M. RWY unusable after heavy rain.	WID 30

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	126.8 Circuit Area

FLIGHT PROCEDURES

Right hand circuits RWY 34.

CTAF 119.1

ADDITIONAL INFORMATION

RWY 16/34 becomes unserviceable after heavy rain.

CHARTS RELATED TO THE AERODROME

WAC 3469, 3470.

MODEWARRE

ELEV 420

FULL NOTAM SERVICE NOT AVBL

VIC		UTC +10	YMOD
381538S	1440531E	VAR 12 DEG E	UNCR

AD OPR F. Cumming, 220 Connies Lane, Buckley, VIC, 3240. PH 0418 476 234.

REMARKS

PPR.

PHYSICAL CHARACTERISTICS

03/21	21c	Unrated. Grass. RWY LEN 650M.	WID 17
15/33	26c	Unrated. Grass. RWY LEN 800M.	WID 17

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	126.8 1500FT

CTAF 119.0

ADDITIONAL INFORMATION

1. One of five airfields in the immediate vicinity.
2. Beware of animals.
3. RWY becomes soft in wet conditions.
4. Model ACFT OPS may occur WI 500M RAD of ARP, SFC - 1,500FT AGL. OPR CTC phone: 0438 918 240.

CHARTS RELATED TO THE AERODROME

WAC 3649, 3470.

Information may be continued on the next page: PTO