NORTHAM

ELEV 500

FULL NOTAM SERVICE NOT AVBL



WA UTC +8 YNTM
313733S 1164104E VAR 1 DEG W UNCR
AD OPR Northam Aero Club, PO Box 247, Northam, WA, 6401.
Email: webmaster@northamaeroclub.com. PH 0428 880 149.
Website: www.northamaeroclub.com.

REMARKS

1. Latest info AVBL FM website or CTC AD OPR or 0407 873 700.
2. The following types of aircraft are not permitted to operate from the Northam Airfield unless the express permission of the Northam Shire Council has been granted:
   a. Gyroplanes *CAO 95.12* and *CAO 95.12.1*
   b. Weight shift Control aircraft and Powered Parachutes. *CAO 95.32*

HANDLING SERVICES AND FACILITIES

VIVA Aviation: Dunnings Fuel. AVGAS H24 credit card bower, MON-FRI Phone 08 9622 1413, AH 0438 035 328. JET A1 not AVBL.

PASSENGER FACILITIES

WC

AERODROME OBSTACLES

Beware of power lines on the Great Eastern Highway Bypass.

PHYSICAL CHARACTERISTICS

14/32	41a	Unrated. Sealed. RWY LEN 1,248M. RWY 14 DTHR 175M. RWY 32 DTHR 98M.	WID 15	RWS 90

AERODROME AND APPROACH LIGHTING

RWY 14/32 LIRL AFRU+PAL 124.2

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 120.3 Circuit Area

LOCAL TRAFFIC REGULATIONS

1. Curfew for repetitive circuit training is 1300 UTC (2100 Local).
2. PRKG in front of Aero Club hangar reserved for fire fighting ACFT.
3. Carriage and use of radio is required by the AD OPR.

FLIGHT PROCEDURES

RWY 32 - Right hand circuits.

CTAF - AFRU 124.2

ADDITIONAL INFORMATION

1. Caution: Ultralight flight training.
2. Turbulence near RWY 14 THR strong easterly wind.

CHARTS RELATED TO THE AERODROME

WAC 3351, 3462.

Information may be continued on the next page: PTO