FLIGHT PROCEDURES

1. All CCTS to the W at 2,000FT AMSL and W of Riddell Road.
2. Ultra-light ACFT (MAX 55KTS) CCTS to the W but E of Riddell Road.
3. Do not overfly pine forest W of RWY intersection below 1,700FT AMSL. Paintball may be in progress.
4. Straight in approaches or base joins not permitted.

CTAF 121.6

ADDITIONAL INFORMATION

1. Airfield used for ab Initio training. Students may be operating in solo CCTS.
2. CAUTION: Note close proximity of CTA (S, E and above 2,500FT AMSL also Riddell Creek Airport 2.2NM N with CCTS to E.
3. Birds in the VCY of AD and RWY.

CHARTS RELATED TO THE AERODROME

WAC 3469, 3470.

PENNY

ELEV 1563

FULL NOTAM SERVICE NOT AVBL



WA		UTC +8	YPEN
284942S	1184948E	VAR 0 DEG E	UNCR

AD OPR Penny Operations Pty Ltd, Level 13, 58 Mounts Bay Road, Perth, WA 6000. PO Box 2714, Cloisters Square PO, WA, 6850.
Email: abhishekkumar@rameliusresources.com.au. PH ARO/AD MGR 0455 555 306 H24. PH 08 9940 3777. Website: www.rameliusresources.com.au.

REMARKS

1. PPR.
2. HJ only.

HANDLING SERVICES AND FACILITIES

Parking allocation and ground handling services by prior arrangement with AD MGR.

APRONS AND TAXIWAYS

1. TWY A unrated. Gravel. WID 15M.
2. APN unrated. Gravel.

PHYSICAL CHARACTERISTICS

18/36	59c	PCR 90/F/B/1.57 MPa/T Gravel. RWY LEN 1,800M. Slope 0.24% down to N.	WID 30	RWS 90

AERODROME AND APPROACH LIGHTING

RWY 18/36 PTBL(1) BY PRIOR ARRANGEMENT

(1) E-Flares for emergencies only. 90 MIN PN.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 124.8

LOCAL TRAFFIC REGULATIONS

1. All fixed wing must make MAX RAD turns at MNM speed at turn pads to avoid SFC damage.
2. All ACFT to use idle power for movements on the APN with the exception of breakaway thrust to initiate taxi.
3. RWS not available for flight operations.

CTAF 126.7

CHARTS RELATED TO THE AERODROME

WAC 3351.

PERCH PLATFORM

ELEV 80

AVFAX CODE 9710

FULL NOTAM SERVICE NOT AVBL

VIC		UTC +10	YUPE
383409S	1471921E	VAR 13 DEG E	UNCR

AD OPR ESSO Australia Pty Ltd., Garretts Road, Longford, VIC, 3851. PH 03 5143 4200.