TORQUAY

ELEV 30

FULL NOTAM SERVICE NOT AVBL

VIC		UTC +10	YTQY
381800S	1442154E	VAR 12 DEG E	UNCR

AD OPR Torqair Pty Ltd, 325 Blackgate Road, Torquay, VIC, 3228.
Email: fly@tigermothworld.com.au. PH 0447 615 100 or 0448 096 066.
Website: www.tigermothworld.com.au.

REMARKS

1. PPR.
2. Landing fees: refer 'Pilot Information' on website.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	123.35 On Ground

CTAF 119.0

CHARTS RELATED TO THE AERODROME

WAC 3469, 3470.

TOTTENHAM

ELEV 793

FULL NOTAM SERVICE NOT AVBL



NSW		UTC +10	YTOT
321522S	1472208E	VAR 11 DEG E	UNCR

AD OPR Lachlan Shire Council, PO Box 216, Condobolin, NSW, 2877.
PH 02 6895 1900: AH 0428 951 966. Website: www.lachlan.nsw.gov.au.

AERODROME OBSTACLES

RWY 03/21 transitional slope is infringed by trees on west side.

PHYSICAL CHARACTERISTICS

03/21	40a	Unrated. RWY LEN 1,204M.	WID 18	RWS 90
11/29	23c	Unrated. Grassed red clay. RWY LEN 705M.	WID 20	RWS 90

AERODROME AND APPROACH LIGHTING

RWY 03/21 self activated solar LGT.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	123.9 3000FT

CTAF 126.7

ADDITIONAL INFORMATION

Significant animal hazard exists.

CHARTS RELATED TO THE AERODROME

WAC 3456, 3457.

Information may be continued on the next page: PTO